



U.S. Department
of Transportation
**Federal Aviation
Administration**



SDR Summary

Service Difficulty Reporting

May 3, 1998 - May 9, 1998

GENERAL AVIATION, ZAC-327

You can improve Air Safety by reporting the problem when you see it!

SECTION

- I Significant Occurrence Report
- II Domestic Service Difficulty Report
- III International Service Difficulty Report
- IV SDR Totals by District Office
- V Index By Aircraft Make and Model
- VI Joint Aircraft System/Component Code Table

ISSUE: 98-19



U.S. Department
of Transportation
**Federal Aviation
Administration**

SDR SUMMARY

General Aviation, ZAC-327



This summary includes domestic (United States) Service Difficulty Reports (SDRs) entered into the data base for aircraft weighing 12,500 lbs. and below. It also includes reports on aeronautical products (engines, propellers, and components), and all helicopters. A separate section for International SDRs for aircraft weighing 12,500 lbs. and under has also been included. Under a data exchange agreement, International SDRs are submitted to the FAA by the Civil Aviation Authority of other countries (currently, Canada - CAN, and Australia - AUS). All reports are sorted by aircraft make, model group (basic model), and Joint Aircraft System/Component (JASC) code. Within each aircraft model group, the specific model shown may vary, but similar types of reports will be grouped together and listed in ascending order by their JASC code. Each field contains all information submitted to the FAA. Some fields are not included in order to make the summary easier to read. Additional information may be obtained by referring to the "operator control number." Send your request to the Aviation Data Systems Branch, AFS-620 at the address or phone below.

The Regulatory Support Division (AFS-600) has established a "HomePage" on the Internet through which the same information is available. There is a large quantity of other information available through the AFS-600 HomePage such as the most current SDR system codes (i.e., Joint Aircraft System/Component Codes). The SDR Question and Answer Section of the Summary will also be transferred to the AFS-600 HomePage to simplify the process of preparing the SDR Summaries in the PDF format each week. There are "hot buttons" to take you to other locations and sites where FAA Flight Standards Service Information is available. The AFS-600 "HomePage" address is:

<http://www.mmac.jccbi.gov/afs/afs600>

"The Service Difficulty Reports in this publication are derived from unverified information submitted by the aviation community without FAA verification for accuracy. The number of SDRs submitted is not an indication of the mechanical reliability or fitness of an airline or individual operator, and the information should not be used as such."

Comments are welcomed and may be directed to:


*Federal Aviation Administration
Aviation Data Systems Branch, AFS-620
P.O. Box 25082
Oklahoma City, OK 73125-5029
Phone: (405) 954-4171, Fax: (405) 954-4748*

Your continued participation is essential and is an integral part of ensuring aviation safety. Thank you for supporting the Service Difficulty Program! If you have any questions regarding this special notice you can contact John Jackson at (405) 954-6486, or Jim Gillespie at (405) 954-1141, or Blake McDonald at (405) 954-0307 in the Aviation Systems Branch (AFS-620). Their E-mail addresses are:

john_e_jackson@mmacmail.jccbi.gov

james_gillespie@mmacmail.jccbi.gov

blake_mcdonald@mmacmail.jccbi.gov



SIGNIFICANT OCCURRENCE REPORT





U.S. Department
of Transportation
**Federal Aviation
Administration**

THE SIGNIFICANT OCCURRENCE REPORT



The Significant Occurrence Report is a compilation all of the star bordered reports that appear in the General Aviation Service Difficulty Report (SDR) Summary, ZAC-327. The Significant Occurrence Report is used to highlight industry problem areas to field inspectors and the aviation public.

Limited analysis is performed by the Aviation Data Systems Branch, AFS-620 during the preparation of the "Significant Occurrence Report", which is generated each week and is included in the front of the Air Carrier SDR Summary. Significant Reports are hand selected by AFS-620's inspectors based on the individual merit of each report. The criteria for selection includes, but is not limited to, items that indicate high failure rates; items related to accidents or incidents; or design or maintenance failures which may affect the safe operation of the aircraft.

In some cases, this limited analysis of SDR data leads to the preparation of information bulletins which are routed to the appropriate product certification office for further investigation of the problem. The end result may be the issuance of an airworthiness directive (AD) by the Aircraft Certification Service (AIR) if warranted.

The Significant Occurrence Report (section I) of the weekly SDR Summary is not intended to be a summary of all significant events and should not be used as such. We recommend that you review further the applicable sections of the SDR summary that may be of interest.

GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT

5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 6220 | 911RX | AGUSTA | | | | DAMPER | WORN | 512 | 6/30/94 |
| | 10017 | A109K2 | | | | 1090101063 | M/R | | 94ZZZX4572 |
| ***** | DURING 600-HOUR INSPECTION, DAMPER ROD END FOUND TO HAVE PLAY, NO PLAY ALLOWED. A REPLACEMENT DAMPER WAS INSTALLED. | | | | | | | | |
| 7414 | 247RJ | AMTRMO | AMTRVW | | | DRIVE COUPLING | FAILED | | 4/17/98 |
| | 999 | SONERAI2 | VW2200VOLKS | | | | ENGINE MAGNETO | | 98ZZZX1697 |
| ***** | THE CAST ALUMINUM MAGNETO DRIVE COUPLING WHICH IS KEYED TO THE FLYWHEEL BROKE INTO FOUR PIECES. THE RESULTANT FRICTION MELTED AND FUSED A PORTION OF THE BROKEN PIECES OF THE COUPLING TO THE STATIONARY CROSS MEMBER ENGINE MOUNT. THIS FAILURE OF THE MAGNETO COUPLING RESULTED IN THE FAILURE OF THE ENGINE DURING CRUISE AND ULTIMATELY THE ACCIDENT WHICH DESTROYED THE AIRCRAFT AND INJURED THE PILOT. THE COUPLING BROKE AT THE KEYWAYS AND SHOWED EVIDENCE OF PRE-EXISTING CRACKS POSSIBLY CASTING FLAWS. SUBMITTER RECOMMENDED THE MAGNETO DRIVE COUPLING BE MILLED FROM A SOLID PIECE OF HIGH GRADE ALUMINUM AND ALL EDGES BE RADIUSED TO PREVENT CRACKING. | | | | | | | | |
| 3418 | 163SP | BEECH | | | | LIFT DETECTOR | SHORTED | 219 | 11/21/97 |
| RT2R | TE872 | E55 | | | | 1513 | SWITCH | | 97ZZZX5114 |
| ***** | AIRCRAFT WAS ON RAMP AFTER LANDING IN WET SNOW. WITH ADDITIONAL SNOW ACCUMULATING ON THE AIRCRAFT, THE STALL WARNING HORN BEGAN TO SOUND. PILOT SILENCED HORN WITH CIRCUIT BREAKER AND ADVISED MAINTENANCE. LIFT DETECTOR WAS FOUND SHORTED INTERNALLY. AFTER EXTERNAL HEATING OF THE LIFT DETECTOR TO REMOVE MOISTURE, FUNCTION CHECKS WERE NORMAL. SUBMITTER RECOMMENDS MANUFACTURER USE ENVIRONMENTALLY SEALED MICROSWITCH IN THE LIFT DETECTOR ASSEMBLY TO AVOID FALSE STALL INDICATIONS. | | | | | | | | |
| 2730 | 6645K | BEECH | | | | TORQUE TUBE | CRACKED | | 2/26/98 |
| EHHR | U209 | C99 | | | | 115610010325 | ELEVATOR | | 98ZZZX1634 |
| ***** | ELEVATOR TORQUE TUBE ASSY, P/N 115610010325, INSPECTED PER SB 2145 (RECURRING) DATED APRIL, 1986. AIRCRAFT HISTORY INDICATES NUMEROUS REPLACEMENTS DUE TO CRACKS IN SUPPORT ASSY, P/N 1156100181, OR TORQUE TUBE, P/N 11510010325. | | | | | | | | |
| 2730 | 6656N | BEECH | | | | SUPPORT | CRACKED | 702 | 2/26/98 |
| EHHR | U213 | C99 | | | 115610010325 | 1156100181 | ELEV TORQ TUBE | | 98ZZZX1635 |
| ***** | ELEVATOR TORQUE TUBE SUPPORT IS INSPECTED EACH 1,000 HOUR RECURRING PER SB 2145, DATED APRIL, 1986. AIRCRAFT HISTORY INDICATES NUMEROUS REPLACEMENTS DUE TO CRACKS OF SUPPORT ASSY, P/N 115610181 OR TORQUE TUBE, P/N 115610010325. | | | | | | | | |
| 7261 | 108W | BELL | ALLSN | | | TUBE | CHAFED | 2100 | 3/12/98 |
| | 52034 | 206L4 | 250C30P | | | 23058110A | SCAVENGE OIL | | 98ZZZX1701 |
| ***** | WHILE REMOVING RENTAL ENGINE AND TRANSFERRING HARD LINE P/N 23058110-A FROM RENTAL ENGINE TO ORIGINAL ENGINE, SEVERE CHAFING NOTED UNDER ADEL CLAMP. THIS IS SCAVENGE OIL LINE FROM BOTTOM OF COMPRESSOR TO THE N1 SIDE OF GEARBOX. ABRASIVE DUST AND AIRBORNE DIRT CREEPS IN BETWEEN HARD RUBBER ADEL CLAMP AND OIL LINE AND CHAFES OR WEARS OIL LINE TO THE POINT OF FAILURE. THE NEED EXISTS FOR CLAMPING DEVICES THAT WOULD ELIMINATE THIS CHAFING CONDITION. IN THE MEANTIME, INSPECTION UNDER CLAMPED AREAS IS PRUDENT TO AVOID AN UNSUSPECTED FAILURE. | | | | | | | | |
| 2810 | 3799S | CESSNA | | | | TANK | BROKEN WELD | 5033 | 4/22/98 |
| | 17250999 | 172E | | | | 05260074 | BAFFLE | | 98ZZZX1651 |
| ***** | WHILE MOVING AIRCRAFT A CLICKING SOUND WAS HEARD. AFTER LOOKING IN THE GAS CAP, A LARGE PART WAS FOUND SLIDING AROUND IN FUEL TANK. AFTER A CLOSER LOOK, FOUND BROKEN WELDS ON INTERNAL RIB OR BAFFLE. CAUSE WAS FUEL MOVEMENT IN TANK, AND RIB WAS ONLY WELDED ON ONE SIDE OF RIB. IF WELDED ON BOTH SIDES, IT MAY HAVE NOT BROKEN LOOSE. IF THE RIB WOULD STICK UNDER FUEL GAUGE, FLOAT COULD INDICATE MORE FUEL THAN WAS IN TANK. | | | | | | | | |
| 3211 | 6360D | CESSNA | | | | BOLT | FAILED | 9401 | 3/19/98 |
| VT3R | 17272746 | 172N | | | | S21381 | LT MLG MOUNT | | 98ZZZX1669 |
| ***** | DURING ROLL-OUT, PILOT LOST DIRECTIONAL CONTROL AND AIRCRAFT VEERED OFF RUNWAY INTO THE DIRT. AFTER CONTACTING UNEVEN TERRAIN, THE LT MLG STRUT COLLAPSED AFT CAUSING DAMAGE TO LT MLG FAIRINGS, FUSELAGE, AND LT STABILIZER/ELEVATORS. INSPECTION SHOWED THE P/N S2138-1 BOLT HAD BROKEN INSIDE STRUT ALLOWING STRUT TO ROTATE AFT. METALLURGICAL ANALYSIS DETERMINED THE BOLT WAS PREVIOUSLY CRACKED. SUBMITTER RECOMMENDED A SAFE LIFE LIMIT BE ESTABLISHED. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|--|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 3252 | 5331V | CESSNA | | | | BARREL | FAILED | | 11/1/97 |
| | 172RG0506 | 172RG | | | | 14421121 | SHIMMY DAMPENER | | 97ZZZX5129 |
| ***** | AIRCRAFT WAS BROUGHT TO MAINTENANCE AFTER A TRAINING FLIGHT WITH REPORT OF A SEVERE NOSE WHEEL VIBRATION. AN INSPECTION REVEALED THAT THE END OF THE SHIMMY DAMPENER BARREL CLOSEST TO THE SERVICE HOLE WAS BROKEN OFF. THE OUTER RETAINING LINE AND BEARING HEAD WERE MISSING. | | | | | | | | |
| 8010 | 9898G | CESSNA | | | | SOLENOID | FAILED | 2445 | 4/19/98 |
| | 17259798 | 172L | | | | S19911 | STARTER | | 98ZZZX1678 |
| ***** | WHEN AIRCRAFT MASTER SWITCH WAS TURNED ON THE STARTER ENGAGED CAUSING THE PROPELLER TO TURN. THE SOLENOID P/N S-199-1 WAS REMOVED AND OPENED UP. WATER, RUST, AND CORROSION WERE FOUND. THIS CAUSED THE SOLENOID TO REMAIN IN THE CLOSED POSITION. THIS CONDITION IS A SERIOUS SAFETY CONDITION AND COULD CAUSE INJURY OR DEATH. A NEW SOLENOID WAS INSTALLED, IT WAS SEALED WITH EPOXY PRIOR TO INSTALLATION TO PREVENT WATER OR MOISTURE FROM ENTERING IT. THE LOCATION OF THE SOLENOID IN THE COWLING ALLOWS RAIN TO ENTER THE UNIT. | | | | | | | | |
| 7120 | 7518M | CESSNA | | | | BRACKET | CRACKED | | 10/17/97 |
| BX4R | 55818 | 175 | | | | 05131329 | ENG MT ATTACH | | 97ZZZX5123 |
| ***** | ALL FOUR ENGINE MOUNT BRACKETS ON THE FORWARD END OF THE ENGINE MOUNT STRINGERS WERE CRACKED AND HOLE AREA BENT OUT. THIS AREA BULGED OUT AROUND BOLT HOLE. AIRCRAFT HAS LYCOMING 180 HP MOD. | | | | | | | | |
| 3211 | 8655T | CESSNA | | | | U-BOLT | FAILED | 4450 | 4/21/98 |
| | 52555 | 182C | | | | 0541153 | LT MLG | | 98ZZZX1673 |
| ***** | DURING 100-HOUR INSPECTION, ONE LEG OF THE U-BOLT ON THE LT MAIN GEAR LEG WAS FOUND BROKEN IN THE THREAD AREA. SUBMITTER SUSPECTS IT WAS DUE TO FATIGUE. A CLOSER LOOK AT THESE BOLTS DURING INSPECTION WOULD BE IN ORDER. | | | | | | | | |
| 7810 | 335PC | CESSNA | | | | EXHAUST STACK | WORN | | 3/18/98 |
| | 3350053 | 335 | | | | 991030130 | LT ENG INBD | | 98ZZZX1662 |
| ***** | DURING A ROUTINE ENGINE CHANGE, THE EXHAUST COMPONENTS WERE INSPECTED AND THE LEFT ENGINE, INBOARD EXHAUST STACK (ELBOW) WAS FOUND WITH 2 LARGE HOLES CAUSED BY CONTACT FROM THE HEAT SHIELDS MOUNTED ABOVE THE ELBOW. THE HEAT SHIELDS ALSO HAD HOLES IN THEM AND WERE BURNED BY THE ESCAPING EXHAUST GASSES. ROUTED DIRECTLY ABOVE THE HEAT SHIELDS IS THE MAIN WIRE BUNDLE CONTAINING ALL NECESSARY WIRING FROM THE LEFT ENGINE. SEVERAL WIRES SHOWED SIGNS OF HEAT DAMAGE TO THE INSULATION AND ONE WIRE WAS BURNED COMPLETELY IN HALF. | | | | | | | | |
| 3233 | 310AV | CESSNA | | | | STUD | FAILED | | 4/1/98 |
| GMNR | 5500028 | 550 | | | | 65412045 | MLG ACTUATOR | | 98ZZZX1692 |
| ***** | IN PERFORMING 10,000-HOUR MLG INSPECTION AND UPON INSTALLING NUT ON STUD, STUD SHEERED IN HALF AT BASE OF THREADED AREA ALLOWING ACTUATOR TO SEPARATE FROM LANDING GEAR. AIRCRAFT WAS ON JACKS. UPON INSPECTION OF STUD, DETERMINED IT WAS CRACKED AND CORRODED. | | | | | | | | |
| 3213 | 2750K | LUSCOM | | | | GEAR LEG | FAILED | 1710 | 4/10/98 |
| | 5477 | 8A | | | | 0831192 | RT MLG | | 98ZZZX1659 |
| ***** | CORROSION INTERNALLY. FRACTURE ABOVE WELD BELOW BRAKE PULLEY. TOTAL GEAR FAILURE ON RIGHT GEAR ON LANDING. SEE LUSCOMBE NEW LETTER NR 113. | | | | | | | | |
| 2710 | 261CB | MOONEY | | | | CONTROL ROD | RUSTED | 3967 | 1/15/98 |
| EA6R | 250391 | M20K | | | | 730048001 | RT AILERON | | 98ZZZX1698 |
| ***** | DURING ANNUAL INSPECTION NOTED AILERON ROD RUSTY. UPON FURTHER INSPECTION, FOUND ROD RUSTED TO THE EXTENT IT COULD BE SEPARATED IN TWO WITH LIGHT HAND PRESSURE. SUBMITTER RECOMMENDED INSPECTING AT EACH ANNUAL. | | | | | | | | |
| 3230 | 60DC | PIPER | | | | BELLCRANK | CRACKED | 5261 | 3/31/98 |
| BONR | 600797806123 | PA60600 | | | | 400088001 | LT MLG WELL | | 98ZZZX1695 |
| ***** | DURING ROUTINE TRAINING FLIGHT, TOWER REPORTED THE LT MLG INBOARD DOOR REMAINED OPEN AFTER LANDING GEAR EXTENSION. AIRCRAFT LANDED WITHOUT INCIDENT. INSPECTED AIRCRAFT AND FOUND LT MLG BELLCRANK P/N 400088-001 BROKEN. THIS ALLOWED SEQUENCE VALVE TO OPEN CAUSING MLG DOOR TO FREEFALL OPEN. THE SAME PROBLEM OCCURRED IN 1994 TO RT BELLCRANK WITH 4,266.3 HRS TT. THE REPLACEMENT LT BELLCRANK IS SUBSTANTIALLY IMPROVED OVER ORIGINAL PART. SUBMITTER RECOMMENDED A SERVICE BULLETIN TO REQUIRE FREQUENT INSPECTIONS OF ORIGINAL PARTS. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 2710 | 9729W | PIPER | | | | SUPPORT | CRACKED | | 4/1/98 |
| | 2823207 | PA28140 | | | | 6210201 | AIL BELLCRANK | | 98ZZZX1677 |
| ***** | AILERON BELLCRANK SUPPORTS BROKEN AT FORWARD ENDS OF SUPPORT. THE DAMAGE HAS TO BE FOUND WITH A MIRROR. THE BELLCRANK SUPPORTS LOOK SATISFACTORY LOOKING IN THE ACCESS HOLES ORIGINALLY INSTALLED BY PIPER. THE FRONT FLANGE OF THE AILERON BELLCRANK SUPPORT BRACKETS FRONT BOLT HOLES FOR MOUNTING CRACKED COMPLETELY FROM ONE FLANGE SUPPORT EDGE TO THE OTHER. SUSPECT CAUSED BY HIGH WINDS AND NO AILERON LOCKING PROVISION ON THIS AIRCRAFT. THE DAMAGE IS HIDDEN BY THE WAY THE SUPPORTS' FLANGE IS BENT UP ON THE OUTBOARD EDGE. THE INBOARD FLANGE THAT IS BOLTED AND RIVETED TO THE RIB IS THE AREA THAT CRACKS. | | | | | | | | |
| 3213 | 7732Y | PIPER | | | | AXLE NUT | FAILED | | 3/26/98 |
| | 30821 | PA30 | | | | MS20364624C | NLG | | 98ZZZX1672 |
| ***** | AXLE NUT P/N MS 20364-624C (PIPER P/N 752-482) WORKED LOOSE AND FELL OFF OF NOSE GEAR AXLE TIE BOLT P/N 20854-00. THIS NUT IS ADJUSTED ONLY TIGHT ENOUGH TO REMOVE FREE PLAY ON NOSE WHEEL BEARINGS. IT IS NOT TORQUED TO A SPECIFIC TORQUE. WHEN NUT CAME OFF, THIS ALLOWED TIE BOLT TO SLIDE OUT OF NOSE GEAR TO THE SIDE. TIE BOLT THEN JAMMED NOSE GEAR IN THE UP POSITION. AFTER 1 HR OF TRYING TO DISLODGE L/G, ACFT LANDED WHEELS UP WITH NO INJURIES AND MINOR DAMAGE. SUBMITTER RECOMMENDED REPLACING ANY AXLE TIE BOLT WITH THREAD WEAR AND INSTALL NEW LOCKNUTS AND A SLIGHTLY LONGER TIE BOLT ALLOWING AN363C NUT (NOT THIN TYPE) OR DRILLED TIE BOLT FOR CASTLE NUT AND COTTER PIN ARRANGEMENT. TT ON ACFT IS 7,300 HRS. | | | | | | | | |
| 6320 | 1546G | SKRSKY | | | | SPUR GEAR | FRACTURED | | 4/27/98 |
| HEER | 760076 | S76A | | | | 7635109032047 | M/R GEARBOX | | 98ZZZX1706 |
| ***** | INVESTIGATION INTO A SERIES OF CHIP DETECTOR LIGHTS ON THE MAIN GEARBOX REVEALED THE SPUR GEAR HAD FRACTURED IN THREE PLACES. THE WEB OF THE GEAR HAD TWO SEPARATE FRACTURES AND THE SHAFT OF THE GEAR HAD ONE FRACTURE. TWO OF THE PINS (P/N HL12VLJ-8-5/6) THAT SECURE THE SPUR GEAR ASSEMBLY TOGETHER HAD ALSO SHEARED. MANY OTHER PINS SHOWED SIGNS OF WORKING. THE MAIN GEARBOX WAS OVERHAULED 227 OPERATING HOURS PRIOR TO THIS OCCURRENCE. THE SPUR GEAR IS NOT A LIFE LIMIT PART; THEREFORE, HISTORICAL RECORDS ARE NOT REQUIRED AND THE TOTAL TIME IN SERVICE OF THE GEAR IS NOT KNOWN AT THIS TIME. | | | | | | | | |
| 5210 | 51TB | SOCATA | | | | GUIDE | FAILED | 1628 | 3/19/98 |
| FO6R | 488 | TB20TRINIDAD | | | | TB1025042102 | RT DOOR FWD CAB | | 98ZZZX1668 |
| ***** | WHILE TROUBLESHOOTING AN AIR LEAK ON THE RT DOOR, DISCOVERED THE FWD DOOR LATCH WAS NOT OPERATING DUE TO A BROKEN LOWER LATCH GUIDE. FURTHER INVESTIGATION REVEALED THE BROKEN LATCH GUIDE WAS A P/N TB1025042100 GUIDE MADE OF PLASTIC INSTEAD OF THE PROPER P/N TB1025042102 GUIDE MADE OF MACHINED ALUMINUM. A CHECK OF THE OTHER DOOR LATCHES ON THE RT AND LT DOORS ALSO FOUND IMPROPER P/N GUIDES INSTALLED. THERE WAS NO RECORD OR INDICATIONS THAT THE GUIDES HAD BEEN PREVIOUSLY REPLACED. RECOMMEND INSPECTION OF DOOR LATCHES AND REPLACEMENT OF IMPROPER PARTS. | | | | | | | | |

(End of GENERAL AVIATION SIGNIFICANT OCCURRENCE REPORT)

Run Date: 15-May-98

FEDERAL AVIATION ADMINISTRATION SIGNIFICANT OCCURRENCE REPORT INDEX

Showing Specific Part Numbers and Aircraft Model by Year

FOR THE PERIOD OF: 5/3/98 To 5/9/98

| <u>PART NUMBER</u> | | <u>TOTAL</u> | <u>YEAR</u> | | | | | | | | | | | |
|---------------------------|-------------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| <u>PART NAME</u> | <u>ACFT MODEL</u> | | <u>1987</u> | <u>1988</u> | <u>1989</u> | <u>1990</u> | <u>1991</u> | <u>1992</u> | <u>1993</u> | <u>1994</u> | <u>1995</u> | <u>1996</u> | <u>1997</u> | <u>1998</u> |
| 0470 | | | | | | | | | | | | | | |
| NUT | MINI500 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # 0470 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| 05131329 | | | | | | | | | | | | | | |
| BRACKET | 175 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # 05131329 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| 05260074 | | | | | | | | | | | | | | |
| TANK | 172D | 1 | - | - | - | - | - | - | 1 | - | - | - | - | - |
| | 172E | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| | 172K | 1 | - | - | - | - | - | - | 1 | - | - | - | - | - |
| TOTAL of # 05260074 ----- | | 3 | - | - | - | - | - | - | 2 | - | - | - | - | 1 |
| 0541153 | | | | | | | | | | | | | | |
| U BOLT | 172 | 1 | - | - | - | - | - | 1 | - | - | - | - | - | - |
| | 172A | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - |
| | 172K | 1 | - | - | - | - | 1 | - | - | - | - | - | - | - |
| | 182A | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| U-BOLT | 172 | 2 | - | - | - | - | 1 | 1 | - | - | - | - | - | - |
| | 172B | 1 | - | - | - | - | 1 | - | - | - | - | - | - | - |
| | 172C | 1 | - | - | - | 1 | - | - | - | - | - | - | - | - |
| | 172D | 1 | - | - | - | - | - | 1 | - | - | - | - | - | - |
| | 172F | 1 | - | - | - | - | 1 | - | - | - | - | - | - | - |

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 5/3/98 To 5/9/98 (cont'd)

| <u>PART NUMBER</u> | | <u>YEAR</u> | | | | | | | | | | | | | |
|-----------------------------|-------------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--|
| <u>PART NAME</u> | <u>ACFT MODEL</u> | <u>TOTAL</u> | <u>1987</u> | <u>1988</u> | <u>1989</u> | <u>1990</u> | <u>1991</u> | <u>1992</u> | <u>1993</u> | <u>1994</u> | <u>1995</u> | <u>1996</u> | <u>1997</u> | <u>1998</u> | |
| 0541153 | | | | | | | | | | | | | | | |
| U-BOLT | 172G | 1 | - | - | - | - | - | - | - | - | - | 1 | - | - | |
| | 172H | 1 | - | - | - | - | - | - | 1 | - | - | - | - | - | |
| | 172K | 2 | - | - | - | - | 1 | - | - | - | - | 1 | - | - | |
| | 175 | 1 | - | - | - | 1 | - | - | - | - | - | - | - | - | |
| | 182A | 3 | - | - | - | - | 1 | - | 1 | - | - | 1 | - | - | |
| | 182B | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| | 182C | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 0541153 ----- | | 20 | - | - | - | 2 | 6 | 3 | 2 | - | - | 3 | 2 | 2 | |
| 0831192 | | | | | | | | | | | | | | | |
| GEAR LEG | 8A | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 0831192 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| 1090101063 | | | | | | | | | | | | | | | |
| DAMPER | A109K2 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 1090101063 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| 115610010325 | | | | | | | | | | | | | | | |
| CASTING | 100BEECH | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| SUPPORT | B100 | 1 | - | - | - | 1 | - | - | - | - | - | - | - | - | |
| TORQUE TUBE | 100BEECH | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| | 99 | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| | 99 | 1 | - | - | - | - | - | - | - | 1 | - | - | - | - | |
| | A100 | 1 | - | - | - | 1 | - | - | - | - | - | - | - | - | |
| | B100 | 2 | - | - | - | - | - | - | 1 | - | 1 | - | - | - | |
| | B99 | 1 | - | - | - | 1 | - | - | - | - | - | - | - | - | |

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 5/3/98 To 5/9/98 (cont'd)

| <u>PART NUMBER</u> | | <u>YEAR</u> | | | | | | | | | | | | | |
|-------------------------------|-------------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--|
| <u>PART NAME</u> | <u>ACFT MODEL</u> | <u>TOTAL</u> | <u>1987</u> | <u>1988</u> | <u>1989</u> | <u>1990</u> | <u>1991</u> | <u>1992</u> | <u>1993</u> | <u>1994</u> | <u>1995</u> | <u>1996</u> | <u>1997</u> | <u>1998</u> | |
| 115610010325 | | | | | | | | | | | | | | | |
| TORQUE TUBE | C99 | 1 | - | - | - | 1 | - | - | - | - | - | - | - | - | |
| | C99 | 3 | - | - | - | - | - | - | - | - | - | 1 | 1 | 1 | |
| TORQUE TUBE ASSY | 100BEECH | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| TORUQE TUBE | A100 | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| TOTAL of # 115610010325 ----- | | 15 | - | - | - | 4 | - | - | 1 | 1 | 1 | 1 | 5 | 2 | |
| 1156100181 | | | | | | | | | | | | | | | |
| CASTING | 100BEECH | 1 | - | - | - | - | - | 1 | - | - | - | - | - | - | |
| CONTROL TUBE | 99 | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| SUPPORT | 100BEECH | 1 | - | - | - | - | - | - | - | - | - | - | 1 | - | |
| | 100BEECH | 2 | - | - | - | - | - | - | 1 | - | - | - | 1 | - | |
| | A100 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| | C99 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 1156100181 ----- | | 7 | - | - | - | - | - | 1 | 1 | - | - | - | 3 | 2 | |
| 14421121 | | | | | | | | | | | | | | | |
| BARREL | 172RG | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 14421121 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| 1513 | | | | | | | | | | | | | | | |
| LIFT DETECTOR | E55 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 1513 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| 214010103115 | | | | | | | | | | | | | | | |
| SPINDLE | 214ST | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 214010103115 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| 23058110A | | | | | | | | | | | | | | | |
| TUBE | 206L4 | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |
| TOTAL of # 23058110A ----- | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 | |

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 5/3/98 To 5/9/98 (cont'd)


| <u>PART NUMBER</u> | | <u>YEAR</u> | | | | | | | | | | | | | |
|---|-------------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--|
| <u>PART NAME</u> | <u>ACFT MODEL</u> | <u>TOTAL</u> | <u>1987</u> | <u>1988</u> | <u>1989</u> | <u>1990</u> | <u>1991</u> | <u>1992</u> | <u>1993</u> | <u>1994</u> | <u>1995</u> | <u>1996</u> | <u>1997</u> | <u>1998</u> | |
| 2607003468 | | | | | | | | | | | | | | | |
| LINE | 35A | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| TOTAL of # 2607003468 - - - - - | | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| 400088001 | | | | | | | | | | | | | | | |
| BELLCRANK | PA60600 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| | PA60600A | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | |
| TOTAL of # 400088001 - - - - - | | <u>2</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>1</u> | |
| 6210201 | | | | | | | | | | | | | | | |
| BRACKET | PA28140 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | |
| SUPPORT | PA28140 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| | PA28180 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | |
| SUPPORT ASSEMBLY | PA32260 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | |
| TOTAL of # 6210201 - - - - - | | <u>4</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>1</u> | |
| 65412045 | | | | | | | | | | | | | | | |
| STUD | 550 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| TOTAL of # 65412045 - - - - - | | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| 730048001 | | | | | | | | | | | | | | | |
| CONTROL ROD | M20K | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| TOTAL of # 730048001 - - - - - | | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| 7635109032047 | | | | | | | | | | | | | | | |
| SPUR GEAR | S76A | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| TOTAL of # 7635109032047 - - - - - | | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| 991030130 | | | | | | | | | | | | | | | |
| EXHAUST STACK | 335 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| TOTAL of # 991030130 - - - - - | | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| MS20364624C | | | | | | | | | | | | | | | |
| AXLE NUT | PA30 | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| TOTAL of # MS20364624C - - - - - | | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | |
| S19911 | | | | | | | | | | | | | | | |
| CONTACTOR | 150M | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>1</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | <u>-</u> | |

FAA SIGNIFICANT OCCURRENCE REPORT INDEX 5/3/98 To 5/9/98 (cont'd)

| <u>PART NUMBER</u> | | <u>YEAR</u> | | | | | | | | | | | | |
|---|--------------------------|---------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| <u>PART NAME</u> | <u>ACFT MODEL</u> | <u>TOTAL</u> | <u>1987</u> | <u>1988</u> | <u>1989</u> | <u>1990</u> | <u>1991</u> | <u>1992</u> | <u>1993</u> | <u>1994</u> | <u>1995</u> | <u>1996</u> | <u>1997</u> | <u>1998</u> |
| S19911 | | | | | | | | | | | | | | |
| SOLENOID | 172L | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # S19911 - - - - - | | 2 | - | - | - | - | - | - | 1 | - | - | - | - | 1 |
| S21381 | | | | | | | | | | | | | | |
| BOLT | 172N | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # S21381 - - - - - | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TB1025042102 | | | | | | | | | | | | | | |
| GUIDE | TB20TRINIDAD | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # TB1025042102 - - - - - | | 1 | - | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL for ALL (61) PART NUMBERS: - - - - | | 69 | - | - | - | 7 | 6 | 4 | 8 | 1 | 1 | 4 | 12 | 26 |
| END OF SIGNIFICANT OCCURRENCE REPORT INDEX | | | | | | | | | | | | | | |



DOMESTIC SERVICE DIFFICULTY REPORT



DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-----------------------------|---------------------------|------------------------|----------------------------|
| 8120 KVJA | 621KE BA556 | BEECH G18S | | | | GEAR 8797 | FAILED REAR SECTION | 4/3/98 91 | 98ZZZX1652 |
| SUPERCHARGER INPUT GEAR FAILED. CAUSE UNKNOWN. | | | | | | | | | |
| 5522 | 520MC BB43 | BEECH 200BEECH | | | | ELEVATOR 101610000606 | DAMAGED RT OUTBOARD | 8540 | 10/9/97 97ZZZX5116 |
| AFTER A HANGAR RASH INCIDENT, THE RIGHT ELEVATOR WAS BEING REPAIRED FOR DAMAGE TO THE FIBERGLASS TIP. AFTER REMOVAL OF THE TIP, THREE HOLES IN THE OUTBOARD TRAILING EDGE AREA OF THE SKIN WERE FOUND FILLED WITH BODY FILLER. THE FILLER WAS REMOVED AND AN ALUMINUM DOUBLER WAS INSTALLED AFTER BEING APPROVED ON FORM 8110-3. | | | | | | | | | |
| 5620 | 60PD BB58 | BEECH 200BEECH | | | | WINDOWS 1014301835 | DELAMINATED NR 5 RT | 11/18/97 97ZZZX5120 | |
| DURING ROUTINE CLEANING OF THE AIRCRAFT WINDOWS, DELAMINATION BUBBLES WERE NOTED NEAR THE BOTTOM EDGE AREA OF THE NR 5 PASSENGER WINDOW. BUBBLES WERE ABOUT THE SIZE OF A PENCIL ERASER OR SMALLER. TOTAL AREA WAS APPROXIMATELY 8 INCHES BY .50 INCH. WINDOW WAS REPLACED WITH NEW. | | | | | | | | | |
| 5730 | 56CC BB189 | BEECH 200BEECH | | | | PANEL | CRACKED RT WING OTBD | 8093 97ZZZX5119 | 11/13/97 |
| THE INBOARD AREA OF THE RIGHT OUTBOARD WING PANEL HAS A .3750 INCH CRACK FROM THE TOP OF THE RADIUS CUT-OUT ON THE LEADING EDGE FAIRING. | | | | | | | | | |
| 5753 | 56CC BB189 | BEECH 200BEECH | | | | BRACKET | CRACKED RT OTBD FLAP | 893 97ZZZX5117 | 11/13/97 |
| DURING INSPECTION, A .50 INCH CRACK WAS NOTED WHERE THE BRACKET FOR THE FLAP INNER CONNECT ATTACHES ON THE RIGHT OUTBOARD FLAP. IT APPEARS THE ROD END FOR THE INNER CONNECT WAS LOOSE WHERE IT ATTACHED TO THE BRACKET AND ALLOWED ENOUGH PLAY FOR THE ROD END TO STRIKE THE BASE OF THE BRACKET CAUSING A CRACK. | | | | | | | | | |
| 5753 | 56CC BB189 | BEECH 200BEECH | | | | SKIN | CRACKED INBD FLAP | 8093 97ZZZX5118 | 11/13/97 |
| DURING INSPECTION, A .75 INCH CRACK WAS FOUND NEAR A RIVET WHICH ATTACHES THE ENGINE NACELLE TRAILING EDGE FAIRING TO THE INBOARD FLAP. THE CRACK WOULD NOT HAVE RESULTED IN ANY DAMAGE, BUT SINCE IT IS PART OF A CONTROL SURFACE, RESULTED IN BEING A MAJOR REPAIR. | | | | | | | | | |
| 5512 | 228RA LW197 | BEECH E90 | | | 50600001623 | SKIN 5062000153 | CRACKED LT HORIZ STAB | 5794 97ZZZX5115 | 11/3/97 |
| AFTER REMOVAL OF THE SURFACE DE-ICE BOOT, A SMALL CRACK APPROXIMATELY .6250 INCH LONG WAS FOUND RADIATING FROM A RIVET HOLE ON THE LEFT HORIZONTAL STABILIZER AT STA 63.0. THE CRACK WAS RADIATING OUTBOARD AND AFT. CRACKED AREA WAS REMOVED AND A FLUSH DOUBLER WAS INSTALLED. | | | | | | | | | |
| 2730 EHHR | 6645K U209 | BEECH C99 | | | | TORQUE TUBE 115610010325 | CRACKED ELEVATOR | 2/26/98 98ZZZX1634 | |
| ***** ELEVATOR TORQUE TUBE ASSY, P/N 115610010325, INSPECTED PER SB 2145 (RECURRING) DATED APRIL, 1986. AIRCRAFT HISTORY INDICATES NUMEROUS REPLACEMENTS DUE TO CRACKS IN SUPPORT ASSY, P/N 1156100181, OR TORQUE TUBE, P/N 11510010325. | | | | | | | | | |
| 2730 EHHR | 6656N U213 | BEECH C99 | | | 115610010325 | SUPPORT 1156100181 | CRACKED ELEV TORQ TUBE | 702 98ZZZX1635 | 2/26/98 |
| ***** ELEVATOR TORQUE TUBE SUPPORT IS INSPECTED EACH 1,000 HOUR RECURRING PER SB 2145, DATED APRIL, 1986. AIRCRAFT HISTORY INDICATES NUMEROUS REPLACEMENTS DUE TO CRACKS OF SUPPORT ASSY, P/N 115610181 OR TORQUE TUBE, P/N 115610010325. | | | | | | | | | |

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|---|-------------------------|---------------------|-----------------------|----------------------|---------------------------|---------------------------|-----------|----------------------------|
| 3231 JDWA | 118SF U32 | BEECH 99 | | | 1158100366 | CAM 15810038 | BENT RT OTBD MLG DOOR | | 4/6/98 98ZZZX1689 |
| PIC REPORTED THE INABILITY TO EXTEND THE LANDING GEAR ELECTRICALLY, WITH A LOUD BANG NOTED IMMEDIATELY UPON EXTENSION. THE LANDING GEAR WAS EXTENDED MANUALLY, AND THE AIRCRAFT LANDED WITHOUT FURTHER INCIDENT. SUBSEQUENT INVESTIGATION DISCLOSED A TRIPPED LANDING GEAR CIRCUIT BREAKER, AND A BENT RT OUTBOARD MLG DOOR ACTUATING CAM. THE GEAR DOOR ROLLER ASSY STRUCK THE UNDERSIDE OF THE LANDING GEAR ACTUATING CAM CAUSING THE GEAR TO BIND IN THE WHEEL WELL. INVESTIGATION FAILED TO DETERMINE A CAUSE. THE CAM ASSY MAY HAVE BEEN MIS-RIGGED, OR FAILED TO SNAP OVERCENTER DUE TO WEAK RETURN SPRINGS. | | | | | | | | | |
| 2731 | 7201Q 17260501 | CESSNA 172L | | | | ACTUATOR 12600741 | WORN ELEVATOR TRIM | 4749 | 4/6/98 98ZZZX1654 |
| HAD EXCESSIVE PLAY. MAXIMUM PLAY .131 - HAS .330 PLAY. INSTALLED NEW PART. | | | | | | | | | |
| 2810 | 3799S 17250999 | CESSNA 172E | | | | TANK 0526007201 | BROKEN WELD BAFFLE | 5033 | 4/22/98 98ZZZX1650 |
| WHILE MOVING AIRCRAFT A CLICKING SOUND WAS HEARD. AFTER LOOKING IN THE GAS CAP, A LARGE PART WAS FOUND SLIDING AROUND IN FUEL TANK. AFTER A CLOSER LOOK, FOUND BROKEN WELDS ON INTERNAL RIB OR BAFFLE. CAUSE WAS FUEL MOVEMENT IN TANK, AND RIB WAS ONLY WELDED ON ONE SIDE OF RIB. IF WELDED ON BOTH SIDES, IT MAY HAVE NOT BROKEN LOOSE. IF THE RIB WOULD STICK UNDER FUEL GAUGE, FLOAT COULD INDICATE MORE FUEL THAN WAS IN TANK. | | | | | | | | | |
| 2810 | 3799S 17250999 | CESSNA 172E | | | | TANK 05260074 | BROKEN WELD BAFFLE | 5033 | 4/22/98 98ZZZX1651 |
| ***** | WHILE MOVING AIRCRAFT A CLICKING SOUND WAS HEARD. AFTER LOOKING IN THE GAS CAP, A LARGE PART WAS FOUND SLIDING AROUND IN FUEL TANK. AFTER A CLOSER LOOK, FOUND BROKEN WELDS ON INTERNAL RIB OR BAFFLE. CAUSE WAS FUEL MOVEMENT IN TANK, AND RIB WAS ONLY WELDED ON ONE SIDE OF RIB. IF WELDED ON BOTH SIDES, IT MAY HAVE NOT BROKEN LOOSE. IF THE RIB WOULD STICK UNDER FUEL GAUGE, FLOAT COULD INDICATE MORE FUEL THAN WAS IN TANK. | | | | | | | | |
| 3211 VT3R | 6360D 17272746 | CESSNA 172N | | | | BOLT S21381 | FAILED LT MLG MOUNT | 9401 | 3/19/98 98ZZZX1669 |
| ***** | DURING ROLL-OUT, PILOT LOST DIRECTIONAL CONTROL AND AIRCRAFT VEERED OFF RUNWAY INTO THE DIRT. AFTER CONTACTING UNEVEN TERRAIN, THE LT MLG STRUT COLLAPSED AFT CAUSING DAMAGE TO LT MLG FAIRINGS, FUSELAGE, AND LT STABILIZER/ELEVATORS. INSPECTION SHOWED THE P/N S2138-1 BOLT HAD BROKEN INSIDE STRUT ALLOWING STRUT TO ROTATE AFT. METALLURGICAL ANALYSIS DETERMINED THE BOLT WAS PREVIOUSLY CRACKED. SUBMITTER RECOMMENDED A SAFE LIFE LIMIT BE ESTABLISHED. | | | | | | | | |
| 3242 | 97LP 17274398 | CESSNA 172P | | | | DISC 164306151 | OVERHEATED RT MLG | | 10/21/97 97ZZZX5127 |
| UPON INSTALLATION OF NEW CLEVELAND BRAKE DISC AND LININGS ON RT MAIN WHEEL, ACFT WAS TAXIED FOR RUN-UP AND LOUD SQUEELING EMITTED FROM RT BRAKE. PAINT ON DISC DAMAGED LININGS AND CAUSED OVERHEATING. REMOVED PAINT FROM DISC WHERE PADS RIDE, INSTALLED NEW LININGS, CHECKED SATISFACTORILY. SUBMITTER STATED NEW BRAKE DISC'S SHOULD NOT BE PAINTED WHERE LININGS RIDE. CONTACTED PARKER HANNIFIN CORP. | | | | | | | | | |
| 3252 | 7201Q 17260501 | CESSNA 172L | | | | DAMPENER 04425121 | WORN NLG | 4749 | 4/6/98 98ZZZX1653 |
| SHIMMY DAMPENER HAD NO FLUID AND SHAFT WOULD NOT COME OUT FOR OVERHAUL. INSTALLED NEW PART. | | | | | | | | | |
| 3252 | 5331V 172RG0506 | CESSNA 172RG | | | | BARREL 14421121 | FAILED SHIMMY DAMPENER | | 11/1/97 97ZZZX5129 |
| ***** | AIRCRAFT WAS BROUGHT TO MAINTENANCE AFTER A TRAINING FLIGHT WITH REPORT OF A SEVERE NOSE WHEEL VIBRATION. AN INSPECTION REVEALED THAT THE END OF THE SHIMMY DAMPENER BARREL CLOSEST TO THE SERVICE HOLE WAS BROKEN OFF. THE OUTER RETAINING LINE AND BEARING HEAD WERE MISSING. | | | | | | | | |
| 5753 | 738QA 17270144 | CESSNA 172N | | | 052390138 | ROLLER BEARING 0523920 | WORN RT OTBD FLAP | | 3/20/98 98ZZZX1671 |
| RT OUTBOARD LOWER FLAP ROLLER JAMMED IN TRACK CAUSING EXTENSIVE FLAP DAMAGE AND INABILITY TO RAISE FLAPS TO FULL UP POSITION. UPON LANDING, FLAP ROLLER FOUND WORN THROUGH TO ATTACH HARDWARE INDICATING IT HAD NOT BEEN ROLLING, BUT SLIDING IN TRACK. HAVE FOUND SIMILAR 'STUCK' ROLLERS ON OTHER 172 AIRCRAFT DUE TO IMPROPER INSTALLATION OF WASHER STACK ON BOTH SIDES OF ROLLER. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 8010 | 9898G | CESSNA | | | | SOLENOID | FAILED | 2445 | 4/19/98 |
| | 17259798 | 172L | | | | S19911 | STARTER | | 98ZZZX1678 |
| ***** | WHEN AIRCRAFT MASTER SWITCH WAS TURNED ON THE STARTER ENGAGED CAUSING THE PROPELLER TO TURN. THE SOLENOID P/N S-199-1 WAS REMOVED AND OPENED UP. WATER, RUST, AND CORROSION WERE FOUND. THIS CAUSED THE SOLENOID TO REMAIN IN THE CLOSED POSITION. THIS CONDITION IS A SERIOUS SAFETY CONDITION AND COULD CAUSE INJURY OR DEATH. A NEW SOLENOID WAS INSTALLED, IT WAS SEALED WITH EPOXY PRIOR TO INSTALLATION TO PREVENT WATER OR MOISTURE FROM ENTERING IT. THE LOCATION OF THE SOLENOID IN THE COWLING ALLOWS RAIN TO ENTER THE UNIT. | | | | | | | | |
| 7120 | 7518M | CESSNA | | | | BRACKET | CRACKED | | 10/17/97 |
| BX4R | 55818 | 175 | | | | 051313210 | ENG MT ATTACH | | 97ZZZX5124 |
| | ALL FOUR ENGINE MOUNT BRACKETS ON THE FORWARD END OF THE ENGINE MOUNT STRINGERS WERE CRACKED AND HOLE AREA BENT OUT. THIS AREA BULGED OUT AROUND BOLT HOLE. AIRCRAFT HAS LYCOMING 180 HP MOD. | | | | | | | | |
| 7120 | 7518M | CESSNA | | | | BRACKET | CRACKED | | 10/17/97 |
| BX4R | 55818 | 175 | | | | 05131329 | ENG MT ATTACH | | 97ZZZX5123 |
| ***** | ALL FOUR ENGINE MOUNT BRACKETS ON THE FORWARD END OF THE ENGINE MOUNT STRINGERS WERE CRACKED AND HOLE AREA BENT OUT. THIS AREA BULGED OUT AROUND BOLT HOLE. AIRCRAFT HAS LYCOMING 180 HP MOD. | | | | | | | | |
| 7120 | 7518M | CESSNA | | | | BRACKET | CRACKED | | 10/17/97 |
| BX4R | 55818 | 175 | | | | 051313211 | ENG MT ATTACH | | 97ZZZX5125 |
| | ALL FOUR ENGINE MOUNT BRACKETS ON THE FORWARD END OF THE ENGINE MOUNT STRINGERS WERE CRACKED AND HOLE AREA BENT OUT. THIS AREA BULGED OUT AROUND BOLT HOLE. AIRCRAFT HAS LYCOMING 180 HP MOD. | | | | | | | | |
| 2720 | 5545S | CESSNA | | | | RUDDER BAR | FAILED | 3147 | 4/16/98 |
| | R18201604 | R182 | | | | | RT RUDDER | | 98ZZZX1666 |
| | RIGHT HAND RUDDER BAR ASSEMBLY, WELDED ON FITTING THAT CONNECTS TO NOSE GEAR STEERING AND CONTROLS RUDDER TRIM, BROKE AWAY FROM RUDDER BAR ASSY. UPON INSPECTION OF WELDED FITTING, IT APPEARS TO HAVE BEEN A COLD WELD. | | | | | | | | |
| 3211 | 8655T | CESSNA | | | | U-BOLT | FAILED | 4450 | 4/21/98 |
| | 52555 | 182C | | | | 0541153 | LT MLG | | 98ZZZX1673 |
| ***** | DURING 100-HOUR INSPECTION, ONE LEG OF THE U-BOLT ON THE LT MAIN GEAR LEG WAS FOUND BROKEN IN THE THREAD AREA. SUBMITTER SUSPECTS IT WAS DUE TO FATIGUE. A CLOSER LOOK AT THESE BOLTS DURING INSPECTION WOULD BE IN ORDER. | | | | | | | | |
| 3030 | 709FX | CESSNA | | | | PITOT HEAT | FAILED | 1148 | 3/31/98 |
| COEA | 208B0430 | 208B | | | | | RT WING | | COEA9801709 |
| | DURING CLIMB-OUT IN IMC CONDITIONS, THE PAR WARNING ILLUMINATED INDICATING EXCESS AIRSPEED. COPILOT AIRSPEED INDICATOR WAS ABOVE REDLINE. PILOT DECLARED AN EMERGENCY AND RETURNED TO BASE WITHOUT EVENT. MAINTENANCE FOUND NR 2 PITOT HEAT INOPERATIVE AND HAD ICED OVER IN-FLIGHT CAUSING COPILOT AIRSPEED TO INDICATE ABOVE ACTUAL. NR 2 PITOT TUBE WAS REPLACED. STATIC SYSTEM LEAK CHECKED SATISFACTORY. PITOT HEAT SYSTEM FUNCTION CHECK SATISFACTORY. AIRCRAFT RETURNED TO SERVICE. (X) | | | | | | | | |
| 5511 | 59063 | CESSNA | | | | SPAR | CRACKED | | 1/28/98 |
| | 21060062 | 210L | | | | 123262224 | STABILIZER | | 98ZZZX1636 |
| | CRACKS HAVE BEEN FOUND ON THE REAR STABILIZER SPAR. SUSPECT CRACKS ARE CAUSED BY IMPROPER USE OF A RIVET SQUEEZER DURING FACTORY INSTALLATION. SUBMITTER STATED THESE CRACKS AND TOOLING MARKS HAVE BEEN FOUND ON 4 OTHER ASSEMBLIES. CRACKS RANGE IN SIZE FROM .25 INCH TO .50 INCH LONG, AND ARE FOUND ABOVE THE RIVET TAIL. | | | | | | | | |
| 7810 | 335PC | CESSNA | | | | EXHAUST STACK | WORN | | 3/18/98 |
| | 3350053 | 335 | | | | 991030130 | LT ENG INBD | | 98ZZZX1662 |
| ***** | DURING A ROUTINE ENGINE CHANGE, THE EXHAUST COMPONENTS WERE INSPECTED AND THE LEFT ENGINE, INBOARD EXHAUST STACK (ELBOW) WAS FOUND WITH 2 LARGE HOLES CAUSED BY CONTACT FROM THE HEAT SHIELDS MOUNTED ABOVE THE ELBOW. THE HEAT SHIELDS ALSO HAD HOLES IN THEM AND WERE BURNED BY THE ESCAPING EXHAUST GASSES. ROUTED DIRECTLY ABOVE THE HEAT SHIELDS IS THE MAIN WIRE BUNDLE CONTAINING ALL NECESSARY WIRING FROM THE LEFT ENGINE. SEVERAL WIRES SHOWED SIGNS OF HEAT DAMAGE TO THE INSULATION AND ONE WIRE WAS BURNED COMPLETELY IN HALF. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------------|-----------|----------------------------|
| 8120 GNXA | 38CJ 402C0023 | CESSNA 402C | | | | VALVE C1650060107 | LEAKING WASTEGATE | 682 | 4/3/98 98ZZZX1661 |
| DURING FLIGHT AT 10,000 MSL, PILOT NOTICED THAT OIL PRESSURE ON RIGHT ENGINE WAS DROPPING SLOWLY AND OIL TEMP WAS RISING SLOWLY FOLLOWED SHORTLY BY A COMPLETE LOSS OF MANIFOLD PRESSURE. THE PILOT TOOK PRECAUTIONARY MEASURES AND SHUT DOWN ENGINE. HE CONTINUED ON AND MADE AN UNEVENTFUL SINGLE ENGINE LANDING. MAINTENANCE PERSONNEL FOUND THE WASTEGATE ACTUATOR FAILED AND ALL THE ENGINE OIL WAS DUMPED. INSPECTION REVEALED THE SEAL INSIDE THE ACTUATOR WAS BAD. AN OVERHAUL OF THE COMPLETE ASSY REPAIRED THE PROBLEMS. NO KNOWN CAUSE FOR SEAL FAILURE. | | | | | | | | | |
| 2710 EBVR | 674G 5500435 | CESSNA 550 | | | | CABLE | MISINSTALLED TERMINAL END | 4295 | 6/22/94 94ZZZX4575 |
| DURING PHASE 5 INSPECTION, AILERON CONTROL CABLES AT THE COCKPIT YOKES WERE REMOVED FOR INSPECTION. AT YOKE DISASSEMBLY, FOUND CABLE TERMINAL END HARDWARE NOT PROPERLY INSTALLED. NUTS WERE ONLY ON THE AN3 BOLTS BY 2-3 THREADS AND FIBER LOCK WAS NOT ENGAGED. ALL FOUR CABLES WERE FOUND IN THIS CONDITION. HAD THEY COME OFF, AILERON CONTROL WOULD HAVE BEEN LOST. | | | | | | | | | |
| 3233 GMNR | 310AV 5500028 | CESSNA 550 | | | | STUD 65412045 | FAILED MLG ACTUATOR | | 4/1/98 98ZZZX1692 |
| ***** IN PERFORMING 10,000-HOUR MLG INSPECTION AND UPON INSTALLING NUT ON STUD, STUD SHEERED IN HALF AT BASE OF THREADED AREA ALLOWING ACTUATOR TO SEPARATE FROM LANDING GEAR. AIRCRAFT WAS ON JACKS. UPON INSPECTION OF STUD, DETERMINED IT WAS CRACKED AND CORRODED. | | | | | | | | | |
| 2435 | 515AM 95008 | GULSTM 695 | | LEARSIEGLER | | STARTER 230790001 | FAILED START/GEN | 1023 | 2/3/98 98ZZZX1638 |
| UPON REMOVAL OF STARTER/GENERATOR, FOUND MAIN SHAFT BEARING FAILED CAUSING AN INTERNAL SHORT TO STARTER HOUSING. PER OPERATOR, FAILURE WAS NOT ABNORMAL AND DUE TO TIME ON COMPONENT. | | | | | | | | | |
| 3213 | 2750K 5477 | LUSCOM 8A | | | | GEAR LEG 0831192 | FAILED RT MLG | 1710 | 4/10/98 98ZZZX1659 |
| ***** CORROSION INTERNALLY. FRACTURE ABOVE WELD BELOW BRAKE PULLEY. TOTAL GEAR FAILURE ON RIGHT GEAR ON LANDING. SEE LUSCOMBE NEW LETTER NR 113. | | | | | | | | | |
| 2710 EA6R | 261CB 250391 | MOONEY M20K | | | | CONTROL ROD 730048001 | RUSTED RT AILERON | 3967 | 1/15/98 98ZZZX1698 |
| ***** DURING ANNUAL INSPECTION NOTED AILERON ROD RUSTY. UPON FURTHER INSPECTION, FOUND ROD RUSTED TO THE EXTENT IT COULD BE SEPARATED IN TWO WITH LIGHT HAND PRESSURE. SUBMITTER RECOMMENDED INSPECTING AT EACH ANNUAL. | | | | | | | | | |
| 3230 BONR | 60DC 600797806123 | PIPER PA60600 | | | | BELLCRANK 400088001 | CRACKED LT MLG WELL | 5261 | 3/31/98 98ZZZX1695 |
| ***** DURING ROUTINE TRAINING FLIGHT, TOWER REPORTED THE LT MLG INBOARD DOOR REMAINED OPEN AFTER LANDING GEAR EXTENSION. AIRCRAFT LANDED WITHOUT INCIDENT. INSPECTED AIRCRAFT AND FOUND LT MLG BELLCRANK P/N 400088-001 BROKEN. THIS ALLOWED SEQUENCE VALVE TO OPEN CAUSING MLG DOOR TO FREEFALL OPEN. THE SAME PROBLEM OCCURRED IN 1994 TO RT BELLCRANK WITH 4,266.3 HRS TT. THE REPLACEMENT LT BELLCRANK IS SUBSTANTIALLY IMPROVED OVER ORIGINAL PART. SUBMITTER RECOMMENDED A SERVICE BULLETIN TO REQUIRE FREQUENT INSPECTIONS OF ORIGINAL PARTS. | | | | | | | | | |
| 3060 JGVR | | PIPER PA23250 | | | 758180 | BRACKET 758243 | CRACKED DEICE BRUSH BLK | | 4/16/98 98ZZZX1679 |
| CUSTOMER RETURNED P/N 758-180 (4E1515-3) PROP DEICE BRUSH BLOCK ASSY BECAUSE BRACKET P/N 758-243 (431514-2) WAS CRACKED IN RADIUS OF BEND. | | | | | | | | | |
| 3230 | 51ME 277854066 | PIPER PA23250 | | | 1619800 | BOLT 400235 | FAILED NLG DRAG BRACE | | 4/15/98 98ZZZX1667 |
| UPPER NOSE GEAR DRAG BRACE BOLT FAILED. FAILURE OCCURRED ON BOLT UNDER DRAG BRACE BUSHING. METAL FATIGUE IS SUSPECTED REASON FOR FAILURE. SUBMITTER SUGGESTED REMOVING AND VISUALLY INSPECTING BOLT AND/OR PERFORM NDT OF BOLT. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 2710 | 9729W | PIPER | | | | SUPPORT | CRACKED | | 4/1/98 |
| | 2823207 | PA28140 | | | | 6210200 | AIL BELLCRANK | | 98ZZZX1676 |
| | AILERON BELLCRANK SUPPORTS BROKEN AT FORWARD ENDS OF SUPPORT. THE DAMAGE HAS TO BE FOUND WITH A MIRROR. THE BELLCRANK SUPPORTS LOOK SATISFACTORY LOOKING IN THE ACCESS HOLES ORIGINALLY INSTALLED BY PIPER. THE FRONT FLANGE OF THE AILERON BELLCRANK SUPPORT BRACKETS FRONT BOLT HOLES FOR MOUNTING CRACKED COMPLETELY FROM ONE FLANGE SUPPORT EDGE TO THE OTHER. SUSPECT CAUSED BY HIGH WINDS AND NO AILERON LOCKING PROVISION ON THIS AIRCRAFT. THE DAMAGE IS HIDDEN BY THE WAY THE SUPPORTS' FLANGE IS BENT UP ON THE OUTBOARD EDGE. THE INBOARD FLANGE THAT IS BOLTED AND RIVETED TO THE RIB IS THE AREA THAT CRACKS. | | | | | | | | |
| 2710 | 9729W | PIPER | | | | SUPPORT | CRACKED | | 4/1/98 |
| | 2823207 | PA28140 | | | | 6210201 | AIL BELLCRANK | | 98ZZZX1677 |
| ***** | AILERON BELLCRANK SUPPORTS BROKEN AT FORWARD ENDS OF SUPPORT. THE DAMAGE HAS TO BE FOUND WITH A MIRROR. THE BELLCRANK SUPPORTS LOOK SATISFACTORY LOOKING IN THE ACCESS HOLES ORIGINALLY INSTALLED BY PIPER. THE FRONT FLANGE OF THE AILERON BELLCRANK SUPPORT BRACKETS FRONT BOLT HOLES FOR MOUNTING CRACKED COMPLETELY FROM ONE FLANGE SUPPORT EDGE TO THE OTHER. SUSPECT CAUSED BY HIGH WINDS AND NO AILERON LOCKING PROVISION ON THIS AIRCRAFT. THE DAMAGE IS HIDDEN BY THE WAY THE SUPPORTS' FLANGE IS BENT UP ON THE OUTBOARD EDGE. THE INBOARD FLANGE THAT IS BOLTED AND RIVETED TO THE RIB IS THE AREA THAT CRACKS. | | | | | | | | |
| 5412 | 6166H | PIPER | | | | FIREWALL | CORRODED | 2108 | 9/17/97 |
| H8AR | 28R7803093 | PA28R201T | | | | 3575305 | TURBO AREA | | 97ZZZX5122 |
| | HOLE IN FIREWALL OBSERVED DURING ANNUAL INSPECTION. UPON REMOVAL, FOUND INTERIOR CORROSION MUCH MORE ADVANCED THAN EXTERIOR. HOLE SEEMED TO BE CAUSED BY CONSTANT EXPOSURE TO TURBOCHARGER OPERATING TEMPERATURES. PLASTIC ON AFT SIDE OF FIREWALL EXHIBITED SIGNS OF THERMAL BREAKDOWN AND CHARRING. | | | | | | | | |
| 5412 | 36751 | PIPER | | | | FIREWALL | CORRODED | | 10/27/97 |
| H8AR | 28R7803339 | PA28R201T | | | | 3575305 | TURBO AREA | | 97ZZZX5121 |
| | DURING MAINTENANCE FOR ALTERNATOR FAILURE, FOUND FIREWALL HAD A HOLE DUE TO CORROSION. SUSPECT CORROSION DUE TO HEAT EXPOSURE FROM TURBOCHARGER. | | | | | | | | |
| 3213 | 7732Y | PIPER | | | | AXLE NUT | FAILED | | 3/26/98 |
| | 30821 | PA30 | | | | MS20364624C | NLG | | 98ZZZX1672 |
| ***** | AXLE NUT P/N MS 20364-624C (PIPER P/N 752-482) WORKED LOOSE AND FELL OFF OF NOSE GEAR AXLE TIE BOLT P/N 20854-00. THIS NUT IS ADJUSTED ONLY TIGHT ENOUGH TO REMOVE FREE PLAY ON NOSE WHEEL BEARINGS. IT IS NOT TORQUED TO A SPECIFIC TORQUE. WHEN NUT CAME OFF, THIS ALLOWED TIE BOLT TO SLIDE OUT OF NOSE GEAR TO THE SIDE. TIE BOLT THEN JAMMED NOSE GEAR IN THE UP POSITION. AFTER 1 HR OF TRYING TO DISLodge L/G, ACFT LANDED WHEELS UP WITH NO INJURIES AND MINOR DAMAGE. SUBMITTER RECOMMENDED REPLACING ANY AXLE TIE BOLT WITH THREAD WEAR AND INSTALL NEW LOCKNUTS AND A SLIGHTLY LONGER TIE BOLT ALLOWING AN363C NUT (NOT THIN TYPE) OR DRILLED TIE BOLT FOR CASTLE NUT AND COTTER PIN ARRANGEMENT. TT ON ACFT IS 7,300 HRS. | | | | | | | | |
| 3260 | 92877 | PIPER | | | | SWITCH | OUT OF ADJUST | 76 | 2/6/98 |
| | 3246078 | PA32R301 | | | | | RT MLG DOWNLOCK | | 98ZZZX1674 |
| | GEAR DOWN LIGHT DID NOT COME ON WHEN THE GEAR WAS EXTENDED. FOUND RT MLG DOWNLOCK LIGHT SWITCH OUT OF ADJUSTMENT. JACKED AIRCRAFT AND ADJUSTED SWITCH. | | | | | | | | |
| 5210 | 51TB | SOCATA | | | | GUIDE | FAILED | 1628 | 3/19/98 |
| FO6R | 488 | TB20TRINIDAD | | | | TB1025042102 | RT DOOR FWD CAB | | 98ZZZX1668 |
| ***** | WHILE TROUBLESHOOTING AN AIR LEAK ON THE RT DOOR, DISCOVERED THE FWD DOOR LATCH WAS NOT OPERATING DUE TO A BROKEN LOWER LATCH GUIDE. FURTHER INVESTIGATION REVEALED THE BROKEN LATCH GUIDE WAS A P/N TB1025042100 GUIDE MADE OF PLASTIC INSTEAD OF THE PROPER P/N TB1025042102 GUIDE MADE OF MACHINED ALUMINUM. A CHECK OF THE OTHER DOOR LATCHES ON THE RT AND LT DOORS ALSO FOUND IMPROPER P/N GUIDES INSTALLED. THERE WAS NO RECORD OR INDICATIONS THAT THE GUIDES HAD BEEN PREVIOUSLY REPLACED. RECOMMEND INSPECTION OF DOOR LATCHES AND REPLACEMENT OF IMPROPER PARTS. | | | | | | | | |
| 7160 | 4631V | VARGA | | | BRACKETT | GASKET | DETERIORATED | | 4/1/98 |
| | VAC8777 | 2150AMORISY | | | | BA4101 | CARB HEAT BOX | | 98ZZZX1663 |
| | DURING ANNUAL INSPECTION, FOUND CARBURETOR HEAT BOX GASKET P/N BA-4101 (BRACKETT) IN A DETERIORATED CONDITION. ON VARGA MODEL 2150A THERE ARE TWO BA-4101 GASKETS. ONE BETWEEN THE AIR VARGA P/N 30020-31 DUCT ASSY, AND ONE BETWEEN DUCT ASSY AND VARGA P/N 30020-32 CARBURETOR HEAT BOX. THE GASKET BETWEEN THE CARB AIR BOX AND DUCT ASSY IS THE SAME GASKET THAT AD 96-09-06 APPLIES. AIRCRAFT TT 1,526.0 HOURS, TT ON PART UNKNOWN. | | | | | | | | |

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT)

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS

5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--------------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|---------------------------|-----------|----------------------------|
| 3425 HEEA | 866MP 5089 | AEROSP AS355F1 | | | KA51A | SYNCHRO 071105304 | DEFECTIVE COCKPIT HSI | | 4/9/94 HEEA942216 |
| | HSI 20 DEGREES - 100 DEGREES OFF. | | | | | | | | |
| 3452 HEEA | 5785Y 5105 | AEROSP AS355F1 | | | KT76 | TRANSPONDER 066106200 | INOP COCKPIT | | 5/7/94 HEEA942178 |
| | TRANSPONDER PUTS OUT NO SIGNAL. TROUBLESHOT AND REPLACED TRANSISTOR Q415, CAVITY OSCILLATOR V101 AND ADJUSTED 9 VOLT POWER SUPPLY. REPAIRED PROBLEM. | | | | | | | | |
| 7320 | 942MS 5498 | AEROSP AS355F2 | ALLSN 250C20F | | | CABLE 704A34130163 | FRAYED NR 2 N2 CONTROL | 99 | 4/27/98 98ZZZX1683 |
| | CABLE FRAYED AND BEARING WORN OUT CAUSING BINDING OF N2 LINKAGE. SUBMITTER SUGGESTED INSTALLING A BETTER, MORE RELIABLE SYSTEM. | | | | | | | | |
| 2432 KY1R | | AEROSP SA365N1 | | | | BATTERY 99892R4495 | DEFECTIVE EMERG DC SYS | | 2/22/94 94ZZZX4579 |
| | BATTERY WILL NOT HOLD CHARGE, PUT A LOAD ON BATTERY, IT FAILED. | | | | | | | | |
| 2432 KY1R | | AEROSP SA365N1 | | | | BATTERY 99892R4495 | DEFECTIVE EMERG DC SYS | | 2/22/94 94ZZZX4580 |
| | BATTERY WILL NOT HOLD CHARGE, PUT A LOAD ON BATTERY, IT FAILED. | | | | | | | | |
| 6420 KY1R | | AEROSP SA365N1 | | | | SPIDER 365A33214200 | WORN T/R | | 2/23/94 94ZZZX4578 |
| | SPIDER BUSHINGS OUT OF LIMITS, 33MM. | | | | | | | | |
| 2913 | 911RX 10017 | AGUSTA A109K2 | | | | COUPLING 807712 | WORN NR 2 HYD PUMP | 512 | 6/30/94 94ZZZX4571 |
| | DURING 600-HOUR INSPECTION, DRIVE COUPLING IN NR 2 HYDRAULIC PUMP WAS FOUND WORN ON PUMP SIDE. A NEW DRIVE COUPLING SAME P/N WAS INSTALLED. | | | | | | | | |
| 3212 | 911RX 10017 | AGUSTA A109K2 | | | | SWITCH 1090760451 | OPEN FLOAT | 512 | 6/30/94 94ZZZX4573 |
| | DURING 600-HOUR INSPECTION, CHECK OUT OF FLOAT SWITCH PROVED IT WAS INOPERATIVE 'OPEN'. NEW SWITCH SAME P/N WAS ORDERED WHICH FIXED PROBLEM. | | | | | | | | |
| 6220 | 911RX 10017 | AGUSTA A109K2 | | | | DAMPER 1090101063 | WORN M/R | 512 | 6/30/94 94ZZZX4572 |
| **** | DURING 600-HOUR INSPECTION, DAMPER ROD END FOUND TO HAVE PLAY, NO PLAY ALLOWED. A REPLACEMENT DAMPER WAS INSTALLED. | | | | | | | | |
| 6420 | 911RX 10017 | AGUSTA A109K2 | | | | BUSHING 1090131193 | WORN T/R TRUNNION | 12 | 7/11/94 94ZZZX4570 |
| | TAIL ROTOR SLEEVE TRUNNION SLIPPAGE CAUSED UNUSUAL RATE OF WEAR ON TRUNNION BUSHINGS. REMOVED, REPAIRED AND REINSTALLED TRUNNION ASSY IAW AGUSTA FAX-1171 AND INSTALLED NEW BUSHINGS. TIME SINCE NEW TRUNNION INSTALLATION, 11.6 HOURS. | | | | | | | | |
| 2312 HEEA | 2272V 3621 | BELL 206B | | | | TRANSCIEVER 064105430 | MALFUNCTION COCKPIT | | 4/14/94 HEEA942171 |
| | SCRATCHY RECEPTION ON 123:00. DISPLAY GOING OUT. VERIFIED FAULTY DISPLAY; BUT NO RECEPTION PROBLEM. REPLACED DS901 DISPLAY AND REPAIRED. BENCH CHECK GOOD. | | | | | | | | |

**** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 2312 HEEA | 6251X 51552 | BELL 206L3 | | | KX155 | RECEIVER 069102435 | FAILED NAV/COMM | | 4/22/98 HEEA0014013 |
| NAV COMM RECEIVER NO DISPLAY. | | | | | | | | | |
| 2312 HEEA | 6160Z 51610 | BELL 206L3 | | | | TRANSCIEVER 064105430 | DEFECTIVE COCKPIT | | 4/29/94 HEEA942170 |
| HIGH NOISE WHEN KEYING MIKE FOR FIRST 15 MINUTES OF OPERATION, THEN NORMAL. FOUND SOME DISPLAY SEGMENTS INOPERATIVE. REPLACED DISPLAY DS901. REPAIRED AND ADJUSTED SQUELCH AND SIDE TONE. BENCH CHECK GOOD. | | | | | | | | | |
| 2330 HEEA | 206LS 51070 | BELL 206L3 | | | | AUDIO PANEL 066105552 | FAILED COCKPIT | | 4/22/98 HEEA0014017 |
| PA CHANNEL INOPERATIVE AND DUAL SINGLE SWITCH LOOSE. | | | | | | | | | |
| 2430 HEEA | 4282Z 51499 | BELL 206L3 | | | | RELAY A1077 | STUCK DC SYS | | 4/29/98 HEEA0014060 |
| STUCK CLOSED AFTER INSTALLATION. RESET RELAY AND TRIED AGAIN, UNIT THEN STARTED SMOKING. REPLACED WITH SERVICEABLE RELAY SYSTEM. | | | | | | | | | |
| 2432 HEEA | 3181Y 3772 | BELL 206B | | | 30135001 | CELL 17SP100 | DEFECTIVE NR 3 | | 1/26/94 HEEA942131 |
| BATTERY INSPECTED BY ACCESSORY SHOP AND FOUND CELL #3 WOULD NOT ACCEPT A CHARGE. CELL REPLACED. | | | | | | | | | |
| 2432 HEEA | 2268V 3605 | BELL 206B3 | | | 30135001 | CELL 17SP100 | DEFECTIVE NR 1 | | 4/1/94 HEEA942130 |
| BATTERY INSPECTED WHEN RECEIVED AND FOUND CELL #1 WOULD NOT HOLD UP ON CAPACITY TEST. CELL REPLACED. | | | | | | | | | |
| 2432 HEEA | 5014Y 45219 | BELL 206L1 | | | 3055401C | CELL 17SP100 | DEFECTIVE NR 11 | | 4/4/94 HEEA942132 |
| BATTERY INSPECTED BY ACCESSORY SHOP AND FOUND CELL #11 WOULD NOT HOLD UP ON CAPACITY TEST. CELL REPLACED. | | | | | | | | | |
| 2432 HEEA | 206LS 51070 | BELL 206L3 | | | 3055401C | CELL 17SP100 | DEFECTIVE NR 9 | | 2/19/94 HEEA942133 |
| BATTERY INSPECTED BY ACCESSORY SHOP AND FOUND CELL #9 WOULD NOT ACCEPT A CHARGE. CELL REPLACED. | | | | | | | | | |
| 2432 HEEA | 4180F 51469 | BELL 206L3 | | | 3055401C | CELL 17SP100 | WEAK NR 5 | | 3/22/94 HEEA942134 |
| BATTERY WEAK. INSPECTED BY ACCESSORY SHOP AND FOUND CELL #5 WOULD NOT HOLD UP ON CAPACITY TEST. CELL REPLACED. | | | | | | | | | |
| 2435 HEEA | 50182 45242 | BELL 206L1 | | | 200SGL132Q | START/GEN 200SGL1008 | CORRODED END BELL | 475 | 4/22/98 HEEA0014015 |
| EXCESSIVE CORROSION FOUND ON END BELL DURING IT'S FIRST 500 HOUR INSPECTION WHICH CORRODED THROUGH ONE OF THE SCREW HOLES. NOTE: THIS SEEMS TO HAVE HAPPENED DUE TO THE TYPE FINISH THESE END BELL ASSEMBLIES HAVE. THEY DON'T HAVE ANY PAINT OR PRIMER. | | | | | | | | | |
| 2562 HEEA | 513EH 45421 | BELL 206L1 | | | NARCO | ELT ELT910 | FAILED COCKPIT | | 5/1/98 HEEA0014111 |
| ELT UNIT FOUND IN ON POSITION FOR UNKNOWN TIME. | | | | | | | | | |
| 2562 HEEA | 6610E 51424 | BELL 206L3 | | | NARCO | ELT ELT10 | DEFECTIVE COCKPIT | | 4/29/98 HEEA0014086 |
| ELT RESET BUTTON WILL NOT SPRING BACK. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 2822 | 206BY | BELL | | | | PUMP CARTRIDGE | FAILED | | 4/21/98 |
| LS1R | 2871 | 206B3 | | | | 2C271 | BOOST PUMP | | 98ZZZX1680 |
| FORWARD BOOST PUMP INOPERABLE. REMOVED AND REPLACED BOOST PUMP. AIRCRAFT RETURNED TO SERVICE. CONTROL NR 98-4-10. | | | | | | | | | |
| 2842 | 7074W | BELL | | | | TRANSDUCER | DEFECTIVE | 445 | 1/26/94 |
| HEEA | 52033 | 206L | | | | BSE20630G | FUEL SYS | | HEEA942139 |
| TRANSDUCER OUTPUT DOES NOT INCREASE ABOVE 6.3V. REPORTED ERRATIC READINGS ON AIRCRAFT. | | | | | | | | | |
| 3210 | | BELL | | | | CROSSTUBE | DEFECTIVE | | 5/19/94 |
| HEEA | | 206L1 | | | | 206053203103 | S/N PLACARD | | HEEA942207 |
| RIVET INSTALLED IN MIDDLE OF SERIAL NUMBER. UNABLE TO READ S/N. | | | | | | | | | |
| 3210 | | BELL | | | | CROSSTUBE | DEFECTIVE | | 5/12/94 |
| HEEA | | 206L1 | | | | 206053203101 | S/N PLACARD | | HEEA942167 |
| RIVET INSTALLED IN MIDDLE OF S/N. UNABLE TO READ. | | | | | | | | | |
| 3210 | | BELL | | | | CROSSTUBE | DEFECTIVE | | 5/11/94 |
| HEEA | | 206L1 | | | | 206053203101 | S/N PLACARD | | HEEA942160 |
| RIVET INSTALLED IN MIDDLE OF S/N. UNABLE TO READ. | | | | | | | | | |
| 3213 | 22751 | BELL | | | | FITTING ASSY | WORN | | 4/30/98 |
| HEEA | 3627 | 206B3 | | | | 206030104001 | CROSSTUBE | | HEEA0014100 |
| FITTING ASSY WORN AND GOUGED. SCRAPPED FITTINGS AND REPLACED WITH SERVICEABLE FITTINGS. | | | | | | | | | |
| 3421 | 11027 | BELL | | | | ROTOR ASSY | DEFECTIVE | | 5/1/98 |
| HEEA | 45411 | 206L1 | | | | 2360041905 | INDICATOR | | HEEA0014110 |
| ROTOR ASSY BEARINGS ARE BAD. | | | | | | | | | |
| 3422 | 4180F | BELL | | | | GYRO | DEFECTIVE | | 2/26/94 |
| HEEA | 51469 | 206L3 | | | | 102005403 | COCKPIT | | HEEA942218 |
| HORIZ GYRO SLOW TO ERECT, REPORTED PRECESSING. | | | | | | | | | |
| 3423 | 22425 | BELL | | | | COMPASS | LEAKING | | 4/22/98 |
| HEEA | 45743 | 206L1 | | | | C2300DL4B | COCKPIT | | HEEA0014029 |
| COMPASS LEAKING. | | | | | | | | | |
| 3444 | 8594X | BELL | | | | INDICATOR | STICKS | | 4/25/94 |
| HEEA | 51531 | 206L3 | | | KI250 | 066305401 | COCKPIT | | HEEA942180 |
| NEEDLE STICKS AT 500 FEET. LOOSE WASHERS INSIDE OF UNIT. TROUBLESHOT AND REMOVED LOOSE WASHERS FROM INSIDE OF UNIT AND REPLACED BEZEL ASSEMBLY. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 | 3181J | BELL | | | | TRANSPONDER | KNOB BROKEN | | 5/14/94 |
| HEEA | 3771 | 206B | | | KT76 | 066106200 | COCKPIT | | HEEA942215 |
| BROKEN KNOB. REPLACED KNOB AND ALSO REPLACED DETERIORATED RESISTOR R477. REPAIRED PROBLEM. | | | | | | | | | |
| 3452 | 3181Y | BELL | | | | TRANSPONDER | FAILED | | 4/29/98 |
| HEEA | 3772 | 206B3 | | | KT76 | 066106200 | COCKPIT | | HEEA0014057 |
| NUMBERS ON THE DIAL, DO NOT MATCH DECODER NUMBER TRANSMITTING. FOUND UNIT SHOWING FALSE PULSES. CLEANED WAFER SWITCHES. REPAIRED. ADJUSTED PULSE WIDTH AND FREQUENCY TO SPECS. BENCH CHECK GOOD. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 3452 | 2759U | BELL | | | | TRANSPONDER | INOP | | 4/27/94 |
| HEEA | 45267 | 206L1 | | | KT76 | 066106200 | COCKPIT | | HEEA942176 |
| ATC NOT RECEIVING. TROUBLESHOT AND REPLACED V101 OSCILLATOR, R477 RESISTOR AND FACEPLATE. REPAIRED. PERFORMED MOD 6 BY INSTALLING Q415 SPACER. REPAIRED. | | | | | | | | | |
| 3452 | 2250U | BELL | | | | TRANSPONDER | INTERMITTENT | | 3/21/94 |
| HEEA | 45754 | 206L1 | | | KT76 | 066106200 | COCKPIT | | HEEA942175 |
| INTERMITTENT OPERATION. TROUBLESHOT AND REPLACED CAVITY OSCILLATOR V101, DIODE CR202, CAPACITORS, C202 AND C204, TRANSISTOR Q201, FUSE F401, MIXER DIODE AND COAX FOR MIXER DIODE AND DETERIORATED RESISTOR R477. REPAIRED PROBLEM. | | | | | | | | | |
| 3452 | 21497 | BELL | | | | TRANSPONDER | FAILED | | 4/29/98 |
| HEEA | 51518 | 206L3 | | | KT76 | 066106200 | COCKPIT | | HEEA0014053 |
| MODE "C" REPORTED INOPERATIVE BY ATC. PERFORMED PRELIMINARY INSPECTION. FOUND PULSE WIDTH TO BE OUT OF SPECS AND REPLY LIGHT TO CONSTANTLY BLINK. | | | | | | | | | |
| 3457 | 9907K | BELL | | | | GPS | FAILED | 1422 | 4/16/98 |
| LS1R | 2040 | 206B | | | GPS150 | 0110005400 | COCKPIT | | 98ZZZX1685 |
| GPS WILL NOT PICK UP SATELLITE UNIT SENT TO MANUFACTURER FOR REPAIR. CONTROL NR 984-9. | | | | | | | | | |
| 3457 | | BELL | | | | GPS | DEFECTIVE | | 4/29/98 |
| HEEA | | 206L1 | | | GPS 150 | 0110005400 | COCKPIT | | HEEA0014055 |
| GPS NO LONGER NEEDED ON AIRCRAFT. BENCH CHECK REQUIRED. PERFORMED PRELIMINARY INSPECTION. FOUND DIRECT TO BUTTON UNREADABLE. | | | | | | | | | |
| 3457 | 22425 | BELL | | | | GPS | FAILED | | 4/29/98 |
| HEEA | 45743 | 206L1 | | | GPS 150 | 0110005400 | COCKPIT | | HEEA0014056 |
| GPS TAKES 30 MINUTES TO COME ON. PERFORMED PRELIMINARY INSPECTION. FOUND UNIT TO HAVE UNREADABLE ENTRY AND CRSR BUTTONS. | | | | | | | | | |
| 5260 | 6251X | BELL | | | | STEP | CORRODED | | 4/29/98 |
| HEEA | 51552 | 206L3 | | | | 206310110 | ENTRY | | HEEA0014052 |
| STEP CORRODED BEYOND LIMITS. | | | | | | | | | |
| 5313 | | BELL | | | | LONGERON | MIS MFG | | 4/30/98 |
| HEEA | | 206L1 | | | | 206031314123S | FUSELAGE | | HEEA0014090 |
| TOOLING HOLES NOT IN ALIGNMENT WITH ORIGINAL, CAUSING BOW ALONG CENTER OF LONGERON. | | | | | | | | | |
| 5320 | | BELL | | | | INTERCOSTAL | DAMAGED | | 5/1/98 |
| HEEA | | 206L1 | | | | 206033410040S | FUSELAGE | | HEEA0014105 |
| MECHANICAL DAMAGE ON LOWER FORWARD BEND RADIUS. | | | | | | | | | |
| 5530 | 8592X | BELL | | | | FIN ASSY | MIS MARKED | | 4/29/98 |
| HEEA | 51508 | 206L3 | | | | 206023126103 | VERT FIN | | HEEA0014046 |
| FIN ASSY RECEIVED WITH INCORRECT PART NUMBER. FOUND PART TO BE A R/H FIN WITH A LEFT HAND PART NUMBER ON IT. LOCATION OF INSERTS ARE ALL FOR R/H SIDE. (SHOULD HAVE BEEN P/N 206-023-126-102) | | | | | | | | | |
| 6220 | 2775A | BELL | | | | WASHER | DETERIORATED | 1196 | 5/18/94 |
| HEEA | 45297 | 206L1 | | | 206011100159 | 206010110105 | M/R THRUST | | HEEA942204 |
| EXCESSIVE WEAR-MATERIAL DETERIORATING. REPLACED THRUST WASHERS-LOWER TORQUE ON ADJUSTING SCREWS (PRELOAD TOO HIGH). | | | | | | | | | |
| 6220 | 1076Y | BELL | | | | WASHER | DETERIORATED | 1150 | 5/23/94 |
| HEEA | 45380 | 206L1 | | | 206011100159 | 206010110105 | M/R THRUST | | HEEA942228 |
| EXCESSIVE WEAR-MATERIAL DETERIORATING. REPLACED THRUST WASHERS. LOWER TORQUE ON ADJUSTING SCREWS-PRELOAD TOO HIGH. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|-----------------------------|-------------------------------|-----------|----------------------------|
| 6310 HEEA | 22718 3618 | BELL 206B | | | | DR.SHAFT 206040015103 | OVERTEMP GR BOX COUPLING | 9888 | 3/9/94 HEEA942165 |
| INDICATION OF OVERTEMP (DISC SIDE ONLY TWO EACH YELLOW TEMP-PLATES) REPAIRED AND RETURNED TO SERVICE. | | | | | | | | | |
| 6310 HEEA | 22718 3618 | BELL 206B | | | | DR.SHAFT 206040015103 | OVERTEMP GR BOX COUPLING | 6261 | 3/7/94 HEEA942164 |
| INDICATION OF OVERTEMP (DISC SIDE ONLY TWO EACH YELLOW TEMP-PLATES) REPAIRED AND RETURNED TO SERVICE. | | | | | | | | | |
| 6310 HEEA | 22718 3618 | BELL 206B | | | | DR.SHAFT 206040015103 | OVERTEMP GR BOX COUPLING | 7339 | 4/12/94 HEEA942166 |
| INDICATION OF OVERTEMP (DISC SIDE TWO EACH YELLOW TEMP-PLATES). BOOT TORN. (OPPOSITE SIDE TWO EACH YELLOW AND RED TEMP-PLATES) REPAIRED AND RETURNED TO SERVICE. | | | | | | | | | |
| 6310 HEEA | 2268X 3607 | BELL 206B3 | | | | DR.SHAFT 206040015103 | OVER TEMP GR BOX COUPLING | 8295 | 4/22/94 HEEA942161 |
| INDICATION OF OVERTEMP (DISC SIDE 2 EACH YELLOW TEMP-PLATES)(OPPOSITE SIDE 2 EACH YELLOW AND RED TEMP-PLATES). BOOT OPEN. REPAIRED AND RETURNED TO SERVICE. | | | | | | | | | |
| 6310 HEEA | 2268X 3607 | BELL 206B3 | | | | DR.SHAFT 206040015103 | OVERTEMP GR BOX COUPLING | 7918 | 5/11/94 HEEA942163 |
| INDICATION OF OVERTEMP (OPPOSITE SIDE 2 EACH YELLOW TEMP-PLATES). REPAIRED AND RETURNED TO SERVICE. | | | | | | | | | |
| 6310 HEEA | 2268X 3607 | BELL 206B3 | | | | DR.SHAFT 206040015103 | OVERTEMP GR BOX COUPLING | 8351 | 5/10/94 HEEA942162 |
| INDICATION OF OVERTEMP (DISC SIDE 2 EACH YELLOW TEMP-PLATES)(OPPOSITE SIDE 2 EACH YELLOW TEMP-PLATES). REPAIRED AND RETURNED TO SERVICE. | | | | | | | | | |
| 6310 HEEA | 62127 52023 | BELL 206L | | | | SLEEVE SEAL 214040814105 | LEAKING FREEWHEEL | 296 | 4/2/94 HEEA942150 |
| FREEWHEEL UNIT AFT CAP SEAL LEAKING. O RING (M83248-1-021), O RING (M83248-1-140), SEAL (214-040-841-101), ADAPTER (406-040-550-101), SLEEVE (214-040-814-105) ALSO REPLACED. | | | | | | | | | |
| 6320 HEEA | 7077B 52037 | BELL 206L | | | 206040004115 | PUMP SEAL 406340100101 | LEAKING XMSN OIL | 1127 | 5/12/94 HEEA942236 |
| TRANSMISSION OIL PUMP OUTPUT SEAL LEAKING. | | | | | | | | | |
| 6320 HEEA | 2770Y 45291 | BELL 206L1 | | | | INDICATOR 90093013 | FLUCTUATES XMSN TEMP/PRESS | | 4/29/98 HEEA0014074 |
| OIL PRESS NEEDLE FLUCTUATES. | | | | | | | | | |
| 6410 HEEA | 5007N 45184 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 393 | 5/11/94 HEEA942198 |
| BLADE BEARING CRACKED. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 5014Y 45219 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 597 | 4/21/94 HEEA942190 |
| BLADE BEARING CRACKED. BLADE S/N CS4772 & CS43. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 5014Y 45219 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 993 | 4/21/94 HEEA942191 |
| BLADE BEARING CRACKED. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|---------------------------|-------------------------|-----------|----------------------------|
| 6410 HEEA | 50182 45242 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 138 | 5/4/94 HEEA942195 |
| BLADE BEARING CRACKED. BLADE S/N CS2967 & CS29. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 5745N 45489 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 276 | 5/2/94 HEEA942193 |
| BLADE BEARING CRACKED. BLADE S/N CS2802 & CS27. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 5745N 45489 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 485 | 5/2/94 HEEA942194 |
| BLADE BEARING CRACKED. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 5745S 45491 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 833 | 5/12/94 HEEA942197 |
| BLADE CRACKED. BLADE S/N CS3971 & CS39. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 3892R 45594 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 257 | 4/20/94 HEEA942192 |
| BLADE BEARING CRACKED. BLADE S/N CS6038 & CS60. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 3905B 45598 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 514 | 4/18/94 HEEA942189 |
| BLADE BEARING CRACKED. BLADE S/N CS3712 & CS37. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 3905B 45598 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 169 | 5/13/94 HEEA942200 |
| BLADE BEARING CRACKED. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. PARTS AND LABOR WILL BE INVOICED...PM#6202. | | | | | | | | | |
| 6410 HEEA | 3905B 45598 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 68 | 5/13/94 HEEA942199 |
| BLADE BEARING CRACKED. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 22425 45743 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 630 | 5/13/94 HEEA942201 |
| BLADE BEARING CRACKED. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6410 HEEA | 2245Y 45751 | BELL 206L1 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R BLADE | 23 | 4/14/94 HEEA942188 |
| BLADE BEARING CRACKED. BLADE S/N CS2950 & CS28. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. PARTS AND LABOR WILL BE INVOICED...PM#6202. | | | | | | | | | |
| 6410 HEEA | 205FC 51130 | BELL 206L3 | | | 206016201127 | BEARING 206010765001 | CRACKED T/R | 270 | 5/4/94 HEEA942196 |
| BLADE BEARING CRACKED. BLADE S/N CS6042 & CS60. ALSO REPLACED SLEEVE P/N 206-010-733-003. SEE MMIR'S 2188 THROUGH 2201. PARTS SCRAPPED LOCALLY. | | | | | | | | | |
| 6520 HEEA | 62127 52023 | BELL 206L | | | | INDICATOR 204040508011 | LOOSE T/R GR BOX OIL | 885 | 5/10/94 HEEA942159 |
| TAIL ROTOR GEARBOX OIL LEVEL INDICATOR SPINS FREELY DUE TO NO LOCK TAB. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------------|--------------------------|-----------|----------------------------|
| 6520 HEEA | 62127 52023 | BELL 206L | | | | SEAL 206340103101 | LEAKING T/R GR BOX | 524 | 5/10/94 HEEA942158 |
| T/R GEARBOX INPUT SEAL LEAKING. ALSO REPLACED ORING (M83248-1-213), SLEEVE (206-040-420-101), WASHER (NAS1443-7P), ORING (MS29561-230). | | | | | | | | | |
| 6520 HEEA | 7074W 52033 | BELL 206L | | | | SEAL 206340103101 | LEAKING T/R GR BOX | 262 | 4/10/94 HEEA942156 |
| T/R GEARBOX INPUT SEAL LEAKING. ALSO REPLACED ORING (M83248-1-213), WASHER (NAS1443-7P), SPACER (206-040-420-101). | | | | | | | | | |
| 6520 HEEA | 7077B 52037 | BELL 206L | | | | SEAL 206340103101 | LEAKING T/R GR BOX | 221 | 4/5/94 HEEA942157 |
| T/R GEARBOX INPUT SEAL LEAKING. ALSO REPLACED ORING (M83248-1-213), SLEEVE (206-040-420-101), WASHER (NAS1443-7P). | | | | | | | | | |
| 6520 HEEA | | BELL 206L1 | | | | PINION 206040440103 | DEFECTIVE T/R GR BOX | | 4/21/98 HEEA0013993 |
| SILVER COATING FLAKING FROM GEAR TOOTH. | | | | | | | | | |
| 6710 HEEA | 2777D 45299 | BELL 206L1 | | | | TUBE ASSY 206001342001 | CORRODED CYCLIC | | 4/17/94 HEEA942147 |
| UPON INSPECTION OF TUBE ASSY, CORROSION PITS WERE FOUND. SOME PITS WERE .008 AND .009 DEEP. INSTALLED NEW TUBE ASSEMBLY. | | | | | | | | | |
| 6710 HEEA | 49EA 51507 | BELL 206L3 | | | | ACTUATOR 206062721109 | DEFECTIVE M/R CONTROL | | 5/1/98 HEEA0014104 |
| ACTUATOR WILL NOT ADJUST. | | | | | | | | | |
| 6710 HEEA | 6161A 51611 | BELL 206L3 | | | | ACTUATOR 206062721109 | FAILED M/R | | 4/22/98 HEEA0014033 |
| ACTUATOR INOPERATIVE. | | | | | | | | | |
| 6720 HEEA | 3905B 45598 | BELL 206L1 | | | | BELLCRANK ASSY 206001763001 | CHAFED ANTI TORQUE | | 4/29/98 HEEA0014049 |
| BELLCRANK CHAFFED AT ROD END ATTACH AREA. REPLACED BELLCRANK WITH SERVICEABLE PART. | | | | | | | | | |
| 7170 RW8A | 828BA 3426 | BELL 206B | ALLSN 250C20J | | | DRAIN VALVE 6854255 | CRACKED BURNER | | 11/19/97 97ZZZX5131 |
| DURING 100-HOUR INSPECTION, BURNER DRAIN VALVE WAS FOUND CRACKED UNDER O-RING BOSS AREA. | | | | | | | | | |
| 7170 HEEA | 3905B 45598 | BELL 206L1 | | | | HOSE ASSY 70031A202000 | CLOGGED EXH DRAIN | | 4/29/98 HEEA0014050 |
| CLOGGED EXH COLLECTOR DRAIN HOSE. REPLACED WITH NEW HOSE. | | | | | | | | | |
| 7230 HEEA | 50046 45173 | BELL 206L1 | ALLSN 250C28B | | 23033191 | CARBON SEAL 23004513 | WORN ENG COMP | 358 | 4/21/98 HEEA0014005 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL HOUSING TANGS. INSTALLED A NEW SEAL. | | | | | | | | | |
| 7230 HEEA | 2764F 45279 | BELL 206L1 | ALLSN 250C28B | | 23033191 | CARBON SEAL 23004513 | WORN ENG COMP | 368 | 4/21/98 HEEA0014008 |
| ENGINE REMOVED DUE TO COMPRESSOR HIGH TIME IMPELLER. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL TANGS AND TANG SLOTS. INSTALLED A NEW SEAL. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 7230 | 2770Y | BELL | ALLSN | | | GEAR | WORN | 630 | 4/21/98 |
| HEEA | 45291 | 206L1 | 250C28B | | 23033191 | 23056634 | SPUR ADAPTER | | HEEA0014009 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. INSPECTION OF COMPRESSOR PARTS REVEALED: STEP WEAR BEYOND SERVICEABLE LIMITS ON SPUR GEARSHAFT AFT SPLINES (FAILED NO-GO GAUGE) INSTALLED A NEW SPUR GEAR. | | | | | | | | | |
| 7230 | 2772A | BELL | ALLSN | | | CARBON SEAL | WORN | 352 | 4/21/98 |
| HEEA | 45311 | 206L1 | 250C28B | | 23033191 | 23004513 | ENG COMP | | HEEA0014006 |
| ENGINE REMOVED DUE TO CRACKED SCROLL. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL TANGS AND TANG SLOTS. INSTALLED A NEW SEAL. | | | | | | | | | |
| 7230 | 27766 | BELL | ALLSN | | | GEARSHAFT | STEPWEAR | 224 | 5/1/94 |
| HEEA | 45312 | 206L1 | 250C28B | | 23033191 | 23008090 | SPUR ADAPTER | | HEEA942141 |
| ENGINE REMOVED DUE TO LOW POWER. UPON INSPECTION OF COMPRESSOR PARTS NOTED STEP WEAR BEYOND LIMITS ON SPUR ADAPTER GEARSHAFT FORWARD AND AFT SPLINES. INSTALLED NEW SPUR ADAPTER GEARSHAFT. | | | | | | | | | |
| 7230 | 8590X | BELL | ALLSN | | | GEARSHAFT | STEP WEAR | 817 | 4/28/94 |
| HEEA | 51494 | 206L3 | 250C30P | | 23033193 | 23008090 | SPUR ADAPTER | | HEEA942140 |
| ENGINE REMOVED DUE TO HIGH CYCLED WHEELS. UPON INSPECTION OF COMPRESSOR PARTS NOTED STEP WEAR BEYOND LIMITS ON SPUR ADAPTER GEARSHAFT AFT SPLINES. INSTALLED NEW SPUR ADAPTER GEARSHAFT. | | | | | | | | | |
| 7230 | 8592X | BELL | ALLSN | | | CARBON SEAL | WORN | 928 | 4/21/98 |
| HEEA | 51508 | 206L3 | 250C30P | | 23051643 | 23004513 | ENG COMP | | HEEA0014007 |
| ENGINE REMOVED DUE TO CRACKED SCROLL. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL TANGS AND TANG SLOTS. INSTALLED A NEW SEAL. | | | | | | | | | |
| 7250 | 49573 | BELL | ALLSN | | | BEARING | FAILED | 921 | 3/30/98 |
| | 1665 | 206B | 250C20B | | | A6871505 | TURBINE NR 5 | | 98ZZZX1682 |
| AFTER A NORMAL FLIGHT (EXTERNAL LOAD) AND SHUT-DOWN, THE PILOT REPORTED AN ABNORMAL NOISE WHILE TURNING ROTOR BACKWARDS TO TIE-DOWN POSITION. UPON REMOVAL OF THE TURBINE MODULE, THE FORWARD HALF OF THE NR 5 BEARING INNER CAGE FELL OUT. (THIS IS A 1-PIECE UNIT, NOT 2) THIS BEARING IS THE SUBJECT OF AD 96-19-01. THERE HAD BEEN NO PREVIOUS SIGNS OF DISTRESS, I.E., CHIP LIGHTS, ETC. ENGINE OIL FILTER REMAINS CLEAN AT REMOVAL OF TURBINE. SUSPECT THAT BEARING FAILED AFTER SHUT DOWN IN THAT AT OPERATIONAL SPEED NEAR 60K RPM, MAJOR TURBINE DAMAGE WOULD HAVE OCCURRED IN MILLI-SECONDS. REPLACED WITH OEM BEARING. | | | | | | | | | |
| 7250 | 104PH | BELL | ALLSN | | | COUPLING | WORN | 697 | 4/21/98 |
| HEEA | 3622 | 206B3 | 250C20B | | 6898735 | 6898977 | ENGINE N1 | | HEEA0014002 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. UPON INSPECTION OF TURBINE PARTS NOTED: N1 COUPLING FAILED NO-GO GAUGE. INSTALLED A NEW N1 COUPLING. | | | | | | | | | |
| 7250 | 27766 | BELL | ALLSN | | | COUPLING | STEPWEAR | 320 | 5/1/94 |
| HEEA | 45312 | 206L1 | 250C28B | | 23033185 | 23032345 | N1 | | HEEA942142 |
| ENGINE REMOVED DUE TO LOW POWER. UPON INSPECTION OF TURBINE PARTS NOTED STEP WEAR BEYOND LIMITS ON N1 COUPLING SPLINES. INSTALLED NEW N1 COUPLING. | | | | | | | | | |
| 7250 | 5737T | BELL | ALLSN | | | WHEEL | SULFIDATION | 1489 | 4/25/94 |
| HEEA | 45454 | 206L1 | 250C28B | | 23031899 | 6895801 | 1ST STSGE | | HEEA942143 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. UPON INSPECTION OF TURBINE PARTS NOTED SULFIDATION ON 1ST STAGE WHEEL BLADES. | | | | | | | | | |
| 7250 | 2250U | BELL | ALLSN | | | WHEEL | SULFIDATION | 820 | 5/18/94 |
| HEEA | 45754 | 206L1 | 250C28B | | 23033185 | 6895801 | 1ST STAGE | | HEEA942240 |
| ENGINE WAS REMOVED DUE TO WHINING AT ALL POWER SETTINGS. UPON INSPECTION OF TURBINE PARTS NOTED SULFICATION ON 1ST STAGE WHEEL BLADES. PART SCRAPPED. | | | | | | | | | |
| 7261 | 2125M | BELL | ALLSN | | | ELEMENT | FAILED | | 5/23/94 |
| HEEA | 45649 | 206L1 | 250C30 | | | 03808808 | ENG OIL | | HEEA942237 |
| BYPASS BUTTON POPPED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|----------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 7261 | 108W | BELL | ALLSN | | | TUBE | CHAFED | 2100 | 3/12/98 |
| | 52034 | 206L4 | 250C30P | | | 23058110A | SCAVENGE OIL | | 98ZZZX1701 |
| ***** | WHILE REMOVING RENTAL ENGINE AND TRANSFERRING HARD LINE P/N 23058110-A FROM RENTAL ENGINE TO ORIGINAL ENGINE, SEVERE CHAFING NOTED UNDER ADEL CLAMP. THIS IS SCAVENGE OIL LINE FROM BOTTOM OF COMPRESSOR TO THE N1 SIDE OF GEARBOX. ABRASIVE DUST AND AIRBORNE DIRT CREEPS IN BETWEEN HARD RUBBER ADEL CLAMP AND OIL LINE AND CHAFES OR WEARS OIL LINE TO THE POINT OF FAILURE. THE NEED EXISTS FOR CLAMPING DEVICES THAT WOULD ELIMINATE THIS CHAFING CONDITION. IN THE MEANTIME, INSPECTION UNDER CLAMPED AREAS IS PRUDENT TO AVOID AN UNSUSPECTED FAILURE. | | | | | | | | |
| 7712 | 20898 | BELL | | | | TORQUEMETER | FAILED | | 4/29/98 |
| HEEA | 45721 | 206L1 | | | | 206075739103 | COCKPIT | | HEEA0014077 |
| | TORQUEMETER NEEDLE DOESN'T RETURN TO ZERO. | | | | | | | | |
| 3455 | 5736J | BELL | | | | RECEIVER | FAILED | | 4/29/98 |
| HEEA | 31140 | 212 | | | | 066104701 | COCKPIT ADF | | HEEA0014058 |
| | ADF RECEIVER WEAK RECEIVE AND NOT POINTING CORRECTLY IN ADF MODE. INSPECTED AND FOUND ADF MODE SIGNAL WEAK AND NOT POINTING. TRIED ALIGNING RECEIVER. NO HELP. | | | | | | | | |
| 3457 | 2FOR | BELL | | | | GPS | DEFECTIVE | | 4/23/94 |
| HEEA | 30888 | 212 | | | SKYNAV5000 | 0845000000 | COCKPIT | | HEEA942185 |
| | INTERMITTENTLY DISPLAYS CHARACTERS. | | | | | | | | |
| 6220 | 1079U | BELL | | | | BEARING | WORN | 1176 | 5/9/94 |
| HEEA | 31122 | 212 | | | | 212011112103 | M/R | | HEEA942149 |
| | ROLLER BEARING TEFLON COATING WORN OFF. | | | | | | | | |
| 6220 | 1079U | BELL | | | | BEARING | WORN | 1176 | 5/9/94 |
| HEEA | 31122 | 212 | | | | 212011111103 | M/R | | HEEA942148 |
| | ROLLER BEARING TEFLON COATING WORN OFF. | | | | | | | | |
| 2210 | 59805 | BELL | | | | INDICATOR | FAILED | | 4/29/98 |
| HEEA | 28141 | 214ST | | | | 214175259103 | ELEV POSITION | | HEEA0014085 |
| | ELEV POSITION INDICATOR INOPERATIVE. | | | | | | | | |
| 2312 | 59806 | BELL | | | | CONTROL | FAILED | | 4/29/98 |
| HEEA | 28140 | 214ST | | | | 071121540 | COMM SYS | | HEEA0014088 |
| | 25K PULL TUNING KNOB COMES OUT OF CONTROL HEAD WHEN PULLED. PERFORMED PRELIMINARY INSPECTION. FOUND LOOSE LOCK RING IN UNIT. REINSTALLED LOCK RING, REPAIRED. TESTED UNIT. BENCH CHECK GOOD. | | | | | | | | |
| 2435 | 8045T | BELL | | | | STARTER | FAILED | 762 | 4/27/98 |
| HEEA | 28101 | 214ST | | | | 214060056103 | ENGINE | | HEEA0014034 |
| | DURING 250 HOUR INSPECTION FOUND CLUTCH FAILED TORQUE SLIPPAGE TEST WAS AT 250 IN. LBS. AND END PLAY WAS AT .014 LIMITS ARE .004-.010. | | | | | | | | |
| 2435 | 6957Y | BELL | | | | STARTER | FAILED | | 4/22/98 |
| HEEA | 28139 | 214ST | | | | 214060056103 | START/GEN | | HEEA0014028 |
| | STARTER KICKS OFF EARLY ON START UP. | | | | | | | | |
| 2435 | 59806 | BELL | | | | STARTER | FAILED | 1305 | 4/20/98 |
| HEEA | 28140 | 214ST | | | | 214060056103 | ENGINE | | HEEA0013990 |
| | STARTER WILL NOT DISENGAGE WHEN APPROPRIATE NG% IS ACHIEVED. MUST BE MANUALLY DISENGAGED. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|------------------------|-----------|----------------------------|
| 2435 HEEA | 59806 28140 | BELL 214ST | | | | STARTER 2CM272B1 | MALFUNCTION ENGINE | | 4/28/98 HEEA0014037 |
| DRAWS HIGH VOLTAGE DURING START UP. | | | | | | | | | |
| 2435 HEEA | 59806 28140 | BELL 214ST | | | | STARTER 214060056103 | FAILED ENGINE | 75 | 4/27/98 HEEA0014035 |
| KICKS OUT DURING START AND HIGH VOLTAGE DRAW. | | | | | | | | | |
| 3421 HEEA | 59806 28140 | BELL 214ST | | | | GYRO 258719343 | FAILED COCKPIT | | 4/29/98 HEEA0014072 |
| GYRO WILL NOT BECOME VALID. | | | | | | | | | |
| 6220 HEEA | 8045T 28101 | BELL 214ST | | | 214010100207 | SPINDLE 214010103115 | CRACKED M/R | 2945 | 4/29/98 HEEA0014089 |
| EAR CRACKED IN MOUNT AREA APPROX. 2 INCHES ON BOTH SIDES, ON LOWER SIDE OF TRAILING EDGE OF WHITE BLADE. SCRAPPED PART. | | | | | | | | | |
| 6220 HEER | 8045T 28101 | BELL 214ST | | | 214010100207 | SPINDLE 214010103115 | CRACKED M/R HUB | | 4/27/98 98ZZZX1700 |
| ***** THE MAIN ROTOR SPINDLE WAS CRACKED AT THE TRAILING EDGE TANGS. BOTH LOWER AND UPPER TANGS WERE CRACKED. THE CRACK WAS DETECTED DURING A DAILY VISUAL INSPECTION BY A COMPANY TECHNICIAN. SUBMITTER STATED FAILURE OF THIS SPINDLE WOULD HAVE CERTAINLY LED TO A CATASTROPHIC ACCIDENT. | | | | | | | | | |
| 6230 HEEA | 8045T 28101 | BELL 214ST | | | | SWASHPLATE 214010500105 | LOOSE M/R | 2911 | 4/20/98 HEEA0013984 |
| SWASHPLATE LOWER HUB NUT FOUND UNDER TORQUE. | | | | | | | | | |
| 6510 HEEA | 8045T 28101 | BELL 214ST | | | | SHAFT ASSY 214040622005 | CORRODED T/R | | 4/22/98 HEEA0014021 |
| EXCESSIVE CORROSION. SCRAPPED LOCALLY. | | | | | | | | | |
| 6510 HEEA | 8045T 28101 | BELL 214ST | | | | SHAFT ASSY 214040622005 | CORRODED T/R | | 4/22/98 HEEA0014020 |
| EXCESSIVE CORROSION. SCRAPPED LOCALLY. | | | | | | | | | |
| 6510 HEEA | 8045T 28101 | BELL 214ST | | | | SHAFT ASSY 214040622005 | CORRODED T/R | | 4/22/98 HEEA0014019 |
| EXCESSIVE CORROSION. SCRAPPED LOCALLY. | | | | | | | | | |
| 6510 HEEA | 8045T 28101 | BELL 214ST | | | | SHAFT ASSY 214040622005 | CORRODED T/R | | 4/22/98 HEEA0014022 |
| EXCESSIVE CORROSION. SCRAPPED LOCALLY. | | | | | | | | | |
| 6510 HEEA | 6957Y 28139 | BELL 214ST | | | | SHAFT ASSY 214040622005 | CORRODED T/R | | 4/22/98 HEEA0014023 |
| EXCESSIVE CORROSION. SCRAPPED LOCALLY. | | | | | | | | | |
| 6510 HEEA | 6957Y 28139 | BELL 214ST | | | | SHAFT ASSY 214040622005 | CORRODED T/R | | 4/22/98 HEEA0014024 |
| EXCESSIVE CORROSION. SCRAPPED LOCALLY. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|------------------------------|------------------------------|-----------|----------------------------|
| 7931 HEEA | 59805 28141 | BELL 214ST | | | | INDICATOR 1179405807 | FAILED ENG OIL | | 4/29/98 HEEA0014073 |
| PRESSURE NEEDLE FLUCTUATES WHEN VIBRATED. | | | | | | | | | |
| 2432 HEEA | 6992 47521 | BELL 222U | | | | BATTERY RG380E44 | FAILED DC SYS | 16 | 4/29/98 HEEA0014038 |
| BATTERY WAS FOUND AT 6 VOLTS ON 3-11-98. BATTERY WAS CHARGED TO 22.5 VOLTS. WHILE DISCONNECTED FROM AIRCRAFT, VOLTAGE DROPPED FROM 22.5 VOLTS TO 18 VOLTS IN ONE HOUR. VOLTAGE WAS MEASURED AT 15.4 VOLTS AFTER 5 HOURS. AIRCRAFT BATTERY WAS INSTALLED NEW AT 4469:05 AIRCRAFT HOURS ON 1-30-98. REPLACED WITH SERVICEABLE AIRCRAFT BATTERY. | | | | | | | | | |
| 5610 HEEA | 230UN 23009 | BELL 230 | | | | VENT WINDOW 222031290117 | HINGE BROKE CO-PILOT VENT | 1256 | 5/17/94 HEEA942203 |
| HINGES BROKE OFF CO-PILOT'S VENT WINDOW. | | | | | | | | | |
| 7261 HEEA | 230UN 23009 | BELL 230 | | | | SHAFT SEAL 6854424 | LEAK NR 2 ENG | 524 | 4/29/94 HEEA942146 |
| NR2 ENGINE HAS OIL LEAK. REMOVED AND REPLACED GARLOCK SEAL. | | | | | | | | | |
| 2435 HEEA | 407PH 53003 | BELL 407 | | | | BRUSH 206062200123 | WORN START/GEN | 1817 | 4/20/98 HEEA0013982 |
| PERFORMED 300 HOUR INSPECTION AND FOUND BRUSHES EXCESSIVELY WORN. REPLACED BRUSHES AND PACKING. | | | | | | | | | |
| 2821 HEEA | 407PH 53003 | BELL 407 | | | | VALVE 206061634003 | LEAKS FUEL FILTER | | 4/30/98 HEEA0014093 |
| VALVE LEAKS. | | | | | | | | | |
| 3212 HEEA | 407PH 53003 | BELL 407 | | | | GAUGE 212073905001 | CONTAMINATED FLOAT PRESS | | 4/29/98 HEEA0014067 |
| MOISTURE IN GAUGE. | | | | | | | | | |
| 3212 HEEA | 407MM 53060 | BELL 407 | | | | GAUGE 212073905001 | CONTAMINATED FLOAT PRESS | | 4/29/98 HEEA0014068 |
| MOISTURE IN GAUGE | | | | | | | | | |
| 5302 ALGR | 417AL 53054 | BELL 407 | | | | SKIN | DENTED TAILBOOM | | 4/22/98 98ZZZX1705 |
| DURING PRE-FLIGHT INSPECTION, FOUND SHARP DENT IN LT SIDE OF TAILBOOM SKIN APPROXIMATELY 34.8750 INCH FORWARD OF THE AFT END OF THE TAILBOOM CAN AND APPROXIMATELY 2.25 INCH IN LENGTH. THE DENT APPEARS TO HAVE BEEN CAUSED BY A TAIL ROTOR BLADE STRIKING THE TAILBOOM WHILE THE ROTORS WERE IN MOTION. | | | | | | | | | |
| 5532 HEEA | 437PH 53072 | BELL 407 | | | | FIN ASSEMBLY 206020113229 | DAMAGED VERT FIN | | 4/28/98 HEEA0014036 |
| INSPECTED VERTICAL FIN AS PER ASB407-98-17 FOR CUTS AND SCRATCHES. THE ALLOWABLE DEPTH WAS .020. THE TWO CUTS FOUND WERE .017 AND .024 DEEP. SCRAPPED PART. | | | | | | | | | |
| 6321 HEEA | 406PH 53198 | BELL 407 | | | | TRANSMITTER 222375077113 | FAILED TRANSMISSION | | 4/30/98 HEEA0014096 |
| GAUGE READS ZERO OIL PRESSURE. | | | | | | | | | |
| 6410 ALGR | 457AL 53151 | BELL 407 | | | 407012101107 | BLADE 406016100119 | CRACKED T/R | 1257 | 9/29/97 97ZZZX5133 |
| POST-FLIGHT FOUND TAILROTOR BLADE CRACKED AT INBOARD RADIUS INSIDE TOWARD LEADING EDGE. POSSIBLY STARTED AT CORROSION SPOT. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|------------------------------|-----------|----------------------------|
| 6510 HEEA | CGOFL 53130 | BELL 407 | | | | DISK COUPLING 406040340101 | CRACKED T/R DRIVE | | 4/30/98 HEEA0014098 |
| ONE DISK CRACKED ON NR7 THOMAS COUPLING PACK. | | | | | | | | | |
| 6720 HEEA | 407MM 53060 | BELL 407 | | | | LINK 406312103101 | WORN T/R | | 4/30/98 HEEA0014097 |
| TAIL ROTOR PITCH CHANGE LINK HAS EXCESSIVE MECHANICAL WEAR. | | | | | | | | | |
| 7261 HEEA | 407MM 53060 | BELL 407 | | | | FILTER ELEMENT 23063144 | CLOGGED ENG OIL | | 4/29/98 HEEA0014047 |
| ON DAILY INSPECTION FOUND OIL FILTER BYPASS BUTTON POPPED. REPLACED WITH SERVICEABLE FILTER. | | | | | | | | | |
| 7714 HEEA | 1167G 53067 | BELL 407 | | | | INDICATOR 407375002103 | INTERMITTENT ENG NG | | 4/30/98 HEEA0014099 |
| NG INDICATOR INTERMITTENT INOPERATIVE. | | | | | | | | | |
| 2210 HEEA | 23023 33080 | BELL 412 | | | | TARSYN 2593996333 | FAILED AUTO FLIGHT | | 4/29/98 HEEA0014071 |
| FAILS TEST 6.2 ON SST. COMPASS CARD WILL NOT MOVE. | | | | | | | | | |
| 2210 HEEA | 2148K 36001 | BELL 412 | | | | COMPUTER 7000298901 | FAILED AFCS | | 4/20/98 HEEA0013988 |
| AFCS COMPUTER FAILED. ROLL ACTUATOR HUNTS BOTH DIRECTIONS. | | | | | | | | | |
| 2312 HEEA | 3893L 33006 | BELL 412 | | | | TRANSEIVER 7001840913 | DEFECTIVE COCKPIT DISPLAY | | 4/29/98 HEEA0014087 |
| 50,250,400, AND 1200 LEDS WILL NOT LIGHT. | | | | | | | | | |
| 2312 HEEA | 3893S 33022 | BELL 412 | | | KTR905 | TRANSCIEVER 064100900 | GARBLED COCKPIT | | 2/7/94 HEEA942169 |
| GARBLED. SENT TO ALLIED SIGNAL AVIONICS FOR INSPECTION AND REPAIR. | | | | | | | | | |
| 2312 HEEA | 2258F 33073 | BELL 412 | | | | TRANSCIEVER 7001840913 | MALFUNCTION COCKPIT | | 4/29/98 HEEA0014079 |
| TRANSCIEVER POWER OUT FLUCTUATES WHEN VIBRATED. | | | | | | | | | |
| 2312 HEEA | 23023 33080 | BELL 412 | | | | COMM CONTROL 071121540 | DEFECTIVE COCKPIT | | 4/19/94 HEEA942182 |
| DIGITS TOO DIM IN SUNLIGHT. REPLACED DISPLAY DS901 AND FRONT LENS ON FACEPLATE. ALSO REPLACED TRANSFER SWITCH S102 FOR INTERMITTENT TRANSFER OF FREQUENCY. REPAIRED PROBLEM. | | | | | | | | | |
| 2312 HEEA | 141PH 33197 | BELL 412 | | | | TRANSCIEVER 7001840913 | MALFUNCTION COCKPIT | | 4/29/98 HEEA0014078 |
| TRANSCIEVER POWER OUT FLUCTUATES WHEN VIBRATED. | | | | | | | | | |
| 2312 HEEA | 33008 36004 | BELL 412 | | | | COMM CONTROL 071121540 | DEFECTIVE COCKPIT | | 4/26/94 HEEA942183 |
| CANNOT CHANGE FREQUENCY ON SMALL KNOB. CLEANED KHZ SELECTOR SWITCH S104. ALSO FOUND INTERMITTENT TRANSFER SWITCH S102. REPLACED TRANSFER SWITCH S102. REPAIRED PROBLEM. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|----------------------------|-----------|----------------------------|
| 2370 HEEA | 22608 33075 | BELL 412 | | | | CVR 9806020023 | FAILED COCKPIT | | 4/29/98 HEEA0014054 |
| CVR CAUSES THE "TEST" LIGHT TO STAY ILLUMINATED CONSTANTLY. | | | | | | | | | |
| 2370 HEEA | 2298Z 33077 | BELL 412 | | | | CVR 9806019001 | MALFUNCTION COCKPIT | 3885 | 4/22/98 HEEA0014012 |
| CVR NEEDS EVALUATION. | | | | | | | | | |
| 2436 HEEA | 23023 33080 | BELL 412 | | | | CONTROL UNIT 51509002R | FAILED DC SYS | | 5/1/98 HEEA0014106 |
| GENERATOR WOULD NOT COME ON LINE. | | | | | | | | | |
| 2611 HEEA | 22608 33075 | BELL 412 | | | | SMOKE DETECTOR 302319 | FAILED FUSELAGE | | 4/20/98 HEEA0013987 |
| SMOKE DET FAILS FUNCTION TEST. | | | | | | | | | |
| 2820 HEEA | 293CA 33005 | BELL 412 | | | | VALVE 233565 | FAILED FUEL SYS | | 4/29/98 HEEA0014069 |
| VALVE INOPERATIVE. | | | | | | | | | |
| 2822 HEEA | 2258F 33073 | BELL 412 | | | | CIRCUIT BREAKER MS22073705 | FAILED LT BOOST PUMP | | 10/12/94 94ZZZX6877 |
| LEFT BOOST PUMP WARNING LIGHT CAME ON IN-FLIGHT. CIRCUIT BREAKER TRIPPED AND WOULD NOT RESET. IPC FIGURE 96-39-5. | | | | | | | | | |
| 2822 HEEA | 107X 33113 | BELL 412 | | | | PUMP 205060606003 | FAILED BOOST | | 4/22/98 HEEA0014018 |
| TURNS AT VERY SLOW SPEED AND THEN POPS CIRCUIT BREAKER. | | | | | | | | | |
| 2840 HEEA | 7128R 36007 | BELL 412 | | | | SWITCH 42D218 | FAILED NR 2 FUEL FILTER | | 10/12/94 94ZZZX6876 |
| IN-FLIGHT, NR 2 ENGINE FUEL FILTER LIGHT ILLUMINATED. IPC FIGURE 71-2, ITEM 57. | | | | | | | | | |
| 2842 HEEA | 293CA 33005 | BELL 412 | | | | PROBE 391046199 | FAILED FUEL QTY | | 4/29/98 HEEA0014084 |
| FUEL QTY SENSOR CHAFED WIRE AND TROUBLESHOOTING. | | | | | | | | | |
| 3120 HEEA | 108X 33115 | BELL 412 | | | | CLOCK 212075514001 | MALFUNCTION COCKPIT | | 4/22/98 HEEA0014031 |
| CLOCK LOSES TIMES. | | | | | | | | | |
| 3414 HEEA | 7128R 36007 | BELL 412 | | | | INDICATOR 412075009105 | DEFECTIVE COCKPIT | | 4/20/98 HEEA0013986 |
| AIRSPEED IND EXCESSIVE CASE LEAKAGE AND READ OUT OF TOLERANCE. | | | | | | | | | |
| 3416 HEEA | 293CA 33005 | BELL 412 | | | | ALTIMETER 5035P2P44 | FAILED COCKPIT ENCODE | | 4/29/98 HEEA0014082 |
| ENCODER READS OUT OF TOLERANCE AT 10,000 FEET AND ABOVE. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------|-----------|----------------------------|
| 3416 HEEA | 293CA 33005 | BELL 412 | | | | ALTIMETER 5035P2P44 | ERROR COCKPIT ENCODE | | 4/29/98 HEEA0014083 |
| ENCODING ALT INDICATES 200 FEET LOW OUT OF TOLERANCE. | | | | | | | | | |
| 3416 HEEA | 2261D 33076 | BELL 412 | | | | ALTIMETER 1003511326 | DEFECTIVE COCKPIT | | 3/3/94 HEEA942217 |
| ALTIMETER HAS EXCESSIVE FRICTION ERROR. | | | | | | | | | |
| 3421 HEEA | 3893N 33010 | BELL 412 | | | | INDICATOR 1113034 | FAILED FLT DIRECTOR | | 5/1/98 HEEA0014108 |
| FD FLAG NOT RETRACTING WHEN POWER IS ON. | | | | | | | | | |
| 3421 HEEA | 108X 33115 | BELL 412 | | | | INDICATOR 1113034 | FAILED COCKPIT | | 5/1/98 HEEA0014109 |
| ATTITUDE INDICATOR WILL NOT OPERATE IN PITCH. | | | | | | | | | |
| 3425 HEEA | 2298Z 33077 | BELL 412 | | | | INDICATOR 1113025 | ERRATIC COCKPIT HSI | | 4/16/94 HEEA942223 |
| CROSS TRACK DEVIATION POINTER HAS A ERRATIC OPERATION. | | | | | | | | | |
| 3425 HEEA | 22347 36005 | BELL 412 | | | | INDICATOR 1113025 | STICKS COCKPIT | | 4/29/98 HEEA0014081 |
| HSI INDICATOR HEADING SET POINTER STICKS INTERMITTENTLY. | | | | | | | | | |
| 3444 HEEA | 108X 33115 | BELL 412 | | | | INDICATOR 7000839904 | STICKS RADAR ALT | | 4/29/98 HEEA0014080 |
| RADAR ALT NEEDLE STICKS AT 210 FEET. | | | | | | | | | |
| 5260 HEEA | 293CA 33005 | BELL 412 | | | | ACTUATOR 212075418105 | FAILED STEP | 11 | 4/21/98 HEEA0013998 |
| STEP ACTUATOR INOPERATIVE. | | | | | | | | | |
| 5260 HEEA | 293CA 33005 | BELL 412 | | | | ACTUATOR 212075418105 | FAILED STEP | 8 | 4/21/98 HEEA0013997 |
| STEP ACTUATOR INOPERATIVE. | | | | | | | | | |
| 5260 HEEA | 293CA 33005 | BELL 412 | | | | ACTUATOR 212075418105 | STRIPPED STEP | 365 | 4/21/98 HEEA0013996 |
| ACTUATOR INTERNAL GEAR SEEMS TO BE STRIPPED. | | | | | | | | | |
| 5260 HEEA | 33008 36004 | BELL 412 | | | SYLC502281 | MOTOR FYLM735023 | FAILED STEP | | 4/8/94 HEEA942138 |
| STEP WILL NOT EXTEND. MOTOR INSPECTED BY ACCESSORY SHOP AND FOUND DEAD SPOT ON THE ARMATURE. | | | | | | | | | |
| 6220 HEEA | 2258F 33073 | BELL 412 | | | 412010100193 | BOLT 412010124109 | COATING CHIPPED M/R | 1036 | 5/18/94 HEEA942245 |
| CARBIDE COATING CHIPPED BEYOND LIMITS. SEE MMIR'S #2243 THROUGH #2245 FOR ADDITIONAL BOLTS. BOLT S/N A561, A725 & A739. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|---------------------------------|-----------|----------------------------|
| 6220 HEEA | 2258F 33073 | BELL 412 | | | 412010100193 | BOLT 412010124109 | COATING CHIPPED M/R | 1036 | 5/18/94 HEEA942243 |
| CARBIDE COATING CHIPPED BEYOND LIMITS. SEE MMIR'S #2243 THROUGH #2245 FOR ADDITIONAL BOLTS. BOLT S/N A357 & A365. | | | | | | | | | |
| 6220 HEEA | 2258F 33073 | BELL 412 | | | 412010100193 | BOLT 412010124109 | COATING CHIPPED M/R | 1036 | 5/18/94 HEEA942244 |
| CARBIDE COATING CHIPPED BEYOND LIMITS. SEE MMIR'S #2243 THROUGH #2245 FOR ADDITIONAL BOLTS. BOLT S/N A390, A393 & A440. | | | | | | | | | |
| 6220 HEEA | 2261D 33076 | BELL 412 | | | | BOLT 412010124109 | DEFECTIVE M/R | 580 | 5/18/94 HEEA942208 |
| CARBIDE COATING FLAKING FROM BOLT. BOLT S/N A23, A29, & A745. | | | | | | | | | |
| 6220 HEEA | 2148K 36001 | BELL 412 | | | 412010406115 | BEARING 412310400107 | WORN M/R LINK | 456 | 4/17/94 HEEA942230 |
| BEARING WORN BEYOND LIMITS. | | | | | | | | | |
| 6220 HEEA | 2148K 36001 | BELL 412 | | | 412010406115 | BEARING 412310400107 | WORN M/R LINK | 456 | 4/17/94 HEEA942229 |
| BEARING WORN BEYOND LIMITS. | | | | | | | | | |
| 6220 HEEA | 7128R 36007 | BELL 412 | | | 412010406115 | BEARING 412310400107 | WORN M/R LINK | 722 | 4/28/94 HEEA942231 |
| BEARING WORN BEYOND LIMITS. | | | | | | | | | |
| 6240 HEEA | 142PH 33150 | BELL 412 | | | | DETECTOR 214074280107 | FAILED RPM LIMIT | | 4/21/98 HEEA0013999 |
| RPM LIMIT AUDIO DISABLED. | | | | | | | | | |
| 6420 HEEA | 1202T 33112 | BELL 412 | | | | HUB ASSY 212011701101 | WORN T/R FEATHER BRG | | 4/29/98 HEEA0014064 |
| T/R HUB ASSY WORN FEATHERING BEARING. REPLACED BEARINGS AND RETURNED TO SERVICE. | | | | | | | | | |
| 2612 CHIR | CFHFW 107 | BOEING 1072 | | | | FIRE DETECTOR 473275 | FAILED OUTBOARD | | 3/23/98 CHI2088 |
| FIRE DETECTOR MALFUNCTION CAUSED FIRE LIGHT TO FALSELY ILLUMINATE. INSTALLED PER STC SR00375SE. (X) | | | | | | | | | |
| 2612 CHIR | CFHFW 107 | BOEING 1072 | | | KIDDE | FIRE DETECTOR 473275 | MALFUNCTIONED AFT LOWER OTBD | | 3/23/98 CHI2087 |
| AFT LOWER OUTBOARD FIRE DETECTOR MALFUNCTION CAUSED FIRE LIGHT TO FALSELY ILLUMINATE. INSTALLED PER STC SR00375SE. (X) | | | | | | | | | |
| 2312 HEEA | 4391S S787 | BOLKMS BO105S | | | KY196 | TRANSCIVER 064101900 | DEFECTIVE COCKPIT | | 5/9/94 HEEA942211 |
| TRANSCIVER WARMS UP AND THEN SHUTS OFF. COULD NOT DUPLICATE PROBLEM. ADJUSTED MOD, SIDETONE AND SQUELCH AND FREQUENCY. BENCH CHECK GOOD. | | | | | | | | | |
| 2435 HEEA | 81982 S818 | BOLKMS BO105S | | | | STARTER 23032048 | FAILED ENGINE | 6825 | 4/29/98 HEEA0014070 |
| STARTER WILL NOT ENGAGE. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|---------------------------|-----------|----------------------------|
| 2562 HEEA | 54191 S804 | BOLKMS BO105S | | | NARCO | ELT ELT10 | FAILED BATTERY | | 4/22/98 HEEA0014026 |
| BATTERY INOPERATIVE. TIME SINCE REPAIR 0:00. | | | | | | | | | |
| 2842 HEEA | 81992 S827 | BOLKMS BO105S | | | | TRANSMITTER DK042 | FAILED FUEL IND | 4 | 4/21/98 HEEA0014000 |
| TRANSMITS HIGH OUT OF TOLERANCE THROUGHOUT. | | | | | | | | | |
| 3416 HEEA | 54191 S804 | BOLKMS BO105S | | | ACK | ENCODER A30 | FLUCTUATES COCKPIT | | 4/4/94 HEEA942136 |
| ENCODER OUTPUT FLUCTUATES 200 FEET CONTINUOUSLY. | | | | | | | | | |
| 3422 HEEA | 205BB S58 | BOLKMS BO105S | | | KG102A | GYRO 060001500 | DEFECTIVE COCKPIT | | 3/3/94 HEEA942209 |
| GYRO WILL NOT BECOME VALID AND HEADING IS UNSTABLE. TIME SINCE REPAIR 175:00. | | | | | | | | | |
| 3422 HEEA | 4391S S787 | BOLKMS BO105S | | | KG102A | GYRO 060001500 | TRIPS BREAKER COCKPIT | | 5/2/94 HEEA942210 |
| GYRO POPS CIRCUIT BREAKER. TIME SINCE REPAIR 0:00. | | | | | | | | | |
| 3452 HEEA | 5368F S718 | BOLKMS BO105CB* | | | KT76 | TRANSPONDER 066106200 | INOP COCKPIT | | 4/18/94 HEEA942177 |
| TOWER REPORTED TRANSPONDER WAS NOT WORKING. TROUBLESHOT AND REPLACED V101 (TUBE), R441 (RESISTOR), R429 (RESISTOR). ADJUSTED THE RECEIVER AND TRANSMITTER. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 HEEA | 8197X S808 | BOLKMS BO105S | | | KT76 | TRANSPONDER 066106200 | INOP COCKPIT | | 4/11/94 HEEA942174 |
| TRANSCIEVER INOPERATIVE. TROUBLESHOT AND ADJUSTED LOW POWER OUT. ALSO REPLACED DETERIORATED RESISTOR R477. REPAIRED PROBLEM. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 HEEA | 7136J S830 | BOLKMS BO105S | | | | TRANSPONDER 066106200 | BROKEN COCKPIT | | 5/16/94 HEEA942213 |
| TRANSCIEVER FACE COVER BROKEN. REPLACED FACEPLATE ASSY, DETERIORATED RESISTOR R477 AND PHOTOCCELL V301. ADJUSTED SIDE LOBE SUPPRESSION. REPAIRED PROBLEM. | | | | | | | | | |
| 5302 ALGR | 502AL S103 | BOLKMS BO105C | | | | PLATE 1052180110033 | CRACKED TAILBOOM MOUNT | | 11/5/97 97ZZX5134 |
| DISCOVERED DURING DAILY INSPECTION, WORKING RIVETS AT TAIL ROTOR DRIVESHAFT FORWARD ATTACH BRACKET. REMOVED BRACKET AND DISCOVERED PLATE CRACKED AT RIVET HOLE. | | | | | | | | | |
| 6210 HEEA | 5352H S717 | BOLKMS BO105CB* | | | | BLADE 10515170 | SEPARATION M/R | 7367 | 5/11/94 HEEA942187 |
| SEPARATION ON THE INBOARD LEADING EDGE STRIP ON THE INBOARD END. THE OUTBOARD STRIP HAS EXCESSIVE AMOUNT OF EROSION NEAR THE TIP. SENT TO COMPOSITE TECHNICIS FOR INSPECTION AND REPAIR. | | | | | | | | | |
| 6210 HEEA | 5352H S717 | BOLKMS BO105CB* | | | | BLADE 10515170 | SEPARATION M/R | 7367 | 5/11/94 HEEA942186 |
| SEPARATION ON OUTBOARD END OF THE OUTBOARD STRIP. ALSO WITH EXCESSIVE EROSION ON THE LEADING EDGE ABRASION STRIP. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|--------------------------|-----------|----------------------------|
| 6210 HEEA | 205BB S58 | BOLKMS BO105S | | | | BLADE 10587214 | DEFECTIVE M/R | 8417 | 1/26/94 HEEA942222 |
| UNABLE TO GET SMOOTH RIDE IN FLIGHT WITH GOOD VISUAL TRACK .8 IPS VERTICAL. NOTE: WITH SMOOTH RIDE IN FLIGHT .7 IPS LATERAL ON GROUND. TIME SINCE REPAIR 15:55. | | | | | | | | | |
| 6210 HEEA | 7136H S833 | BOLKMS BO105S | | | | BLADE 10515141 | DEFECTIVE M/R | 6760 | 2/1/94 HEEA942220 |
| UNABLE TO BALANCE M/R BLADE. | | | | | | | | | |
| 6210 HEEA | 7136H S833 | BOLKMS BO105S | | | | BLADE 10515141 | WONT TRACK M/R | 8777 | 2/3/94 HEEA942221 |
| UNABLE TO TRACK BLADE IN FLIGHT - BLADE DIVES EXCESSIVELY. TIME SINCE REPAIR 1:00. | | | | | | | | | |
| 6240 HEEA | 3520T S539 | BOLKMS BO105S | | | | WARNING BOX KDW021A | FAILED ROTOR RPM | | 4/22/98 HEEA0014030 |
| INTERMITTENT LIGHT AND AUDIO AT 100% RPM. | | | | | | | | | |
| 6240 HEEA | 6607K S841 | BOLKMS BO105S | | | | INDICATOR 206075681117 | INTERMITTENT ROTOR | | 4/29/98 HEEA0014075 |
| ROTOR NEEDLE IS INTERMITTENT AND NOISY. | | | | | | | | | |
| 6310 HEEA | 3071K S859 | BOLKMS BO105S | | | 4638001004 | INPUT PINION 4638302002 | WORN FREEWHEEL | | 4/29/98 HEEA0014062 |
| INPUT PINION BEARING JOURNAL WORN BEYOND LIMITS. REPLACED WITH NEW PINION. | | | | | | | | | |
| 6710 HEEA | 50293 S677 | BOLKMS BO105S | | | 10545371 | BEARING 1054537110 | UNBONDED MIXING LEVER | | 4/29/98 HEEA0014044 |
| TEFLON LINER UNBONDED AND BEARING VERY STIFF. UNABLE TO MOVE INNER RACE. REPLACED WITH NEW BEARING. | | | | | | | | | |
| 6710 HEEA | 5031U S678 | BOLKMS BO105S | | | 10545371 | BEARING 1054537110 | UNBONDED MIXING LEVER | | 4/29/98 HEEA0014040 |
| TEFLON UNBONDING FROM BEARING. REPLACED WITH NEW BEARING. | | | | | | | | | |
| 6710 HEEA | 133AE S800 | BOLKMS BO105S | | | 10545371 | BEARING 1054537110 | UNBONDED MIXING LEVER | | 4/29/98 HEEA0014041 |
| TEFLON UNBONDING FROM BEARING. REPLACED WITH NEW BEARING. | | | | | | | | | |
| 6710 HEEA | 81992 S827 | BOLKMS BO105S | | | 10545371 | BEARING 1054537110 | UNBONDED MIXING LEVER | | 4/29/98 HEEA0014043 |
| TEFLON LINER UNBONDED AND BEARING VERY STIFF. UNABLE TO MOVE INNER RACE. REPLACED WITH NEW BEARING. | | | | | | | | | |
| 6710 HEEA | 135AE S838 | BOLKMS BO105S | | | 10545371 | BEARING 1054537110 | UNBONDED MIXING LEVER | | 4/29/98 HEEA0014042 |
| TEFLON UNBONDING FROM BEARING. REPLACED WITH NEW BEARING. | | | | | | | | | |
| 7250 HEEA | 205BB S58 | BOLKMS BO105C | ALLSN 250C20B | | 6898735 | WHEEL 6886407 | SULFIDATION 1ST STAGE | 1422 | 5/4/94 HEEA942239 |
| ENGINE REMOVED DUE TO HIGH CYCLED WHEELS. UPON INSPECTION OF TURBINE PARTS NOTED SULFIDATION ON 1ST STAGE WHEEL BLADES. PART SCRAPPED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|--------------------------|-----------|----------------------------|
| 7250 HEEA | 131AE S787 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | NOZZLE SHIELD 6890040 | CRACKED NR 1 | 665 | 4/21/98 HEEA0013994 |
| ENGINE REMOVED DUE TO TURBINE CYCLES. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD INNER BAND AS MARKED AND CRACK AT POSITIONING LUGS AS MARKED. | | | | | | | | | |
| 7250 HEEA | 133AE S800 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | NOZZLE SHIELD 23062750 | CRACKED NR1 | 753 | 4/21/98 HEEA0014003 |
| ENGINE REMOVED DUE TO 3500 HOUR TURBINE OVERHAUL. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD DOME AREA ABOUT 45% AROUND. | | | | | | | | | |
| 7250 HEEA | 911EB S812 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | TURBINE WHEEL 6898782 | PITTED 2ND STAGE | | 4/21/98 HEEA0014001 |
| RECEIVING INSPECTION REVEALED: PITS BEYOND SERVICEABLE LIMITS ON NR2 WHEEL BLENDED AREA E (AFT) AS MARKED. NOTE: BLENDING OF THESE PITS WOULD EXCEED OVERHAUL LIMITS OF .050 DEEP. INSTALLED A NEW NR2 WHEEL. | | | | | | | | | |
| 7250 HEEA | 8199J S826 | BOLKMS BO105S | ALLSN 250C20B | | 23038241 | TURBINE WHEEL 6886407 | DEFECTIVE 1ST STAGE | 1738 | 4/20/98 HEEA0013981 |
| ENGINE REMOVED DUE TO TURBINE 1750 HOUR INSPECTION. UPON INSPECTION OF TURBINE PARTS NOTED: CATASTROPHIC SULFIDATION ON ALL NR1 WHEEL BLADES. SCRAPPED NR1 WHEEL AND REPLACED WITH SERVICEABLE PART. | | | | | | | | | |
| 7250 HEEA | 8199J S826 | BOLKMS BO105S | ALLSN 250C20B | | 23038241 | TURBINE WHEEL 23001967 | DEFECTIVE 3RD STAGE | 1738 | 4/20/98 HEEA0013980 |
| ENGINE REMOVED DUE TO TURBINE 1750 HOUR INSPECTION. UPON INSPECTION OF TURBINE PARTS NOTED: SEVERE SULFIDATION ON ALL NR3 WHEEL BLADES. SCRAPPED NR3 WHEEL AND REPLACED WITH SERVICEABLE PART. | | | | | | | | | |
| 7250 HEEA | 7136J S830 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | COUPLING 6898977 | STEPWEAR SPLINES | 726 | 5/10/94 HEEA942241 |
| ENGINE REMOVED DUE TO LOW POWER. UPON INSPECTION OF TURBINE PARTS NOTED THE FOLLOWING: STEP WEAR IN EXCESS OF THE .001" OPERATION AND MAINTENANCE MANUAL LIMITS ON TURBINE TO COMPRESSOR COUPLING INTERNAL SPLINES. INSTALLED A NEW COUPLING. | | | | | | | | | |
| 7260 HEEA | 131AE S787 | BOLKMS BO105S | ALLSN 250C20B | | 6894171 | TUBE ASSY 6876925 | WORN ENG GR BOX | | 4/21/98 HEEA0014011 |
| ENGINE REMOVED DUE TO METAL. INSPECTION OF GEARBOX PARTS REVEALED: TUBE ASSY. FAILED DIMENSIONAL CHECK PER CEB1307. INSTALLED A NEW TUBE. | | | | | | | | | |
| 7260 HEEA | 8199J S826 | BOLKMS BO105S | ALLSN 250C20B | | 6894171 | TUBE ASSY 6876925A | WORN ENG GR BOX | 1719 | 4/21/98 HEEA0014010 |
| ENGINE REMOVED DUE TO METAL. INSPECTION OF GEARBOX PARTS REVEALED: TUBE ASSY. FAILED DIMENSIONAL CHECK PER CEB1307. INSTALLED A NEW TUBE. | | | | | | | | | |
| 7321 HEEA | 352TT S59 | BOLKMS BO105S | ALLSN 250C20B | | | FUEL CONTROL 104900A5 | FAULTY ENGINE | | 1/13/94 HEEA942219 |
| FUE CONTROL INTERMITTENT-STAGNATION IN ACCELERATION FROM IDLE TO 70% N1 AND ABOVE. | | | | | | | | | |
| 7714 HEEA | 9190Y S669 | BOLKMS BO105CBS | | | | TACH GENERATOR AG44A202 | FAILED NR 2 ENG | | 9/29/94 94ZZZX6878 |
| OUTBOUND FLIGHT, NR 2 ENGINE N2 TACHOMETER GENERATOR FAILED. RETURNED TO BASE. BO-105IPC, CHAPTER 2-604-00, FIGURE 604, ITEM 240. | | | | | | | | | |
| 7923 HEEA | 9190F S668 | BOLKMS BO105S | | | | VALVE 209072433007 | TRIPS BREAKER OIL SOV | | 4/25/94 HEEA942153 |
| POPS CIRCUIT BREAKER. INSPECTED BY ACCESSORY OVERHAUL SHOP AND FOUND SOLENOID IS SHORTED TO GROUND. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|---------------------------|--------------------------|-----------|----------------------------|
| 2150 HEEA | 191BK 7146 | BOLKMS BK117B1 | | | | ELBOW 117E00113 | MIS MFG VENTURI | | 4/29/98 HEEA0014048 |
| VENTURI P/N 117-E0011-9 DOES NOT FIT PROPERLY IN ELBOW P/N 117-E0011-3. WELD BEADS ON INSIDE OF ELBOW DO NOT ALLOW VENTURI TO FIT FLUSH ON PLATE P/N 117-E0001-47. REPLACED WITH SERVICEABLE PART. | | | | | | | | | |
| 2210 HEEA | 911NC 7026 | BOLKMS BK117A3 | | | | SPAS COMPUTER 11788292 | DEFECTIVE COCKPIT | | 1/22/94 HEEA942227 |
| SPAS LIGHT ILLUMINATES AS SOON AS SWITCH IS PUT INTO POSITION - SPAS OPERATES NORMALLY IN FLIGHT. | | | | | | | | | |
| 2312 HEEA | 911TL 7198 | BOLKMS BK117B1 | | | | TRANSCIEVER 064105430 | DEFECTIVE COCKPIT | | 5/4/94 HEEA942212 |
| TRANSCIEVER NO DISPLAY. | | | | | | | | | |
| 2612 RMXA | 460H 7142 | BOLKMS BK117B1 | | | | DETECTOR 17343624101 | FAILED LOWER AFT | | 4/24/98 98ZZZX1703 |
| FOUND LOWER AFT FIRE DETECTOR STARTING TO SHORT INTERNALLY. REMOVED DEFECTIVE PART, INSTALLED SERVICEABLE PART. | | | | | | | | | |
| 3310 HEEA | 911MZ 7098 | BOLKMS BK117A3 | | | 830000501 | CONTROL 1179203103 | OVERHEAT LIGHTS | | 11/1/97 97ZZZX5132 |
| INSPECTED RHEOSTAT, WIRING, AND INTENSITY CONTROL UNIT. FOUND CONTROL UNIT TO HAVE STRONG ELECTRICAL ODOR. REPLACED WITH NEW UNIT. OPS CHECK GOOD. | | | | | | | | | |
| 3310 HEEA | 132AE 7238 | BOLKMS BK117B1 | | | | POTENTIOMETER 260T4641 | DEFECTIVE COCKPIT | 466 | 5/21/94 HEEA942248 |
| POTENTIOMETER CAUSES INSTRUMENT LIGHT TO BE FULL ON OR FULL OFF; WILL NOT DIM. | | | | | | | | | |
| 3420 HEEA | 134AE 7237 | BOLKMS BK117B2 | | | | INDICATOR 4021541671 | DEFECTIVE COCKPIT | | 4/22/98 HEEA0014032 |
| ARTIFICIAL HORIZ INDICATOR INTERNAL LIGHTS SHORTED. | | | | | | | | | |
| 3457 HEEA | 911TL 7198 | BOLKMS BK117B1 | | | SKYNAV 5000 | GPS 0845000000 | FAILED COCKPIT | | 4/20/98 HEEA0013985 |
| INTERMITTENTLY LOSING POWER AND SHUTTING DOWN. NOT AIRCRAFT WIRING. DOES SAME WHEN POWERED UP ON BENCH. FOUND UNIT TO LOCK UP AND CHANGES MODES WITHOUT PRESSING ANY KEYS. | | | | | | | | | |
| 5610 HEEA | 136AE 7234 | BOLKMS BK117B1 | | | | WINDOW 1172429702 | CRACKED COCKPIT RT | 508 | 5/18/94 HEEA942246 |
| RIGHT WINDOW CRACKED. | | | | | | | | | |
| 6410 BAQA | 911TG 7506 | BOLKMS BK117B1 | | | | BLADE 117317411 | CRACKED T/R | 1087 | 4/21/98 98ZZZX1704 |
| DURING A PRE-FLIGHT INSPECTION, THE MECHANIC FOUND A 3 INCH CRACK AT THE ROOT END OF TAIL ROTOR BLADE. THIS IS THE THIRD EVENT. 11-18-94, 198.4 HRS, S/N 116/118. 5-3-96, 1,050.1 HRS, S/N 103/104. 858.5 HOURS ON THE BLADES, SAME P/N. | | | | | | | | | |
| 6520 HEEA | 911TL 7198 | BOLKMS BK117B1 | | | 4639003007 | COVER 4639311010 | WORN T/R XMSN | 3102 | 4/29/98 HEEA0014063 |
| FORWARD BORE WORN FROM BEARING SPINNING. REPLACED WITH NEW COVER. | | | | | | | | | |
| 6710 HEEA | 911RZ 7092 | BOLKMS BK117A4 | | | 10545371 | BEARING 1054537110 | UNBONDED MIXING LEVER | | 4/29/98 HEEA0014045 |
| TEFLON LINER UNBONDED AND BEARING VERY STIFF. UNABLE TO MOVE INNER RACE. REPLACED WITH NEW BEARING. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|---------------------------|-----------|----------------------------|
| 6710 HEEA | | BOLKMS BK117B1 | | | | TUBE YAJ119607200F | MIS MFG M/R | | 5/23/94 HEEA942205 |
| TUBE NOT THREADED ALL THE WAY FOR ROD ENDS. | | | | | | | | | |
| 6730 HEEA | 132AE 7238 | BOLKMS BK117B1 | | | | ACTUATOR 741C000004 | KICKS YAW SAS | 462 | 5/17/94 HEEA942242 |
| YAW SAS KICKS OFF THEN ON INTERMITTENTLY. | | | | | | | | | |
| 7320 BAQA | 967LS 7067 | BOLKMS BK117A3 | LYC LTS101650B1 | | | ACTUATOR 430110212 | FAILED FLOW FENCE | 181 | 4/16/98 98ZZZX1684 |
| INTERNAL BREAKDOWN OF AIR FLOW MODULATOR (FLOW FENCE ACTUATOR) CAUSED THE OCCURRENCE OF COMPRESSOR STALLS DURING APPROACH TO LANDING. | | | | | | | | | |
| 7414 | 51699 416 | ENSTRM F28C | LYC HIO360E1AD | | | POINTS 10382585 | FAILED RT MAG | | 7/8/94 94ZZZX4574 |
| AIRCRAFT HAD PARTIAL POWER LOSS WITH REDUCTION OF POWER. PILOT FELT ROUGHNESS AND ENTERED AUTOROTATION. OFF-AIRPORT LANDING OKAY. ENGINE INSPECTION REVEALED RT SET OF MAG POINTS CLOSED SUFFICIENTLY ENOUGH TO CAUSE RT SIDE MAG POWER LOSS. INSTALLED NEW SET OF POINTS, P/N 10-382585-OP. OP CHECK OKAY. | | | | | | | | | |
| 6520 LS1R | 369AW 470117D | HUGHES 369D | | | | GEARBOX 369D25400 | MAKING METAL T/R | | 4/16/98 98ZZZX1702 |
| DURING ROUTINE INSPECTION, MECHANIC FOUND METAL AND EXCESSIVELY DARK OIL IN GEARBOX. REMOVED FOR REPAIR AND REPLACED WITH SERVICEABLE UNIT. CONTROL NR 98-4-8. | | | | | | | | | |
| 2430 HEEA | 1546K 760082 | SKRSKY S76A | | | | RELAY A1077D | FAILED DC SYS | | 4/29/98 HEEA0014059 |
| RELAY CONTACTS STUCK. REPLACED WITH SERVICEABLE RELAY. | | | | | | | | | |
| 2430 HEEA | 5435V 760158 | SKRSKY S76A | | | | TRANSFORMER 6153A | FAILED DC SYS | | 4/22/98 HEEA0014027 |
| BURNING SMELL COMING FROM UNIT AND CAUSES TONE IN HEADSET. | | | | | | | | | |
| 2611 HEEA | 1546K 760082 | SKRSKY S76A | | | | SMOKE DETECTOR 30231R7B | MALFUNCTION ENGINE | | 5/1/98 HEEA0014103 |
| SMOKE DETECTOR GAVE INDICATION OF FIRE ONCE IN FLIGHT. | | | | | | | | | |
| 2612 HEEA | 5427S 760168 | SKRSKY S76A | | | | DETECTOR 473205 | FAILED FWD FIRE SENSOR | | 9/29/94 94ZZZX6875 |
| IN CRUISE FLIGHT, FORWARD FIRE SENSOR LIGHT CAME ON. LANDED AT HOUSTON HOBBY. REPLACED FORWARD FLAME DETECTOR. S-76 IPC, CHAPTER 26-11-00, FIGURE 1, ITEM 21. | | | | | | | | | |
| 2910 HEEA | 792CH 760193 | SKRSKY S76A | | | | LINE 7665103003053 | PIN HOLE NR 2 HYD SYS | | 10/17/94 94ZZZX6874 |
| NR 2 HYDRAULIC SYSTEM BECAME NOISEY AND PRESSURE BEGAN TO FLUCTUATE. FOUND DECK COVERED WITH HYDRAULIC OIL. PIN HOLE IN LINE. IPC CHAPTER 29-20-00, FIGURE 1, ITEM 18. | | | | | | | | | |
| 3414 HEEA | 31217 760229 | SKRSKY S76A | | | | INDICATOR 8502CS20LW | FAILED COCKPIT | | 5/1/98 HEEA0014102 |
| AIRSPEED INDICATOR INDICATES HIGH OUT OF TOLERANCE. | | | | | | | | | |
| 3421 HEEA | 1547D 760077 | SKRSKY S76A | | | | INDICATOR 125780 | PRECESSES COCKPIT ADI | | 5/1/98 HEEA0014107 |
| ADI INDICATOR PRECESSING IN FLIGHT. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|-----------------------------|-------------------------------|-----------|----------------------------|
| 3425 HEEA | 1545K 760047 | SKRSKY S76A | | | | INDICATOR 1113025 | INTERMITTENTLY COCKPIT HSI | | 4/15/94 HEEA942225 |
| NAV FLAG AND DEVIATION BAR WORKS INTERMITTENTLY. | | | | | | | | | |
| 3425 HEEA | 1546K 760082 | SKRSKY S76A | | | | INDICATOR 1113025 | NEEDLE STICKS COCKPIT HSI | | 4/23/94 HEEA942224 |
| HEADING NEEDLE STICKS. . | | | | | | | | | |
| 3425 HEEA | 5435V 760158 | SKRSKY S76A | | | | INDICATOR 1113025 | DEFECTIVE COCKPIT HSI | | 3/23/94 HEEA942226 |
| INDICATOR CAUSES SECOND HSI TO BE 180 DEGREES OFF WHEN THIS UNIT IS IN THE COMMAND MODE. TIME SINCE REPAIR 0:00. | | | | | | | | | |
| 3454 HEEA | 3122G 760232 | SKRSKY S76A | | | | RECEIVER 066400700 | MALFUNCTION COCKPIT | | 5/2/94 HEEA942181 |
| #2 NAV RADIO WOULD NOT TEST ON VOR FREQUENCY. INSPECTED FOR CORROSION, ADJUSTED VOR TRACKING, GLIDESCOPE CENTERING, GLIDESCOPE SENSE AND GLIDESCOPE SUPER FLAG. BENCH CHECK GOOD. | | | | | | | | | |
| 5610 HEEA | 5435V 760158 | SKRSKY S76 | | | | WINDSHIELD 7620601001110 | CRACKED PILOT'S | | 10/17/94 94ZZZX6879 |
| BRIGHT ARCING DEVELOPED IN PILOT'S WINDSHIELD. INVESTIGATION REVEALED ARCING AND CRACKS. IPC 56-10-00, FIGURE 1, PAGE 1, ITEM 13. | | | | | | | | | |
| 6320 HEER ***** | 1546G 760076 | SKRSKY S76A | | | | SPUR GEAR 7635109032047 | FRACTURED M/R GEARBOX | | 4/27/98 98ZZZX1706 |
| INVESTIGATION INTO A SERIES OF CHIP DETECTOR LIGHTS ON THE MAIN GEARBOX REVEALED THE SPUR GEAR HAD FRACTURED IN THREE PLACES. THE WEB OF THE GEAR HAD TWO SEPARATE FRACTURES AND THE SHAFT OF THE GEAR HAD ONE FRACTURE. TWO OF THE PINS (P/N HL12VLJ-8-5/6) THAT SECURE THE SPUR GEAR ASSEMBLY TOGETHER HAD ALSO SHEARED. MANY OTHER PINS SHOWED SIGNS OF WORKING. THE MAIN GEARBOX WAS OVERHAULED 227 OPERATING HOURS PRIOR TO THIS OCCURRENCE. THE SPUR GEAR IS NOT A LIFE LIMIT PART; THEREFORE, HISTORICAL RECORDS ARE NOT REQUIRED AND THE TOTAL TIME IN SERVICE OF THE GEAR IS NOT KNOWN AT THIS TIME. | | | | | | | | | |
| 6410 HEEA | 1546G 760076 | SKRSKY S76A | | | | BLADE 7610105101041 | ERODED T/R | 11725 | 4/22/98 HEEA0014016 |
| BOTH PRIMARY RUBBER ERRODED THROUGH AND PITCH HORN "A" IS DUE RETIREMENT. | | | | | | | | | |
| 6510 HEEA | 4253S 760035 | SKRSKY S76A | | | 763610400704 | TUBE ASSY S613764329002 | SEPARATED T/R DRIVE | | 4/29/98 HEEA0014061 |
| T/R DRIVE TUBE SEPARATED BEYOND LIMITS. REPLACED WITH NEW TUBE ASSEMBLY. | | | | | | | | | |
| 7230 HEEA | 792CH 760193 | SKRSKY S76A | ALLSN 250C30S | | 23051643 | SPLINE ADAPTER 230052711 | MIS MFG ENGINE | | 4/30/98 HEEA0014092 |
| RECEIVING INSPECTION REVEALED: O.D. MEASURED (.9853) .0002 UNDER SPECS ON SPLINE ADAPTER O.D. INSTALLED A NEW SPLINE ADAPTER. | | | | | | | | | |
| 7250 HEEA | 5426U 760167 | SKRSKY S76A | ALLSN 250C30S | | 23035128 | NOZZLE SHIELD 23062752 | CRACKED NR 1 | 677 | 4/21/98 HEEA0013995 |
| ENGINE REMOVED DUE TO NR1 AND NR2 WHEEL CYCLES. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD OUTER BAND. | | | | | | | | | |
| 7250 HEEA | 5128 760181 | SKRSKY S76A | ALLSN 250C30S | | 23035128 | NOZZLE SHIELD 6892824 | CRACKED NR 1 | 615 | 4/22/98 HEEA0014025 |
| ENGINE REMOVED DUE TO TURBINE CYCLES. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD DOME AS MARKED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|---------------------------|-----------|----------------------------|
| 7322 HEEA | 706AE 760275 | SKRSKY S76A | | | | FUEL CONTROL 25490925 | MALFUNCTIONED ENGINE | | 4/29/98 HEEA0014051 |
| FUEL CONTROL MALFUNCTION. WILL NOT TOP. DROOPS @ 90% TORQUE. UNIT HAS EXPERIENCED STARTING PROBLEMS | | | | | | | | | |
| 7714 HEEA | 1546K 760082 | SKRSKY S76A | | | | INDICATOR 7645001076101 | FAILED GAS GEN TACH | | 4/29/98 HEEA0014076 |
| GAS GEN TACH NO INDICATION ON DISPLAY OR ANALOG. | | | | | | | | | |
| 2823 HEEA | 350BZ 2653 | SNIAS AS350B2 | | | | VALVE 857A1641 | STUCK FUEL SYS | 839 | 4/29/98 HEEA0014066 |
| VALVE STUCK. | | | | | | | | | |
| 3412 HEEA | 6095S 2777 | SNIAS AS350B | | | | THERMOMETER K150 | READS HIGH COCKPIT | 7 | 5/14/94 HEEA942238 |
| THERMOMETER INDICATES 6 DEGREES HIGH. | | | | | | | | | |
| 3416 HEEA | 350BZ 2653 | SNIAS AS350B | | | | ALTIMETER 5934P1 | ERROR COCKPIT | 349 | 4/21/94 HEEA942155 |
| ALTIMETER READS ERRONEOUSLY. | | | | | | | | | |
| 5270 HEEA | 350BZ 2653 | SNIAS AS350B | | | | SWITCH SP381200 | INOP LT DOOR | 368 | 5/2/94 HEEA942154 |
| DOOR SWITCH INOPERATIVE. | | | | | | | | | |
| 6230 HEEA | 4000L 2873 | SNIAS AS350B2 | | | | LINK 350A37112601 | WORN M/R | 1612 | 4/30/98 HEEA0014094 |
| SISSORS LINK BUSHING WORN. | | | | | | | | | |
| 6230 | 398MA 1856 | SNIAS AS350BA | | | 350A37000305 | BEARING L522110V | DETERIORATED M/R SHAFT | 2774 | 4/27/98 98ZZZX1681 |
| LOWER MAST BEARING OUTER RACE DETERIORATING, MAKING METAL. SUBMITTER STATED ENSURE CORRECT MAST BEARING SHIMMING. | | | | | | | | | |
| 6321 HEEA | 40466 3004 | SNIAS AS350B2 | | | | BRAKE 350A32050002 | WORN ROTOR | 533 | 4/20/98 HEEA0013977 |
| ROTOR BRAKE OIL SOAKED AND WORN. | | | | | | | | | |
| 6330 HEEA | 6100R 2862 | SNIAS AS350B2 | | | 355A12004008 | BEARING 579063 | SEPARATION M/R XMSN MT | | 4/29/98 HEEA0014065 |
| RUBBER SEPARATION ON 4 EACH BEARINGS. | | | | | | | | | |
| 6410 QKLA | 333AS 2893 | SNIAS AS350B2 | | | | BEARING 355A09103601 | DELAMINATED T/R | | 10/9/97 98ZZZX1644 |
| BEARING REMOVED DUE TO DELAMINATION IN EXCESS OF LIMITS. REPLACED WITH NEW BEARING SET. | | | | | | | | | |
| 6420 HEEA | 4000L 2873 | SNIAS AS350B2 | | | | BEARING 350A33211905 | WORN T/R | 965 | 4/20/98 HEEA0013979 |
| T/R HEAD BEARINGS WORN. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 6520 | 333AS | SNIAS | | | | BEARING | DELAMINATED | | 10/9/97 |
| QKLA | 2893 | AS350B2 | | | | 350A33215300 | T/R | | 98ZZZX1643 |
| BEARING REMOVED DUE TO DELAMINATION IN EXCESS OF LIMITS. REPLACED WITH NEW BEARINGS. | | | | | | | | | |
| 7933 | 6095S | SNIAS | | | | TEMP PROBE | FAILED | 2620 | 4/30/98 |
| HEEA | 2777 | AS350B2 | | | | 646600251 | ENG OIL TEMP | | HEEA0014095 |
| TEMP PROBE INOPERATIVE. | | | | | | | | | |
| 7200 | 914ET | UROCOP | PWA | | | ENGINE | MALFUNCTIONED | 178 | 3/29/98 |
| HDNA | | EC135P1 | PW206B | | | | NR 1 | | 98ZZZX1699 |
| TWO MINUTES AFTER TAKEOFF, POWER DECREASED TO 20 - 40 PERCENT OF NORMAL ON NR 1 ENGINE. RETURNED FOR PRECAUTIONARY LANDING. ENGINE APPEARED TO FUNCTION NORMALLY BELOW 50 PERCENT TORQUE, ABOVE 50 PERCENT, TORQUE WOULD DECREASE. NO FURTHER INCIDENT OCCURRED. AIRCRAFT SHUT DOWN. ELECTRICAL CONNECTIONS CHECKED. OPERATIONAL CHECK FLIGHT PERFORMED AND RETURNED TO SERVICE. | | | | | | | | | |
| (End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS) | | | | | | | | | |

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 7320 | 942MS | AEROSP | ALLSN | | | CABLE | FRAYED | 99 | 4/27/98 |
| | 5498 | AS355F2 | 250C20F | | | 704A34130163 | NR 2 N2 CONTROL | | 98ZZZX1683 |
| CABLE FRAYED AND BEARING WORN OUT CAUSING BINDING OF N2 LINKAGE. SUBMITTER SUGGESTED INSTALLING A BETTER, MORE RELIABLE SYSTEM. | | | | | | | | | |
| 7414 | 247RJ | AMTRMO | AMTRVW | | | DRIVE COUPLING | FAILED | | 4/17/98 |
| | 999 | SONERAI2 | VW2200VOLKS | | | | ENGINE MAGNETO | | 98ZZZX1697 |
| ***** | THE CAST ALUMINUM MAGNETO DRIVE COUPLING WHICH IS KEYED TO THE FLYWHEEL BROKE INTO FOUR PIECES. THE RESULTANT FRICTION MELTED AND FUSED A PORTION OF THE BROKEN PIECES OF THE COUPLING TO THE STATIONARY CROSS MEMBER ENGINE MOUNT. THIS FAILURE OF THE MAGNETO COUPLING RESULTED IN THE FAILURE OF THE ENGINE DURING CRUISE AND ULTIMATELY THE ACCIDENT WHICH DESTROYED THE AIRCRAFT AND INJURED THE PILOT. THE COUPLING BROKE AT THE KEYWAYS AND SHOWED EVIDENCE OF PRE-EXISTING CRACKS POSSIBLY CASTING FLAWS. SUBMITTER RECOMMENDED THE MAGNETO DRIVE COUPLING BE MILLED FROM A SOLID PIECE OF HIGH GRADE ALUMINUM AND ALL EDGES BE RADIUSED TO PREVENT CRACKING. | | | | | | | | |
| 7230 | 50046 | BELL | ALLSN | | | CARBON SEAL | WORN | 358 | 4/21/98 |
| HEEA | 45173 | 206L1 | 250C28B | | 23033191 | 23004513 | ENG COMP | | HEEA0014005 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL HOUSING TANGS. INSTALLED A NEW SEAL. | | | | | | | | | |
| 7230 | 2764F | BELL | ALLSN | | | CARBON SEAL | WORN | 368 | 4/21/98 |
| HEEA | 45279 | 206L1 | 250C28B | | 23033191 | 23004513 | ENG COMP | | HEEA0014008 |
| ENGINE REMOVED DUE TO COMPRESSOR HIGH TIME IMPELLER. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL TANGS AND TANG SLOTS. INSTALLED A NEW SEAL. | | | | | | | | | |
| 7230 | 2770Y | BELL | ALLSN | | | GEAR | WORN | 630 | 4/21/98 |
| HEEA | 45291 | 206L1 | 250C28B | | 23033191 | 23056634 | SPUR ADAPTER | | HEEA0014009 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. INSPECTION OF COMPRESSOR PARTS REVEALED: STEP WEAR BEYOND SERVICEABLE LIMITS ON SPUR GEARSHAFT AFT SPLINES (FAILED NO-GO GAUGE) INSTALLED A NEW SPUR GEAR. | | | | | | | | | |
| 7230 | 2772A | BELL | ALLSN | | | CARBON SEAL | WORN | 352 | 4/21/98 |
| HEEA | 45311 | 206L1 | 250C28B | | 23033191 | 23004513 | ENG COMP | | HEEA0014006 |
| ENGINE REMOVED DUE TO CRACKED SCROLL. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL TANGS AND TANG SLOTS. INSTALLED A NEW SEAL. | | | | | | | | | |
| 7230 | 27766 | BELL | ALLSN | | | GEARSHAFT | STEPWEAR | 224 | 5/1/94 |
| HEEA | 45312 | 206L1 | 250C28B | | 23033191 | 23008090 | SPUR ADAPTER | | HEEA942141 |
| ENGINE REMOVED DUE TO LOW POWER. UPON INSPECTION OF COMPRESSOR PARTS NOTED STEP WEAR BEYOND LIMITS ON SPUR ADAPTER GEARSHAFT FORWARD AND AFT SPLINES. INSTALLED NEW SPUR ADAPTER GEARSHAFT. | | | | | | | | | |
| 7230 | 8590X | BELL | ALLSN | | | GEARSHAFT | STEP WEAR | 817 | 4/28/94 |
| HEEA | 51494 | 206L3 | 250C30P | | 23033193 | 23008090 | SPUR ADAPTER | | HEEA942140 |
| ENGINE REMOVED DUE TO HIGH CYCLED WHEELS. UPON INSPECTION OF COMPRESSOR PARTS NOTED STEP WEAR BEYOND LIMITS ON SPUR ADAPTER GEARSHAFT AFT SPLINES. INSTALLED NEW SPUR ADAPTER GEARSHAFT. | | | | | | | | | |
| 7230 | 8592X | BELL | ALLSN | | | CARBON SEAL | WORN | 928 | 4/21/98 |
| HEEA | 51508 | 206L3 | 250C30P | | 23051643 | 23004513 | ENG COMP | | HEEA0014007 |
| ENGINE REMOVED DUE TO CRACKED SCROLL. INSPECTION OF COMPRESSOR PARTS REVEALED: WORN BEYOND SERVICEABLE LIMITS ON SEAL TANGS AND TANG SLOTS. INSTALLED A NEW SEAL. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 7250 | 49573 | BELL | ALLSN | | | BEARING | FAILED | 921 | 3/30/98 |
| | 1665 | 206B | 250C20B | | | A6871505 | TURBINE NR 5 | | 98ZZZX1682 |
| AFTER A NORMAL FLIGHT (EXTERNAL LOAD) AND SHUT-DOWN, THE PILOT REPORTED AN ABNORMAL NOISE WHILE TURNING ROTOR BACKWARDS TO TIE-DOWN POSITION. UPON REMOVAL OF THE TURBINE MODULE, THE FORWARD HALF OF THE NR 5 BEARING INNER CAGE FELL OUT. (THIS IS A 1-PIECE UNIT, NOT 2) THIS BEARING IS THE SUBJECT OF AD 96-19-01. THERE HAD BEEN NO PREVIOUS SIGNS OF DISTRESS, I.E., CHIP LIGHTS, ETC. ENGINE OIL FILTER REMAINS CLEAN AT REMOVAL OF TURBINE. SUSPECT THAT BEARING FAILED AFTER SHUT DOWN IN THAT AT OPERATIONAL SPEED NEAR 60K RPM, MAJOR TURBINE DAMAGE WOULD HAVE OCCURRED IN MILLI-SECONDS. REPLACED WITH OEM BEARING. | | | | | | | | | |
| 7250 | 104PH | BELL | ALLSN | | | COUPLING | WORN | 697 | 4/21/98 |
| HEEA | 3622 | 206B3 | 250C20B | | 6898735 | 6898977 | ENGINE N1 | | HEEA0014002 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. UPON INSPECTION OF TURBINE PARTS NOTED: N1 COUPLING FAILED NO-GO GAUGE. INSTALLED A NEW N1 COUPLING. | | | | | | | | | |
| 7250 | 27766 | BELL | ALLSN | | | COUPLING | STEPWEAR | 320 | 5/1/94 |
| HEEA | 45312 | 206L1 | 250C28B | | 23033185 | 23032345 | N1 | | HEEA942142 |
| ENGINE REMOVED DUE TO LOW POWER. UPON INSPECTION OF TURBINE PARTS NOTED STEP WEAR BEYOND LIMITS ON N1 COUPLING SPLINES. INSTALLED NEW N1 COUPLING. | | | | | | | | | |
| 7250 | 5737T | BELL | ALLSN | | | WHEEL | SULFIDATION | 1489 | 4/25/94 |
| HEEA | 45454 | 206L1 | 250C28B | | 23031899 | 6895801 | 1ST STSGE | | HEEA942143 |
| ENGINE REMOVED DUE TO TURBINE OVERHAUL. UPON INSPECTION OF TURBINE PARTS NOTED SULFIDATION ON 1ST STAGE WHEEL BLADES. | | | | | | | | | |
| 7250 | 2250U | BELL | ALLSN | | | WHEEL | SULFIDATION | 820 | 5/18/94 |
| HEEA | 45754 | 206L1 | 250C28B | | 23033185 | 6895801 | 1ST STAGE | | HEEA942240 |
| ENGINE WAS REMOVED DUE TO WHINING AT ALL POWER SETTINGS. UPON INSPECTION OF TURBINE PARTS NOTED SULFICATION ON 1ST STAGE WHEEL BLADES. PART SCRAPPED. | | | | | | | | | |
| 7261 | 2125M | BELL | ALLSN | | | ELEMENT | FAILED | | 5/23/94 |
| HEEA | 45649 | 206L1 | 250C30 | | | 03808808 | ENG OIL | | HEEA942237 |
| BYPASS BUTTON POPPED. | | | | | | | | | |
| 7261 | 108W | BELL | ALLSN | | | TUBE | CHAFED | 2100 | 3/12/98 |
| | 52034 | 206L4 | 250C30P | | | 23058110A | SCAVENGE OIL | | 98ZZZX1701 |
| ***** | WHILE REMOVING RENTAL ENGINE AND TRANSFERRING HARD LINE P/N 23058110-A FROM RENTAL ENGINE TO ORIGINAL ENGINE, SEVERE CHAFING NOTED UNDER ADEL CLAMP. THIS IS SCAVENGE OIL LINE FROM BOTTOM OF COMPRESSOR TO THE N1 SIDE OF GEARBOX. ABRASIVE DUST AND AIRBORNE DIRT CREEPS IN BETWEEN HARD RUBBER ADEL CLAMP AND OIL LINE AND CHAFES OR WEARS OIL LINE TO THE POINT OF FAILURE. THE NEED EXISTS FOR CLAMPING DEVICES THAT WOULD ELIMINATE THIS CHAFING CONDITION. IN THE MEANTIME, INSPECTION UNDER CLAMPED AREAS IS PRUDENT TO AVOID AN UNSUSPECTED FAILURE. | | | | | | | | |
| 7261 | 230UN | BELL | | | | SHAFT SEAL | LEAK | 524 | 4/29/94 |
| HEEA | 23009 | 230 | | | | 6854424 | NR 2 ENG | | HEEA942146 |
| NR2 ENGINE HAS OIL LEAK. REMOVED AND REPLACED GARLOCK SEAL. | | | | | | | | | |
| 7261 | 407MM | BELL | | | | FILTER ELEMENT | CLOGGED | | 4/29/98 |
| HEEA | 53060 | 407 | | | | 23063144 | ENG OIL | | HEEA0014047 |
| ON DAILY INSPECTION FOUND OIL FILTER BYPASS BUTTON POPPED. REPLACED WITH SERVICEABLE FILTER. | | | | | | | | | |
| 7250 | 205BB | BOLKMS | ALLSN | | | WHEEL | SULFIDATION | 1422 | 5/4/94 |
| HEEA | S58 | BO105C | 250C20B | | 6898735 | 6886407 | 1ST STAGE | | HEEA942239 |
| ENGINE REMOVED DUE TO HIGH CYCLED WHEELS. UPON INSPECTION OF TURBINE PARTS NOTED SULFIDATION ON 1ST STAGE WHEEL BLADES. PART SCRAPPED. | | | | | | | | | |
| 7250 | 131AE | BOLKMS | ALLSN | | | NOZZLE SHIELD | CRACKED | 665 | 4/21/98 |
| HEEA | S787 | BO105S | 250C20B | | 6898735 | 6890040 | NR 1 | | HEEA0013994 |
| ENGINE REMOVED DUE TO TURBINE CYCLES. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD INNER BAND AS MARKED AND CRACK AT POSITIONING LUGS AS MARKED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|---------------------------|-------------------------------|-------------|----------------------------|
| 7250 HEEA | 133AE S800 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | NOZZLE SHIELD 23062750 | CRACKED NR1 | 753 | 4/21/98 HEEA0014003 |
| ENGINE REMOVED DUE TO 3500 HOUR TURBINE OVERHAUL. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD DOME AREA ABOUT 45% AROUND. | | | | | | | | | |
| 7250 HEEA | 911EB S812 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | TURBINE WHEEL 6898782 | PITTED 2ND STAGE | | 4/21/98 HEEA0014001 |
| RECEIVING INSPECTION REVEALED: PITS BEYOND SERVICEABLE LIMITS ON NR2 WHEEL BLENDED AREA E (AFT) AS MARKED. NOTE: BLENDING OF THESE PITS WOULD EXCEED OVERHAUL LIMITS OF .050 DEEP. INSTALLED A NEW NR2 WHEEL. | | | | | | | | | |
| 7250 HEEA | 8199J S826 | BOLKMS BO105S | ALLSN 250C20B | | 23038241 | TURBINE WHEEL 6886407 | DEFECTIVE 1ST STAGE | 1738 | 4/20/98 HEEA0013981 |
| ENGINE REMOVED DUE TO TURBINE 1750 HOUR INSPECTION. UPON INSPECTION OF TURBINE PARTS NOTED: CATASTROPHIC SULFIDATION ON ALL NR1 WHEEL BLADES. SCRAPPED NR1 WHEEL AND REPLACED WITH SERVICEABLE PART. | | | | | | | | | |
| 7250 HEEA | 8199J S826 | BOLKMS BO105S | ALLSN 250C20B | | 23038241 | TURBINE WHEEL 23001967 | DEFECTIVE 3RD STAGE | 1738 | 4/20/98 HEEA0013980 |
| ENGINE REMOVED DUE TO TURBINE 1750 HOUR INSPECTION. UPON INSPECTION OF TURBINE PARTS NOTED: SEVERE SULFIDATION ON ALL NR3 WHEEL BLADES. SCRAPPED NR3 WHEEL AND REPLACED WITH SERVICEABLE PART. | | | | | | | | | |
| 7250 HEEA | 7136J S830 | BOLKMS BO105S | ALLSN 250C20B | | 6898735 | COUPLING 6898977 | STEPWEAR SPLINES | 726 | 5/10/94 HEEA942241 |
| ENGINE REMOVED DUE TO LOW POWER. UPON INSPECTION OF TURBINE PARTS NOTED THE FOLLOWING: STEP WEAR IN EXCESS OF THE .001" OPERATION AND MAINTENANCE MANUAL LIMITS ON TURBINE TO COMPRESSOR COUPLING INTERNAL SPLINES. INSTALLED A NEW COUPLING. | | | | | | | | | |
| 7260 HEEA | 131AE S787 | BOLKMS BO105S | ALLSN 250C20B | | 6894171 | TUBE ASSY 6876925 | WORN ENG GR BOX | | 4/21/98 HEEA0014011 |
| ENGINE REMOVED DUE TO METAL. INSPECTION OF GEARBOX PARTS REVEALED: TUBE ASSY. FAILED DIMENSIONAL CHECK PER CEB1307. INSTALLED A NEW TUBE. | | | | | | | | | |
| 7260 HEEA | 8199J S826 | BOLKMS BO105S | ALLSN 250C20B | | 6894171 | TUBE ASSY 6876925A | WORN ENG GR BOX | 1719 | 4/21/98 HEEA0014010 |
| ENGINE REMOVED DUE TO METAL. INSPECTION OF GEARBOX PARTS REVEALED: TUBE ASSY. FAILED DIMENSIONAL CHECK PER CEB1307. INSTALLED A NEW TUBE. | | | | | | | | | |
| 7321 HEEA | 352TT S59 | BOLKMS BO105S | ALLSN 250C20B | | | FUEL CONTROL 104900A5 | FAULTY ENGINE | | 1/13/94 HEEA942219 |
| FUE CONTROL INTERMITTENT-STAGNATION IN ACCELERATION FROM IDLE TO 70% N1 AND ABOVE. | | | | | | | | | |
| 7320 BAQA | 967LS 7067 | BOLKMS BK117A3 | LYC LTS101650B1 | | AVP1 | ACTUATOR 430110212 | FAILED FLOW FENCE | 181 | 4/16/98 98ZZZX1684 |
| INTERNAL BREAKDOWN OF AIR FLOW MODULATOR (FLOW FENCE ACTUATOR) CAUSED THE OCCURRENCE OF COMPRESSOR STALLS DURING APPROACH TO LANDING. | | | | | | | | | |
| 7322 | 7201Q 17260501 | CESSNA 172L | LYC O320E2D | | FACET MA4SPA | CARBURETOR 105217 | WORN FUEL INLET | 3149 548 | 4/6/98 98ZZZX1655 |
| FUEL INLET FITTING HAD STRIPED THREADS OUT OF CARBURETOR HOUSING AND LEAKING FUEL. INSTALLED REBUILT PART. | | | | | | | | | |
| 8530 | 9477L 17276562 | CESSNA 172P | LYC O320D2J | | | VALVE GUIDE | DEFECTIVE NR 3 CYL EXH VLV | | 4/9/98 1400 98ZZZX1675 |
| ON TAKEOFF, A MOMENTARY ENGINE ROUGHNESS PROMPTED THE PILOT TO ABORT TAKEOFF. THE AIRCRAFT EXCEEDED RUNWAY LENGTH AND STRUCK AN ANTENNA. INSPECTION OF THE ENGINE REVEALED A BUILD-UP OF CARBON IN THE NR 3 EXHAUST VALVE GUIDE. NOTE: ALL EXHAUST VALVE GUIDES WERE REAMED APPROXIMATELY 650 HRS PRIOR TO INCIDENT. AFTER INCIDENT, ENGINE RUN-UP WAS NORMAL. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|--------------------|----------------------|-------------------|--------------------|------------------------|---|--------------------------|-------------|---------------------------|
| 7322 | 1331S 18264895 | CESSNA 182P | CONT O470S | | FACET MA45 | CARBURETOR 1048931 | WORN MIX LEVER | | 11/5/97 97ZZZX5128 |
| INSPECTION OF ENGINE AFTER EMERGENCY LANDING FOUND WHEN MIXTURE WAS FULL RICH, MIXTURE LEVER ON CARBURETOR COULD BE PUSHED TO FULL LEAN WHILE CONTROL CABLE STAYED. CABLE ATTACH BOLT WAS NOT WORN AT ALL, BUT CONTROL LEVER DID HAVE A GROOVE WORN INTO IT ALLOWING LEVER TO MOVE. THE ORIGINAL LOG BOOKS WERE LOST IN 1984. NO LOG BOOK ENTRY SINCE THEN TO INDICATE REPAIR OR OVERHAUL OF CARBURETOR. TOTAL TIME OF AIRCRAFT AND ENGINE, 1,809.1 HOURS. IT IS UNKNOWN IF ENGINE WAS EVER OVERHAULED. | | | | | | | | | |
| 8550 | 3341U 18254741 | CESSNA 182F | CONT O470R | | | T-FITTING AN9171D | CRACKED TURBO LT SIDE | | 4/1/98 98ZZZX1660 |
| INSPECTION FOR AN OIL LEAK FOUND THE T-FITTING THAT FEEDS OIL PRESSURE TO BOTH TURBOS WAS CRACKED. THE FITTING IS LOCATED JUST AFT OF THE LEFT TURBO. IF THE LEAK HAD GONE UNNOTICED, THERE IS A SUBSTANTIAL POSSIBILITY OF AN ENGINE FIRE. RECOMMEND USING BRASS OR STEEL FITTING NEAR TURBOCHARGERS INSTEAD OF ORIGINAL ALUMINUM ONES CALLED OUT FOR IN RAJAY TURBO CONVERSION. | | | | | | | | | |
| 8520 | 756QP U20604274 | CESSNA U206G | CONT IO520F | | | CRANKCASE | CRACKED NR 6 CYL STUD | 580 | 4/14/98 98ZZZX1670 |
| THE CRANKCASE SPLIT FROM NR 6 CYLINDER HOLE TO OIL FILLER HOLE ON TOWARD TO THE FRONT OF THE CASE. THIS OCCURRED IN CONJUNCTION WITH THE CYLINDER MOUNTING STUD IN THIS IMMEIDATE AREA FAILING. THE CIRCUMSTANCES UNDER WHICH IT OCCURED WERE 'NORMAL OPERATION'. SUSPECT CAUSE - OVERTORQUEING OF SAID CYLINDER STUD BOLT. | | | | | | | | | |
| 7414 | 51699 416 | ENSTRM F28C | LYC HIO360E1AD | | | POINTS D4LN2021 10382585 | FAILED RT MAG | | 7/8/94 1345 94ZZZX4574 |
| AIRCRAFT HAD PARTIAL POWER LOSS WITH REDUCTION OF POWER. PILOT FELT ROUGHNESS AND ENTERED AUTOROTATION. OFF-AIRPORT LANDING OKAY. ENGINE INSPECTION REVEALED RT SET OF MAG POINTS CLOSED SUFFICIENTLY ENOUGH TO CAUSE RT SIDE MAG POWER LOSS. INSTALLED NEW SET OF POINTS, P/N 10-382585-OP. OP CHECK OKAY. | | | | | | | | | |
| 7414 | 59829 317652081 | PIPER PA31350 | LYC TIO540J2BD | | ELECTROSYS | MAGNETO | FAILED DISTRIBUT GEAR | 1602 | 11/25/97 97ZZZX5130 |
| AFTER DEPARTURE AND CLIMBING THROUGH 1,200 FEET AGL, PILOT REPORTED THE LEFT ENGINE POPPED TWICE AND SHUT DOWN. UPON INSPECTION, FOUND THE MAGNETO DISTRIBUTOR DRIVE GEARS WERE STRIPPED. ALSO NOTED WAS THE BUSHING IN THE DISTRIBUTOR WAS WORN OUT. | | | | | | | | | |
| 7414 YECR | 59829 317652081 | PIPER PA31350 | LYC TIO540J2BD | | ELECTROSYS D6LN3200 | DISTRIBUTOR GEAR 10682016 | CRACKED MAGNETO | 1091 142 | 12/31/97 98ZZZX1664 |
| MAGNETO WAS INSTALLED ON LEFT ENGINE 11-24-97, AND WAS REMOVED 12-31-97 DUE TO CRACKED, MISSING TOOTH. PREVIOUS MAGNETO HAD SUFFERED FAILURES OF BOTH DIST GEARS. SUSPECT TORSIONAL VIBRATION IN ENGINE. | | | | | | | | | |
| 7414 YECR | 59829 317652081 | PIPER PA31350 | LYC TIO540J2BD | | ELECTROSYS D6LN2230 | DISTRIBUTOR GEAR 10682016 | CRACKED MAGNETO | 1601 | 11/24/97 98ZZZX1665 |
| 11-24-97, MAGNETO WAS REMOVED FROM LEFT ENGINE OF N NR 59829 DUE TO FAILED DISTRIBUTOR GEAR TEETH. MAGNETO HAD 1,601.16 HOURS SINCE OVERHAUL BY ELECTROSYSTEMS, INC., HOWEVER, GEARS MAY NOT HAVE BEEN NEW AT MAGNETO OVERHAUL. | | | | | | | | | |
| 7230 HEEA | 792CH 760193 | SKRSKY S76A | ALLSN 250C30S | | | SPLINE ADAPTER 23051643 230052711 | MIS MFG ENGINE | | 4/30/98 HEEA0014092 |
| RECEIVING INSPECTION REVEALED: O.D. MEASURED (.9853) .0002 UNDER SPECS ON SPLINE ADAPTER O.D. INSTALLED A NEW SPLINE ADAPTER. | | | | | | | | | |
| 7250 HEEA | 5426U 760167 | SKRSKY S76A | ALLSN 250C30S | | | NOZZLE SHIELD 23035128 23062752 | CRACKED NR 1 | 677 | 4/21/98 HEEA0013995 |
| ENGINE REMOVED DUE TO NR1 AND NR2 WHEEL CYCLES. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD OUTER BAND. | | | | | | | | | |
| 7250 HEEA | 5128 760181 | SKRSKY S76A | ALLSN 250C30S | | | NOZZLE SHIELD 23035128 6892824 | CRACKED NR 1 | 615 | 4/22/98 HEEA0014025 |
| ENGINE REMOVED DUE TO TURBINE CYCLES. UPON INSPECTION OF TURBINE PARTS NOTED: CRACKED BEYOND SERVICEABLE LIMITS ON NR1 NOZZLE SHIELD DOME AS MARKED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 7322 | 706AE | SKRSKY | | | | FUEL CONTROL | MALFUNCTIONED | | 4/29/98 |
| HEEA | 760275 | S76A | | | | 25490925 | ENGINE | | HEEA0014051 |
| FUEL CONTROL MALFUNCTION. WILL NOT TOP. DROOPS @ 90% TORQUE. UNIT HAS EXPERIENCED STARTING PROBLEMS | | | | | | | | | |
| 7200 | 914ET | UROCOP | PWA | | | ENGINE | MALFUNCTIONED | 178 | 3/29/98 |
| HDNA | | EC135P1 | PW206B | | | | NR 1 | | 98ZZZX1699 |
| TWO MINUTES AFTER TAKEOFF, POWER DECREASED TO 20 - 40 PERCENT OF NORMAL ON NR 1 ENGINE. RETURNED FOR PRECAUTIONARY LANDING. ENGINE APPEARED TO FUNCTION NORMALLY BELOW 50 PERCENT TORQUE, ABOVE 50 PERCENT, TORQUE WOULD DECREASE. NO FURTHER INCIDENT OCCURRED. AIRCRAFT SHUT DOWN. ELECTRICAL CONNECTIONS CHECKED. OPERATIONAL CHECK FLIGHT PERFORMED AND RETURNED TO SERVICE. | | | | | | | | | |

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - ENGINES)

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|--------------------------|-----------|----------------------------|
| 3425 HEEA | 866MP 5089 | AEROSP AS355F1 | | | KA51A | SYNCHRO 071105304 | DEFECTIVE COCKPIT HSI | | 4/9/94 HEEA942216 |
| HSI 20 DEGREES - 100 DEGREES OFF. | | | | | | | | | |
| 3452 HEEA | 5785Y 5105 | AEROSP AS355F1 | | | KT76 | TRANSPONDER 066106200 | INOP COCKPIT | | 5/7/94 HEEA942178 |
| TRANSPONDER PUTS OUT NO SIGNAL. TROUBLESHOT AND REPLACED TRANSISTOR Q415, CAVITY OSCILLATOR V101 AND ADJUSTED 9 VOLT POWER SUPPLY. REPAIRED PROBLEM. | | | | | | | | | |
| 3425 HEEA | 789DS BB478 | BEECH 200BEECH | | | | FLIGHT DIRECTOR 4018369902 | FAILED COCKPIT | | 4/20/98 HEEA0013989 |
| FLT DIR INOPERATIVE. | | | | | | | | | |
| 3441 HEEA | 500PH BL29 | BEECH 200BEECH | | | | PROCESSOR UNIT 6222898012 | FAILED COCKPIT | | 5/1/98 HEEA0014101 |
| RNAV PROCESSOR UNIT HAS SOME SEGMENTS THAT ARE INOPERATIVE. | | | | | | | | | |
| 3418 RT2R ***** | 163SP TE872 | BEECH E55 | | | | LIFT DETECTOR 1513 | SHORTED SWITCH | 219 | 11/21/97 97ZZZX5114 |
| AIRCRAFT WAS ON RAMP AFTER LANDING IN WET SNOW. WITH ADDITIONAL SNOW ACCUMULATING ON THE AIRCRAFT, THE STALL WARNING HORN BEGAN TO SOUND. PILOT SILENCED HORN WITH CIRCUIT BREAKER AND ADVISED MAINTENANCE. LIFT DETECTOR WAS FOUND SHORTED INTERNALLY. AFTER EXTERNAL HEATING OF THE LIFT DETECTOR TO REMOVE MOISTURE, FUNCTION CHECKS WERE NORMAL. SUBMITTER RECOMMENDS MANUFACTURER USE ENVIRONMENTALLY SEALED MICROSWITCH IN THE LIFT DETECTOR ASSEMBLY TO AVOID FALSE STALL INDICATIONS. | | | | | | | | | |
| 3454 | 216HA TH733 | BEECH 58 | | | COLLINS | RECEIVER 6222080011 | BURNED COCKPIT NAV | 10186 | 3/13/98 98ZZZX1658 |
| AIRCRAFT DEPARTED RIC. EN ROUTE, CREW NOTED BURNED ODOR AND THE NAV UNIT EMITTED SMOKE (A WHISP). CREW PULLED THE CIRCUIT BREAKER OF THE AFFECTED UNIT AND RETURNED TO RIC. | | | | | | | | | |
| 2312 HEEA | 2272V 3621 | BELL 206B | | | | TRANSCIEVER 064105430 | MALFUNCTION COCKPIT | | 4/14/94 HEEA942171 |
| SCRATCHY RECEPTION ON 123:00. DISPLAY GOING OUT. VERIFIED FAULTY DISPLAY; BUT NO RECEPTION PROBLEM. REPLACED DS901 DISPLAY AND REPAIRED. BENCH CHECK GOOD. | | | | | | | | | |
| 2312 HEEA | 6251X 51552 | BELL 206L3 | | | KX155 | RECEIVER 069102435 | FAILED NAV/COMM | | 4/22/98 HEEA0014013 |
| NAV COMM RECEIVER NO DISPLAY. | | | | | | | | | |
| 2312 HEEA | 6160Z 51610 | BELL 206L3 | | | | TRANSCIEVER 064105430 | DEFECTIVE COCKPIT | | 4/29/94 HEEA942170 |
| HIGH NOISE WHEN KEYING MIKE FOR FIRST 15 MINUTES OF OPERATION, THEN NORMAL. FOUND SOME DISPLAY SEGMENTS INOPERATIVE. REPLACED DISPLAY DS901. REPAIRED AND ADJUSTED SQUELCH AND SIDE TONE. BENCH CHECK GOOD. | | | | | | | | | |
| 2330 HEEA | 206LS 51070 | BELL 206L3 | | | | AUDIO PANEL 066105552 | FAILED COCKPIT | | 4/22/98 HEEA0014017 |
| PA CHANNEL INOPERATIVE AND DUAL SINGLE SWITCH LOOSE. | | | | | | | | | |
| 2562 HEEA | 513EH 45421 | BELL 206L1 | | | NARCO | ELT ELT910 | FAILED COCKPIT | | 5/1/98 HEEA0014111 |
| ELT UNIT FOUND IN ON POSITION FOR UNKNOWN TIME. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------|-----------|----------------------------|
| 2562 HEEA | 6610E 51424 | BELL 206L3 | | | NARCO | ELT ELT10 | DEFECTIVE COCKPIT | | 4/29/98 HEEA0014086 |
| ELT RESET BUTTON WILL NOT SPRING BACK. | | | | | | | | | |
| 3421 HEEA | 11027 45411 | BELL 206L1 | | | | ROTOR ASSY 2360041905 | DEFECTIVE INDICATOR | | 5/1/98 HEEA0014110 |
| ROTOR ASSY BEARINGS ARE BAD. | | | | | | | | | |
| 3422 HEEA | 4180F 51469 | BELL 206L3 | | | | GYRO 102005403 | DEFECTIVE COCKPIT | | 2/26/94 HEEA942218 |
| HORIZ GYRO SLOW TO ERECT, REPORTED PRECESSING. | | | | | | | | | |
| 3423 HEEA | 22425 45743 | BELL 206L1 | | | | COMPASS C2300DL4B | LEAKING COCKPIT | | 4/22/98 HEEA0014029 |
| COMPASS LEAKING. | | | | | | | | | |
| 3444 HEEA | 8594X 51531 | BELL 206L3 | | | | INDICATOR 066305401 | STICKS COCKPIT | | 4/25/94 HEEA942180 |
| NEEDLE STICKS AT 500 FEET. LOOSE WASHERS INSIDE OF UNIT. TROUBLESHOT AND REMOVED LOOSE WASHERS FROM INSIDE OF UNIT AND REPLACED BEZEL ASSEMBLY. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 HEEA | 3181J 3771 | BELL 206B | | | | TRANSPONDER 066106200 | KNOB BROKEN COCKPIT | | 5/14/94 HEEA942215 |
| BROKEN KNOB. REPLACED KNOB AND ALSO REPLACED DETERIORATED RESISTOR R477. REPAIRED PROBLEM. | | | | | | | | | |
| 3452 HEEA | 3181Y 3772 | BELL 206B3 | | | | TRANSPONDER 066106200 | FAILED COCKPIT | | 4/29/98 HEEA0014057 |
| NUMBERS ON THE DIAL, DO NOT MATCH DECODER NUMBER TRANSMITTING. FOUND UNIT SHOWING FALSE PULSES. CLEANED WAFER SWITCHES. REPAIRED. ADJUSTED PULSE WIDTH AND FREQUENCY TO SPECS. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 HEEA | 2759U 45267 | BELL 206L1 | | | | TRANSPONDER 066106200 | INOP COCKPIT | | 4/27/94 HEEA942176 |
| ATC NOT RECEIVING. TROUBLESHOT AND REPLACED V101 OSCILLATOR, R477 RESISTOR AND FACEPLATE. REPAIRED. PERFORMED MOD 6 BY INSTALLING Q415 SPACER. REPAIRED. | | | | | | | | | |
| 3452 HEEA | 2250U 45754 | BELL 206L1 | | | | TRANSPONDER 066106200 | INTERMITTENT COCKPIT | | 3/21/94 HEEA942175 |
| INTERMITTENT OPERATION. TROUBLESHOT AND REPLACED CAVITY OSCILLATOR V101, DIODE CR202, CAPACITORS, C202 AND C204, TRANSISTOR Q201, FUSE F401, MIXER DIODE AND COAX FOR MIXER DIODE AND DETERIORATED RESISTOR R477. REPAIRED PROBLEM. | | | | | | | | | |
| 3452 HEEA | 21497 51518 | BELL 206L3 | | | | TRANSPONDER 066106200 | FAILED COCKPIT | | 4/29/98 HEEA0014053 |
| MODE "C" REPORTED INOPERATIVE BY ATC. PERFORMED PRELIMINARY INSPECTION. FOUND PULSE WIDTH TO BE OUT OF SPECS AND REPLY LIGHT TO CONSTANTLY BLINK. | | | | | | | | | |
| 3457 LS1R | 9907K 2040 | BELL 206B | | | | GPS 0110005400 | FAILED COCKPIT | 1422 | 4/16/98 98ZZZX1685 |
| GPS WILL NOT PICK UP SATELLITE UNIT SENT TO MANUFACTURER FOR REPAIR. CONTROL NR 984-9. | | | | | | | | | |
| 3457 HEEA | | BELL 206L1 | | | | GPS 0110005400 | DEFECTIVE COCKPIT | | 4/29/98 HEEA0014055 |
| GPS NO LONGER NEEDED ON AIRCRAFT. BENCH CHECK REQUIRED. PERFORMED PRELIMINARY INSPECTION. FOUND DIRECT TO BUTTON UNREADABLE. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|---------------------------|------------------------------|-----------|----------------------------|
| 3457 HEEA | 22425 45743 | BELL 206L1 | | | GPS 150 | GPS 0110005400 | FAILED COCKPIT | | 4/29/98 HEEA0014056 |
| GPS TAKES 30 MINUTES TO COME ON. PERFORMED PRELIMINARY INSPECTION. FOUND UNIT TO HAVE UNREADABLE ENTRY AND CRSR BUTTONS. | | | | | | | | | |
| 3455 HEEA | 5736J 31140 | BELL 212 | | | | RECEIVER 066104701 | FAILED COCKPIT ADF | | 4/29/98 HEEA0014058 |
| ADF RECEIVER WEAK RECEIVE AND NOT POINTING CORRECTLY IN ADF MODE. INSPECTED AND FOUND ADF MODE SIGNAL WEAK AND NOT POINTING. TRIED ALIGNING RECEIVER. NO HELP. | | | | | | | | | |
| 3457 HEEA | 2FOR 30888 | BELL 212 | | | SKYNAV5000 | GPS 0845000000 | DEFECTIVE COCKPIT | | 4/23/94 HEEA942185 |
| INTERMITTENTLY DISPLAYS CHARACTERS. | | | | | | | | | |
| 2210 HEEA | 23023 33080 | BELL 412 | | | | TARSYN 2593996333 | FAILED AUTO FLIGHT | | 4/29/98 HEEA0014071 |
| FAILS TEST 6.2 ON SST. COMPASS CARD WILL NOT MOVE. | | | | | | | | | |
| 2210 HEEA | 2148K 36001 | BELL 412 | | | | COMPUTER 7000298901 | FAILED AFCS | | 4/20/98 HEEA0013988 |
| AFCS COMPUTER FAILED. ROLL ACTUATOR HUNTS BOTH DIRECTIONS. | | | | | | | | | |
| 2312 HEEA | 3893L 33006 | BELL 412 | | | | TRANSEIVER 7001840913 | DEFECTIVE COCKPIT DISPLAY | | 4/29/98 HEEA0014087 |
| 50,250,400, AND 1200 LEDS WILL NOT LIGHT. | | | | | | | | | |
| 2312 HEEA | 3893S 33022 | BELL 412 | | | KTR905 | TRANSCIEVER 064100900 | GARBLED COCKPIT | | 2/7/94 HEEA942169 |
| GARBLED. SENT TO ALLIED SIGNAL AVIONICS FOR INSPECTION AND REPAIR. | | | | | | | | | |
| 2312 HEEA | 2258F 33073 | BELL 412 | | | | TRANSCIEVER 7001840913 | MALFUNCTION COCKPIT | | 4/29/98 HEEA0014079 |
| TRANSCIEVER POWER OUT FLUCTUATES WHEN VIBRATED. | | | | | | | | | |
| 2312 HEEA | 23023 33080 | BELL 412 | | | | COMM CONTROL 071121540 | DEFECTIVE COCKPIT | | 4/19/94 HEEA942182 |
| DIGITS TOO DIM IN SUNLIGHT. REPLACED DISPLAY DS901 AND FRONT LENS ON FACEPLATE. ALSO REPLACED TRANSFER SWITCH S102 FOR INTERMITTENT TRANSFER OF FREQUENCY. REPAIRED PROBLEM. | | | | | | | | | |
| 2312 HEEA | 141PH 33197 | BELL 412 | | | | TRANSCIEVER 7001840913 | MALFUNCTION COCKPIT | | 4/29/98 HEEA0014078 |
| TRANSCIEVER POWER OUT FLUCTUATES WHEN VIBRATED. | | | | | | | | | |
| 2312 HEEA | 33008 36004 | BELL 412 | | | | COMM CONTROL 071121540 | DEFECTIVE COCKPIT | | 4/26/94 HEEA942183 |
| CANNOT CHANGE FREQUENCY ON SMALL KNOB. CLEANED KHZ SELECTOR SWITCH S104. ALSO FOUND INTERMITTENT TRANSFER SWITCH S102. REPLACED TRANSFER SWITCH S102. REPAIRED PROBLEM. | | | | | | | | | |
| 2370 HEEA | 22608 33075 | BELL 412 | | | | CVR 9806020023 | FAILED COCKPIT | | 4/29/98 HEEA0014054 |
| CVR CAUSES THE "TEST" LIGHT TO STAY ILLUMINATED CONSTANTLY. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--------------|---|-------------------------|---------------------|-----------------------|----------------------|---------------------------|--------------------------|-----------|----------------------------|
| 2370 HEEA | 2298Z 33077 | BELL 412 | | | | CVR 9806019001 | MALFUNCTION COCKPIT | 3885 | 4/22/98 HEEA0014012 |
| | CVR NEEDS EVALUATION. | | | | | | | | |
| 3120 HEEA | 108X 33115 | BELL 412 | | | | CLOCK 212075514001 | MALFUNCTION COCKPIT | | 4/22/98 HEEA0014031 |
| | CLOCK LOSES TIMES. | | | | | | | | |
| 3414 HEEA | 7128R 36007 | BELL 412 | | | | INDICATOR 412075009105 | DEFECTIVE COCKPIT | | 4/20/98 HEEA0013986 |
| | AIRSPEED IND EXCESSIVE CASE LEAKAGE AND READ OUT OF TOLERANCE. | | | | | | | | |
| 3416 HEEA | 293CA 33005 | BELL 412 | | | | ALTIMETER 5035P2P44 | ERROR COCKPIT ENCODE | | 4/29/98 HEEA0014083 |
| | ENCODING ALT INDICATES 200 FEET LOW OUT OF TOLERANCE. | | | | | | | | |
| 3416 HEEA | 293CA 33005 | BELL 412 | | | | ALTIMETER 5035P2P44 | FAILED COCKPIT ENCODE | | 4/29/98 HEEA0014082 |
| | ENCODER READS OUT OF TOLERANCE AT 10,000 FEET AND ABOVE. | | | | | | | | |
| 3416 HEEA | 2261D 33076 | BELL 412 | | | | ALTIMETER 1003511326 | DEFECTIVE COCKPIT | | 3/3/94 HEEA942217 |
| | ALTIMETER HAS EXCESSIVE FRICTION ERROR. | | | | | | | | |
| 3421 HEEA | 3893N 33010 | BELL 412 | | | | INDICATOR 1113034 | FAILED FLT DIRECTOR | | 5/1/98 HEEA0014108 |
| | FD FLAG NOT RETRACTING WHEN POWER IS ON. | | | | | | | | |
| 3421 HEEA | 108X 33115 | BELL 412 | | | | INDICATOR 1113034 | FAILED COCKPIT | | 5/1/98 HEEA0014109 |
| | ATTITUDE INDICATOR WILL NOT OPERATE IN PITCH. | | | | | | | | |
| 3425 HEEA | 2298Z 33077 | BELL 412 | | | | INDICATOR 1113025 | ERRATIC COCKPIT HSI | | 4/16/94 HEEA942223 |
| | CROSS TRACK DEVIATION POINTER HAS A ERRATIC OPERATION. | | | | | | | | |
| 3425 HEEA | 22347 36005 | BELL 412 | | | | INDICATOR 1113025 | STICKS COCKPIT | | 4/29/98 HEEA0014081 |
| | HSI INDICATOR HEADING SET POINTER STICKS INTERMITTENTLY. | | | | | | | | |
| 3444 HEEA | 108X 33115 | BELL 412 | | | | INDICATOR 7000839904 | STICKS RADAR ALT | | 4/29/98 HEEA0014080 |
| | RADAR ALT NEEDLE STICKS AT 210 FEET. | | | | | | | | |
| 2312 HEEA | 4391S S787 | BOLKMS BO105S | | | KY196 | TRANSCEIVER 064101900 | DEFECTIVE COCKPIT | | 5/9/94 HEEA942211 |
| | TRANSCEIVER WARMS UP AND THEN SHUTS OFF. COULD NOT DUPLICATE PROBLEM. ADJUSTED MOD, SIDETONE AND SQUELCH AND FREQUENCY. BENCH CHECK GOOD. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|---------------------------|--------------------------|-----------|----------------------------|
| 2562 HEEA | 54191 S804 | BOLKMS BO105S | | | NARCO | ELT ELT10 | FAILED BATTERY | | 4/22/98 HEEA0014026 |
| BATTERY INOPERATIVE. TIME SINCE REPAIR 0:00. | | | | | | | | | |
| 3416 HEEA | 54191 S804 | BOLKMS BO105S | | | ACK | ENCODER A30 | FLUCTUATES COCKPIT | | 4/4/94 HEEA942136 |
| ENCODER OUTPUT FLUCTUATES 200 FEET CONTINUOUSLY. | | | | | | | | | |
| 3422 HEEA | 205BB S58 | BOLKMS BO105S | | | | GYRO 060001500 | DEFECTIVE COCKPIT | | 3/3/94 HEEA942209 |
| GYRO WILL NOT BECOME VALID AND HEADING IS UNSTABLE. TIME SINCE REPAIR 175:00. | | | | | | | | | |
| 3422 HEEA | 4391S S787 | BOLKMS BO105S | | | KG102A | GYRO 060001500 | TRIPS BREAKER COCKPIT | | 5/2/94 HEEA942210 |
| GYRO POPS CIRCUIT BREAKER. TIME SINCE REPAIR 0:00. | | | | | | | | | |
| 3452 HEEA | 5368F S718 | BOLKMS BO105CB* | | | | TRANSPONDER 066106200 | INOP COCKPIT | | 4/18/94 HEEA942177 |
| TOWER REPORTED TRANSPONDER WAS NOT WORKING. TROUBLESHOT AND REPLACED V101 (TUBE), R441 (RESISTOR), R429 (RESISTOR). ADJUSTED THE RECEIVER AND TRANSMITTER. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 HEEA | 8197X S808 | BOLKMS BO105S | | | | TRANSPONDER 066106200 | INOP COCKPIT | | 4/11/94 HEEA942174 |
| TRANSCEIVER INOPERATIVE. TROUBLESHOT AND ADJUSTED LOW POWER OUT. ALSO REPLACED DETERIORATED RESISTOR R477. REPAIRED PROBLEM. BENCH CHECK GOOD. | | | | | | | | | |
| 3452 HEEA | 7136J S830 | BOLKMS BO105S | | | | TRANSPONDER 066106200 | BROKEN COCKPIT | | 5/16/94 HEEA942213 |
| TRANSCEIVER FACE COVER BROKEN. REPLACED FACEPLATE ASSY, DETERIORATED RESISTOR R477 AND PHOTOCELL V301. ADJUSTED SIDE LOBE SUPPRESSION. REPAIRED PROBLEM. | | | | | | | | | |
| 2210 HEEA | 911NC 7026 | BOLKMS BK117A3 | | | | SPAS COMPUTER 11788292 | DEFECTIVE COCKPIT | | 1/22/94 HEEA942227 |
| SPAS LIGHT ILLUMINATES AS SOON AS SWITCH IS PUT INTO POSITION - SPAS OPERATES NORMALLY IN FLIGHT. | | | | | | | | | |
| 2312 HEEA | 911TL 7198 | BOLKMS BK117B1 | | | | TRANSCIEVER 064105430 | DEFECTIVE COCKPIT | | 5/4/94 HEEA942212 |
| TRANSCIEVER NO DISPLAY. | | | | | | | | | |
| 3420 HEEA | 134AE 7237 | BOLKMS BK117B2 | | | | INDICATOR 4021541671 | DEFECTIVE COCKPIT | | 4/22/98 HEEA0014032 |
| ARTIFICIAL HORIZ INDICATOR INTERNAL LIGHTS SHORTED. | | | | | | | | | |
| 3457 HEEA | 911TL 7198 | BOLKMS BK117B1 | | | | GPS 0845000000 | FAILED COCKPIT | | 4/20/98 HEEA0013985 |
| INTERMITTENTLY LOSING POWER AND SHUTTING DOWN. NOT AIRCRAFT WIRING. DOES SAME WHEN POWERED UP ON BENCH. FOUND UNIT TO LOCK UP AND CHANGES MODES WITHOUT PRESSING ANY KEYS. | | | | | | | | | |
| 6113 | 7353S 18265144 | CESSNA 182P | | | | BULKHEAD 075263717 | CRACKED SPINNER | 2302 | 11/7/97 97ZZZX5126 |
| FOUND SPINNER BULKHEAD CRACKED AT ATTACHMENT BOLTS. SUBMITTER STATED THIRD BULKHEAD FOUND CRACKED THIS YEAR. OTHER AIRCRAFT RECORDS SHOW PART TIMES AT 1,560 - 1,890 HOURS. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------------|-----------|----------------------------|
| 3414 HEEA | 31217 760229 | SKRSKY S76A | | | | INDICATOR 8502CS20LW | FAILED COCKPIT | | 5/1/98 HEEA0014102 |
| AIRSPEED INDICATOR INDICATES HIGH OUT OF TOLERANCE. | | | | | | | | | |
| 3421 HEEA | 1547D 760077 | SKRSKY S76A | | | | INDICATOR 125780 | PRECESSES COCKPIT ADI | | 5/1/98 HEEA0014107 |
| ADI INDICATOR PRECESSING IN FLIGHT. | | | | | | | | | |
| 3425 HEEA | 1545K 760047 | SKRSKY S76A | | | | INDICATOR 1113025 | INTERMITTENTLY COCKPIT HSI | | 4/15/94 HEEA942225 |
| NAV FLAG AND DEVIATION BAR WORKS INTERMITTENTLY. | | | | | | | | | |
| 3425 HEEA | 1546K 760082 | SKRSKY S76A | | | | INDICATOR 1113025 | NEEDLE STICKS COCKPIT HSI | | 4/23/94 HEEA942224 |
| HEADING NEEDLE STICKS. . | | | | | | | | | |
| 3425 HEEA | 5435V 760158 | SKRSKY S76A | | | | INDICATOR 1113025 | DEFECTIVE COCKPIT HSI | | 3/23/94 HEEA942226 |
| INDICATOR CAUSES SECOND HSI TO BE 180 DEGREES OFF WHEN THIS UNIT IS IN THE COMMAND MODE. TIME SINCE REPAIR 0:00. | | | | | | | | | |
| 3454 HEEA | 3122G 760232 | SKRSKY S76A | | | | RECEIVER 066400700 | MALFUNCTION COCKPIT | | 5/2/94 HEEA942181 |
| #2 NAV RADIO WOULD NOT TEST ON VOR FREQUENCY. INSPECTED FOR CORROSION, ADJUSTED VOR TRACKING, GLIDESCOPE CENTERING, GLIDESCOPE SENSE AND GLIDESCOPE SUPER FLAG. BENCH CHECK GOOD. | | | | | | | | | |
| 3416 HEEA | 350BZ 2653 | SNIAS AS350B | | | | ALTIMETER 5934P1 | ERROR COCKPIT | 349 | 4/21/94 HEEA942155 |
| ALTIMETER READS ERRONEOUSLY. | | | | | | | | | |

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS)

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS

5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327


| ATA | REG. NO | ACFT MAKE | ENG MAKE | PROP MAKE | COMP MFG | PART NAME | PART COND | TT | DIFF. DATE |
|------|-----------|------------|----------|-----------|----------|-------------|-----------|-----|--------------|
| OPER | SERIAL NO | ACFT MODEL | ENG MDL | PROP MDL | COMP MDL | PART NUMBER | PART LOC. | TSO | OPER CONT NO |

(There was no data for this report.)

(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS)



INTERNATIONAL SERVICE DIFFICULTY REPORT



INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|----------------------------|------------------|----------------------------|
| 2421 | | AYRES S2RNORMAL | PWA R1340AN1 | | SKYTRONICS 765ST | ROTOR 761 | SHORTED ALTERNATOR | 148 | 6/28/93 CA930709211 |
| (CAN) ALTERNATOR VIBRATED APART. THRU BOLTS AND END HOUSING SHOWED SIGNS OF BEING LOOSE AND WORN. AS ALL PARTS WERE LOOSE, ROTOR STARTED BANGING INTO STATOR ASSY. CUSTOMER TOLD SUBMITTER THAT THIS WAS THE THIRD OCCURRENCE AT APPROXIMATELY 100 TO 150 HOURS | | | | | | | | | |
| 5610 | | BEECH A100 | PWA PT6A28 | | PPG 5042006931 | WINDSHIELD BA2918 | CRACKED LH | 40 | 11/29/93 CA931208201 |
| (CAN) IN CRUISE WITH W/S HEAT ON WINDSHIELD CRACKED. PART TC: 82. | | | | | | | | | |
| 5753 | | BEECH 100BEECH | PWA PT6A28 | | | SKIN 5016000389 | DEFECTIVE FLAP | 9/25/97 | CA971007009 |
| (CAN) AFTER RECEIVING THIRD SKIN FROM BEECH, ITEM STILL DID NOT CONFORM TO SPECS. BEECH CONTACTED INFORMING THEM ITEM APPEARED TO BE INCORRECTLY STAMPED. IF THE SKIN IS INSTALLED AS RECEIVED WOULD RESULT IN A TWISTED FLAP. BEECH IS CURRENTLY CONDUCTING CONFORMITY CHECK ON REMAINING INVENTORY TO IDENTIFY SOURCE OF THE PROBLEM AND CORRECT IT. AIRCRAFT TT: 15,891 HOURS. | | | | | | | | | |
| 2720 | | BEECH 200BEECH | PWA PT6A41 | | FISHER | REGULATOR 115241791 | FAILED RUDDER BOOST | 1958 | 7/12/93 CA930715601 |
| (CAN) ON SINGLE ENGINE APPROACH WITH STBD. ENGINE AT FLIGHT IDLE AND RUDDER BOOST "ON", THE RUDDER BOOST APPLIED FULL LEFT RUDDER. RUDDER BOOST TURNED "OFF", BUT RUDDER STAYED LOCKED IN FULL LEFT POSITION. BOTH PILOTS NEEDED TO HOLD RUDDER IN NEUTRAL POSITION. AT END OF LANDING ROLL, RUDDER RETURNED TO NORMAL. REGULATOR AND 2 RELIEF VALVES REPLACED. | | | | | | | | | |
| 5740 | | BEECH F33A | CONT IO520B | | | DRAIN | PLUGGED LT/RT WING FTNG | 3584 | 6/23/93 CA930709206 |
| (CAN) LT AND RT WING UPPER ATTACHMENT FITTING DRAIN HOLES PLUGGED CAUSING ACCUMULATION OF WATER WHICH EGRESSED INTO WING ATTACHMENT BOLT BORES. | | | | | | | | | |
| 3233 | | BEECH 95B55B | CONT IO470L | | | MOTOR 9581001719 | OVERHEATED LDG GEAR | 29 | 12/1/93 CA931207019 |
| (CAN) LANDING GEAR SELECTED DOWN, U/C ONLY EXTENDED PART WAY AND AN ELECTRIC SMELL WAS NOTICEABLE. ELECTRIC MOTOR FOUND TURNING SLOWLY AND OVERHEATING ON BENCH CHECK. | | | | | | | | | |
| 7602 | | BEECH 95B55 | CONT IO470L | | | CABLE 5038901021 | BROKEN MIXTURE | 11/4/97 10 | CA971121003 |
| (CAN) SHORTLY AFTER TAKEOFF, THE AIRCRAFT CAPTAIN REPORTED THE RT MIXTURE WAS NOT RESPONDING NORMALLY. AIRCRAFT RETURNED TO DEPARTURE POINT. MAINTENANCE INVESTIGATION FOUND THE MIXTURE CABLE HAD BROKEN AT THE ROD END TO ENGINE. THIS IS THE THIRD FAILURE OF THIS KIND. | | | | | | | | | |
| 7602 | | BEECH 95B55 | CONT IO470L | | | CABLE 5038901021 | BROKE MIXTURE | 10/29/97 52 | CA971121002 |
| (CAN) RT MIXTURE WAS REPORTED AS STICKING, NIL RESPONSE. MAINTENANCE INVESTIGATION FOUND THE MIXTURE CABLE HAD BROKEN AT THE ROD END TO THE ENGINE. THIS IS THE SECOND TYPE OF OCCURRENCE. | | | | | | | | | |
| 7602 | | BEECH 95B55 | CONT IO470L | | | CABLE 5038901021 | BROKE MIXTURE | 10/8/97 1363 | CA971121001 |
| (CAN) THE RT ENGINE FUEL MIXTURE CABLE FAILED ON APPROACH. THIS ACTION RESULTED IN THE RT ENGINE MIXTURE ROLLING BACK TO IDLE CUT-OFF STOPPING THE ENGINE. MAINTENANCE INVESTIGATION REVEALED THE MIXTURE CABLE FAILED AT THE SWAGE ATTACHMENT END TO THE ROD AT THE ENGINE. CABLE REPLACED. | | | | | | | | | |
| 2742 | | BEECH 99 | PWA PT6A28 | | | ACTUATOR 11538011119 | INOPERATIVE HORZ STAB | 10/15/97 3941 | CA971113063 |
| (CAN) HORIZONTAL STABILIZER TRIM ACTUATOR FAILED 1.7 HRS AFTER INSTALLATION. ACTUATOR WAS PREVIOUSLY SENT IN FOR REPAIR OF MAIN TRIM MOTOR AND FAILED IN THE MAIN TRIM MOTOR SIDE AGAIN. INVESTIGATION FOR CAUSE OF THE FAILURE IS CURRENTLY IN PROGRESS. PART TC: 7,318. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|----------------------------|-----------|----------------------------|
| 2742 | | BEECH B99 | PWA PT6A28 | | TALLEY 1136T10023 | ARMATURE 8F353 | OPEN PITCH TRIM ACT | 398 | 7/6/93 CA930722202 |
| (CAN) ARMATURE LEADS "FLYING" AWAY FROM COMMUTATOR, EVEN THOUGH LEADS ARE STRAPPED DOWN. THUS, INTERMITTENT OPERATION OF PITCH TRIM ACTUATOR. | | | | | | | | | |
| 2720 | | CESSNA 150L | | | | CABLE 41749 | FRAYED RUDDER LT | | 10/8/93 CA931018601 |
| (CAN) RUDDER CONTROL CABLES FOUND CORRODED AND FRAYED. RT CABLE P/N 040010750. RT PROBLEM ABOUT 6 INCHES FROM RUDDER END AT PULLEY. LT CABLE PROBLEM AT BOTH ENDS OF CABLE. | | | | | | | | | |
| 5511 | | CESSNA 152 | | | | RIB 53215 | CRACKED HORIZONTAL STAB | 9722 | 6/30/93 CA930719401 |
| (CAN) CRACKING SOUND NOTED ON HORIZONTAL STAB DURING INSPECTION. CRACK FOUND IN LH INBD STAB NOSE RIB & LEADING EDGE WAS LOOSE TO MAIN SKIN. | | | | | | | | | |
| 2435 | | CESSNA 180J | CONT O470K | | | SHAFTGEAR 539568 | CRACKED STARTER ADAPTER | 776 | 6/17/93 CA930712101 |
| (CAN) HARD STARTING SNAG INVESTIGATION. ON REMOVAL OF STARTER ADAPTER, ONE OF THE OUTPUT GEAR TEETH WAS MISSING. THE MISSING TOOTH WAS FOUND IN THE ENGINE OIL SUMP. | | | | | | | | | |
| 7120 | | CESSNA 182J | | | | MOUNT 75161 | CORRODED ENGINE | 3857 | 9/22/93 CA931013127 |
| (CAN) PITTING NOTICED ON ENGINE MOUNT. REMOVAL OF HEAT DEFLECTOR SHROUDS REVEALED SEVERE CORROSION OF ENGINE MOUNT TUBING NEAR EXHAUST COLLECTOR. PITTING MORE THAN HALFWAY THROUGH TUBE WALL. AIRCRAFT PREVIOUSLY COMPLETED 100 HR INSP .6 HRS BEFORE AND DIFFICULTY WAS MISSED. | | | | | | | | | |
| 7810 | | CESSNA 182J | CONT O470R | | | STACK ASSY 7516131 | CORRODED EXHAUST | 3857 | 9/22/93 CA931013126 |
| (CAN) ENGINE REMOVED FOR MOUNT REPAIRS. EXHAUST SYSTEM REMOVED. BOTH LT AND RT COLLECTORS FOUND SEVERELY CORRODED AND BURNED. 100 HR INSP JUST COMPLETED .6 HRS PREVIOUSLY. | | | | | | | | | |
| 2710 | | CESSNA A185F | | | | CABLE 5115113 | CHAFED AILERON STA 72.6 | 3505 | 10/4/93 CA931018604 |
| (CAN) CARRY THROUGH AILERON CONTROL CABLE FOUND BADLY CHAFED AND WITH BROKEN STRANDS ON BOTH LEFT AND RIGHT WINGS AGAINST RUB STRIP P/N 0523233-3. | | | | | | | | | |
| 2750 | | CESSNA A185E | | | | BRACKET 512128 | BROKEN FLAPS STA 65.33 | 9076 | 10/4/93 CA931018301 |
| (CAN) FLAP SYSTEM STIFF. LEFT FLAP PULLEY BRACKET ON LOWER BULKHEAD AT STA 65.33 BROKEN. | | | | | | | | | |
| 2750 | | CESSNA A185E | | | | LEVER 511665 | CRACKED FLAP | 10358 | 10/12/93 CA931103501 |
| (CAN) FLAP LEVER ASSY FOUND CRACKED AND BROKEN IN AREA OF LATCH. LATCH TO RATCHET MECHANISM INOPERATIVE CAUSING FLAPS TO RETRACT SUDDENLY. FLAP HANDLE POSITION HELD MANUALLY BY PILOT ON DESCENT. POSSIBLY CAUSED BY AGE OR EXCESS PRESSURE WHEN FLAPS IN FULL RETRACT. FLAP HANDLE MAY OFTEN BE STEPPED ON AS RT PASSENGER MUST STEP OVER HANDLE TO LT SEAT TO EXIT AIRCRAFT. | | | | | | | | | |
| 7921 | | CESSNA U206 | CONT IO520F | | HARRISON | OIL COOLER 8526732 | CRACKED DIAG BRACE | 50 | 6/30/93 CA930715603 |
| (CAN) OIL COOLER DIAGONAL BRACE FOUND CRACKED MID-WAY BETWEEN ATTACHMENT POINTS. | | | | | | | | | |
| 7921 | | CESSNA U206 | CONT IO520F | MCAULY | HARRISON | OIL COOLER 8526732 | LEAKING ENG OIL | | 7/1/93 CA930715604 |
| (CAN) THIS OIL COOLER SUPPLIED BY WARRANTY. AFTER INSTALLATION AND SHORT TEST FLIGHT, IT DEVELOPED A SERIOUS LEAK. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|----------------------------|-----------|----------------------------|
| 3230 | | CESSNA 210L | CONT IO520L | | | LANDING GEAR | FOLDED LT GEAR | 3806 | 12/23/97 CA980113006 |
| (CAN) AFTER LANDING, THE LT GEAR SLOWLY FOLDED BACK INTO THE RETRACT POSITION. AIRCRAFT SETTLED TO GROUND ON LT STABILIZER CAUSING DAMAGE TO LT STABILIZER AND ELEVATOR. UNDER INVESTIGATION. | | | | | | | | | |
| 3213 | | CESSNA 310I | CONT IO470U | | | TRUSS WELD 841236 | CRACKED MLG RT/LT | 3917 | 7/16/93 CA930727202 |
| (CAN) UPPER AFT WELD ON BOTH RIGHT AND LEFT MLG SHOCK STRUT TRUSS WELDED ASSEMBLIES FOUND CRACKED. THE LAST CHECK IN THIS AREA HAD BEEN CARRIED OUT JUST 70 HRS PREVIOUS WITH NO CRACKS FOUND. LT TRUSS P/N 084120037. | | | | | | | | | |
| 5260 | | CESSNA 310R | CONT IO520MB | MCAULY 3AF32C87 | | STEP SUPPORT 811931 | BROKEN CABIN | | 10/19/93 CA931102301 |
| (CAN) WITH FLOOR REMOVED, THE STEP SUPPORT BRACKET AND SECOND STEP P/N 0811944-1 WERE FOUND CRACKED. POSSIBLY CAUSED BY A LARGE PASSENGER. AIRCRAFT TT: 5,542 HOURS. | | | | | | | | | |
| 5711 | | CESSNA T337B | CONT TSIO360A | | 1422500201 | DOUBLER 14225141 | CRACKED WING FRONT SPAR | | 6/22/93 CA930714101 |
| (CAN) WING SPAR INSPECTED IN ACCORDANCE WITH FAA AD 78-09-05. .25 INCH CRACK FOUND IN RADIUS OF DOUBLER OF FRONT LT SPAR WING ATTACH POINT. | | | | | | | | | |
| 3246 | | CESSNA 441 | | | GOODYEAR 5003064 | WHEEL HALF 5377 | CRACKED MLG | | 10/17/93 CA931102102 |
| (CAN) WHEEL HALF CRACKED BETWEEN BOLT HOLE AND INSIDE SURFACE OF WHEEL ALLOWING AIR TO ESCAPE FROM TUBELESS TIRE. WHEEL HAD BEEN ZYGLOED PREVIOUS TO INSTALLATION AND CRACK WAS NOT DETECTED. WEIGHT ON WHEEL CAUSED CRACK TO OPEN. | | | | | | | | | |
| 3040 | | CESSNA 550 | PWA JT15D4 | | | BLOWER 5773 | SEIZED COCKPIT DEFOG | 2386 | 6/29/93 CA930715110 |
| (CAN) ACRID SMOKE SMELL NOTED BY CREW AND PASSENGER. OXYGEN MASKS USED. NO FIRE NOTED. COCKPIT DEFOG BLOWER FOUND TO BE CAUSE. BLOWER HAD BEEN SELECTED TO HIGH AND BEARING PROBABLY FAILED CAUSING BLOWER TO SEIZE. | | | | | | | | | |
| 5740 | | DHAV DHC2MK1 | PWA R985AN14B | | | WING STRUT C2W113 | CORROSION LOWER FITTING | | 6/2/93 CA930711401 |
| (CAN) LIGHT TO MODERATE STRESS CORROSION AND FRETTING AROUND BOLT HOLES. | | | | | | | | | |
| 5743 | | DHAV DHC3 | | | | STRUT VALC315 | CORROSION LT | 1887 | 11/1/93 CA931103104 |
| (CAN) CORROSION BETWEEN SKINS OF STRUT AND RIVETED FITTINGS AND BETWEEN RIVETED FITTINGS AND LUG FITTINGS STRUT TO FUSELAGE. STRUT WAS A 20,000 HR STRUT. AIRCRAFT TT: 21,848 HOURS. | | | | | | | | | |
| 3250 | | DHAV DHC6300 | PWA PT6A27 | | | CABLE CC6CF12425 | FRAYED NLG STEERING | | 6/28/93 CA930719405 |
| (CAN) NLG STEERING CABLE HAD THREE FRAYED AREAS AT PULLEY POINTS. | | | | | | | | | |
| 5311 | | DHAV DHC6100 | PWA PT6A20 | | | SIDE FRAME C6FSM2528511 | CORRODED LT SIDE | | 7/6/93 CA930715103 |
| (CAN) LT AFT WING PICK-UP AFT END CORRODED ON FUSELAGE. FITTING AND LUG HAS CRACKS. ON REMOVAL, BUSHING HAD NOT BEEN INSTALLED. ACFT TT: 23,236. | | | | | | | | | |
| 5310 | | NOORDN UC64A | | | | FABRIC | TORN FUSELAGE CEILING | 10000 | 6/20/97 CA970709011 |
| (CAN) PILOT NOTED A SLIGHT BUFFETING FOLLOWED BY A SLIGHT ROLL TO THE RIGHT. TEARING AND OIL CANNING SOUND WAS HEARD. ANOTHER AIRCRAFT NOTED THAT THE FABRIC ON UPPER FUSELAGE WAS TORN. REPAIRS CARRIED OUT. AIRCRAFT TT: 9,920 HOURS. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------------|----------------------------|-----------|----------------------------|
| 7820 | | PARTEN P68C | PWA PT6A41 | | PARTEN | MUFFLER 6133134 | CRACKED RT | 188 | 9/27/93 CA931018606 |
| (CAN) MUFFLER FOUND CRACKED AND BROKEN AROUND RT OUTBOARD FLANGE. | | | | | | | | | |
| 2710 | | PIPER PA23250 | LYC IO540C4B5 | | | CABLE 1430004 | CHAFED AILERON | 6731 | 12/22/97 CA980113015 |
| (CAN) AILERON BALANCE CABLE CHAFING ON FLOOR SKIN AND HYDRAULIC LINE CABLE REPLACED, HYDRAULIC LINE RECLAMPED AND FLOOR SKIN MOVED. | | | | | | | | | |
| 2701 | | PIPER PA28140 | | | | CONTROL WHEEL 6855811 | BROKEN PILOTS | 7609 | 6/24/93 CA930713607 |
| (CAN) ON ROLL-OUT AFTER LANDING, PILOT'S CONTROL WHEEL BROKE IN TWO PIECES. BREAK EXTENDED FROM RETAINING PIN HOLE VERTICALLY. AD 69-22-02 HAD BEEN DONE 63 HOURS BEFORE THIS FAILURE. | | | | | | | | | |
| 5730 | | PIPER PA28161 | | | | PAN 6206102 6262 | CRACKED WING WALK | 5019 | 6/21/93 CA930711404 |
| (CAN) CORRUGATED PAN CRACKED ALONG EDGES OF CORRUGATIONS UNDERNEATH WING WALK AREA. FIVE OTHER AC ALSO AFFECTED. FEEDBACK 92-01 REFERS. | | | | | | | | | |
| 5730 | | PIPER PA28161 | LYC O320D3G | | | PAN 6206104 6263 | CRACKED WING WALK AREA | 5019 | 6/21/93 CA930721701 |
| (CAN) CORRUGATED PAN CRACKED ALONG EDGES OF CORRUGATIONS UNDERNEATH WING WALK AREA. FIVE OTHER AIRCRAFT ALSO AFFECTED. FEEDBACK 92-01 REFERS. ACFT TT: 5,969. | | | | | | | | | |
| 8011 | | PIPER PA28236 | LYC O540J3A5 | | PRESTOLITE | STARTER M24222R | FAILED ARMATURE | 449 71 | 10/5/93 CA931015201 |
| (CAN) 71 HOURS AFTER STARTER REPAIR, STARTER DRAGGING. ALL FRONT AND REAR BOLTS OF ARMATURE HOUSING LOOSE. ARMATURE DRAGGED ON WINDINGS. SUSPECT POOR ASSEMBLY. | | | | | | | | | |
| 3233 | | PIPER PA31 | | | | NUT 21151 477676 | CRACKED LT MLG ACTUATOR | 4323 | 6/30/93 CA930713602 |
| (CAN) LEAK AT INBOARD FITTING OF LT MLG ACTUATOR PN REMOVAL, FITTING LOCKNUT FELL APART CORROSION EVIDENT. | | | | | | | | | |
| 5280 | | PIPER PA31350 | | | | HINGE 466522 | CRACKED RT GEAR DOOR | 8915 | 7/2/93 CA930712301 |
| (CAN) CRACK FOUND ON RT GEAR DOOR FORWARD HINGE IN THE AREA SPECIFIED IN PIPER SB 682. HINGE REPLACED. | | | | | | | | | |
| 5520 | | PIPER PA31T | | | | ELEVATOR 55162XS | CRACKED TOP INBD HINGE | 11609 | 12/10/93 CA931217001 |
| (CAN) LEFT HAND ELEVATOR UPPER SKIN CRACKED .50 INCHES AFT OF INBOARD HINGE (STA BL 48.0). SPAR ALSO CRACKING UNDER HINGE P/N 4495502. SB 897A REFERS. | | | | | | | | | |
| 3030 | | PIPER PA34220T | CONT TSIO360KB | | | PITOT HEAD 9639206 9639206 | MALFUNCTION DE ICE | 5236 | 11/19/97 CA971128002 |
| (CAN) PITOT HEAD FREEZES UP IN-FLIGHT RESULTING IN TOTAL LOSS OF AIRSPEED. NEW ELEMENTS INSTALLED AND SAME RESULTS. NOT SUFFICIENT TO MELT ICE IN-FLIGHT. | | | | | | | | | |

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - AIRCRAFT)

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-----------------------------|-----------------------------|--------------|----------------------------|
| 6310 | | AEROSP SA315B | | | 31606330010 | BEARING 31656329223 | DAMAGED CLUTCH | 1 | 5/15/93 CA930722205 |
| (CAN) CLUTCH VIBRATION. | | | | | | | | | |
| 7230 | | AEROSP SA315B | TMECA ARTOUSTE3B | | TMECA IIIB1 | COMPRESSOR 1561 | DAMAGED BLADE L/E | 32 | 6/24/93 CA930722206 |
| (CAN) BLADE LEADING EDGE OF FIRST STAGE COMPRESSOR DAMAGED DUE TO FOD. | | | | | | | | | |
| 6420 | | BELL 204B | | | | CROSSHEAD 204011711001 | DEFECTIVE T/R | | 8/16/97 CA970820003 |
| (CAN) NEW CROSSHEAD HAD PAINT MISSING ON ONE INBOARD TANG. A SMALL RIVET WAS FOUND INSTALLED IN THE CROSSHEAD. | | | | | | | | | |
| 6520 | | BELL 204B | LYC T5311B | | 20404000337 | GEARBOX 244337 | FAILED 42 DEG GR BOX | 4155 1654 | 7/2/93 CA930720301 |
| (CAN) 42 DEGREES GEARBOX FAILED IN HOVER. | | | | | | | | | |
| 6230 | | BELL 206L | | | | LINK LEVER SYS 2613353 | WORN ROTOR SYSTEM | | 9/17/93 CA931018610 |
| (CAN) BEARINGS P/N 206-010-338-001 AND SPACERS P/N 206-010-337-001 FOUND WORN BEYOND LIMITS. | | | | | | | | | |
| 6330 | | BELL 206L | | | | STOP MOUNT ASSY 26336421 | LOOSE MAIN TRANSMISION | | 9/17/93 CA931018609 |
| (CAN) LOOSE STOP MOUNTS CAUSED BY LOSS OF TORQUE ON NAS-1291-7 NUTS. | | | | | | | | | |
| 7170 | | BELL 206L | ALLSN 250C20R2 | | | BELLOWS 118B261 | TORN ENG DRAIN | | 9/17/93 CA931019603 |
| (CAN) RUBBER BELLOWS SWOLLEN AND TORN. | | | | | | | | | |
| 7230 | | BELL 206B | ALLSN 250C20 | | 6853337 | SEAL | LEAKING INLET | 5218 1453 | 2/18/97 CA970311022 |
| (CAN) NR 1 SEAL LEAKING. PART TC: 11,543. | | | | | | | | | |
| 7230 | | BELL 206B | ALLSN 250C20 | | ALLSN | ROTOR 6853337 | PUNCTURED ENG COMPRESSOR | 6672 3216 | 10/4/93 CA931019202 |
| (CAN) HOLE FOUND IN COMPRESSOR ROTOR ASSEMBLY AT 1750 HOUR CASE HALF INSPECTION. PART TC: 9,372. | | | | | | | | | |
| 7712 | | BELL 206L | | | | GAUGE 26751853 | ERROR TORQUE | | 9/19/93 CA931019601 |
| (CAN) TORQUE GAUGE READS 3 PERCENT LOW. | | | | | | | | | |
| 7722 | | BELL 206L | | | | GAUGE 12444412 | ERROR ENG TOT | | 9/19/93 CA931019602 |
| (CAN)TOT GAUGE READS 15 DEGREES CELSIUS HIGH. | | | | | | | | | |
| 7200 | | BELL 212 | PWA PT6T3 | | | ENGINE | FAILED NR 1 | | 8/19/93 CA931013129 |
| (CAN) NR 1 ENGINE HAD LOUD BANG ON TAKEOFF. AIRCRAFT LANDED. ENGINE SENT TO REPAIR AND OVERHAUL. REPORT TO FOLLOW. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------------|--------------|----------------------------|
| 7210 | | BELL 212 | PWA PT6T3 | | | GEAR BOX | FAILED NR1 | | 9/19/93 CA931013123 |
| (CAN) NR 1 GEARBOX FAILED. ENGINE SENT TO P&W FOR DAMAGE ASSESSMENT. | | | | | | | | | |
| 7250 | | BELL 212 | PWA PT6T3 | | 3016700 | COMP TURBNE 313411 | BURNT ENGINE | 9081 2743 | 4/15/93 CA930715602 |
| (CAN) DURING FLIGHT, ENGINE FAILED TO PRODUCE POWER AND OVERTEMPED. INSPECTION REVEALED COMPRESSOR TURBINE WHEEL BURNT AND MATERIAL MISSING. PART TC: 1,879. | | | | | | | | | |
| 7200 | | BOEING 1072 | GE CT58* | | | ENGINE GT58141A | FAILED NR 1 | 2981 | 7/9/93 CA930722101 |
| (CAN) ENGINES WOULD NOT MATCH IN TOPPING. NR 1 ENGINE CHANGED. | | | | | | | | | |
| 7320 | | BOEING 1072 | GE CT581401 | | GE | ACTUATOR FYLC5557 | FAILURE NR 2 ENG | 4596 196 | 8/1/93 CA931013130 |
| (CAN) AFTER REFUELING, AIRCRAFT PILOT WAS UNABLE TO GET RESPONSE FROM NR 2 ENGINE. ENGINE SHUTDOWN MANUALLY. | | | | | | | | | |
| 2550 | | BOLKMS BO105C | ALLSN 250C20B | | | CARGO HOOK 14276 | INTERMITTENT HOOK RELEASE | 51 | 6/14/93 CA930713604 |
| (CAN) HOOK RELEASE INTERMITTENT. AIRCRAFT SYSTEMS CHECK OK. | | | | | | | | | |
| 2550 | | BOLKMS BO105C | ALLSN 250C20B | | | CARGO HOOK 14276 | SHORTED GROUND WIRE | | 6/30/93 CA930715605 |
| (CAN) GROUND WIRE MD5EZON INSULATION MELTED. THIS CAUSED WIRE BUNDLE FROM GROUND LUG TO FIRST CONNECTOR 5MDA TO SHORT OUT. CIRCUIT BREAKER IMD RATED AT 10 AMP DID NOT TRIP. | | | | | | | | | |
| 5302 | | BOLKMS BO105C | ALLSN 250C20B | | BOLKMS 10530101 | SKIN 15325156 | CRACKED RT STA 5500 | 4834 | 9/15/93 CA931102104 |
| (CAN) DURING DAILY INSPECTION A CRACK APPROXIMATELY 2.25 INCHES LONG WAS FOUND ON RT SIDE APPROXIMATELY 14 FEET AFT OF ATTACHMENT FLANGE. AIRCRAFT TT: 6,378 HOURS. | | | | | | | | | |
| 5532 | | BOLKMS BO105CBS | ALLSN 250C20B | | | VERTICAL FIN 15341 | CRACKED UPPER LEFT SIDE | 4380 | 10/2/93 CA931014207 |
| (CAN) CRACK FOUND ON LEFT SIDE OF VERTICAL FIN CRACK SEEMED TO PROPAGATE FROM RIVET HOLE UNDER FISH PLATE, P/N 105-30402-27. | | | | | | | | | |
| 6320 | | BOLKMS BO105CBS | | | 4638001001 | BEARING 46383224 | PEELING LT INPUT | 2171 | 6/16/93 CA930719404 |
| (CAN) BEARING ROLLERS HAVE EXCESSIVE PEELING. INPUT PINION GEAR 4638-302-002 HAS EXCESSIVE PEELING. | | | | | | | | | |
| 7810 | | HILLER UH12E | LYC VO540C2A | | | EXHST MANIFOLD 769618 | CRACKED WELD JOINT | 1866 | 5/2/93 CA930715109 |
| (CAN) CRACK AT WELD JOINT OF EXHAUST MANIFOLD UNDER CARBURETOR HEAT SHROUD. | | | | | | | | | |
| 8530 | | HUGHES 269C | LYC HIO360D1A | | | CYLINDER LW1947 | FAILED ENGINE | 29 | 6/17/93 CA930713601 |
| (CAN) CYLINDERS FAILED. ENGINE REPLACED. | | | | | | | | | |
| 6210 | | HUGHES 369D | ALLSN 250C20B | | | BLADE 369D211516A | CRACKED M/R | 3211 835 | 11/1/93 CA931103105 |
| (CAN) FOLLOWING FLIGHT AND GROUND TRACK AND BALANCE, A LARGE CRACK WAS FOUND ON THE BOTTOM SURFACE OF THE BLADE. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|---------------------------|-----------|----------------------------|
| 6320 | | HUGHES 369D | ALLSN 250C20B | | | CHIP DETECTOR B3148A | CRACKED M/R XMSN | | 8/17/97 CA970904033 |
| (CAN) AREA UNDER 'O' RING OF MAIN TRANSMISSION CHIP DETECTOR HOUSING FOUND CRACKED. SUSPECT OVERTORQUING. | | | | | | | | | |
| 6710 | | SKRSKY S76A | ALLSN 250C30S | | | PBA ACTUATOR 742218 | RESTRICTED FLT CONTROL | | 10/28/93 CA931103103 |
| (CAN) PILOT REPORTED HAVING A RESTRICTED MOVEMENT IN FORWARD CYCLE WHEN GOING THROUGH 80 KNOTS. HYDRAULIC POWER WAS APPLIED UPON RETURN TO BASE AND FREEDOM OF MOVEMENT INSPECTION PERFORMED. A SCREW HOLDING THE CLAMP WHICH HOLDS THE WIRING HARNESS ON THE ACTUATOR WAS FOUND CATCHING A FITTING ON THE FLIGHT CONTROL DECK. | | | | | | | | | |
| 7320 | | SKRSKY S76A | ALLSN 250C30S | | | TUBE B NUT 6893073 | LOOSE NR 2 ENG | | 10/22/93 CA931103102 |
| (CAN) AIRCRAFT LOST POWER ON NR 2 ENGINE. ENGINE HAD INSTABILITY IN POWER RANGE, ALL PNEUMATIC LINES WERE CHECKED FOR LEAKAGE, AIR LEAK WAS FOUND AT "B" NUT OF P/N 6893073 TUBE. | | | | | | | | | |
| 6720 | | SNIAS AS350B | TMECA ARRIEL1A | | 350A33200403 | BEARING 612RSIMT33CA | CORRODED T/R PITCH | 2235 | 8/2/93 CA931019501 |
| (CAN) TAIL ROTOR ASSY FELT ROUGH. INSPECTION REVEALED HEAVY CORROSION AND PRACTICALLY GREASELESS PITCH CONTROL PLATE BEARING AND OUTER RACE. | | | | | | | | | |
| (End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - HELICOPTERS) | | | | | | | | | |

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------------|--------------|----------------------------|
| 7230 | | AEROSP SA315B | TMECA ARTOUSTE3B | | TMECA IIIB1 | COMPRESSOR 1561 | DAMAGED BLADE L/E | 32 | 6/24/93 CA930722206 |
| (CAN) BLADE LEADING EDGE OF FIRST STAGE COMPRESSOR DAMAGED DUE TO FOD. | | | | | | | | | |
| 7320 | | BEECH 200CBEECH | PWA PT6A41 | | | P3 AIR LINE 32779 | CRACKED NR 2 ENGINE | 10/4/93 | CA931013501 |
| (CAN) FOLLOWING NORMAL TAKEOFF WHILE CLIMBING OUT AT CLIMB POWER SETTINGS, THE NR 2 ENGINE DECELERATED TO IDLE SPEED. THE FLIGHT CREW MADE PRECAUTIONARY LANDING WITHOUT MISHAP. MAINTENANCE INVESTIGATION DETERMINED THE CAUSE TO BE A CRACKED P3 AIR LINE THAT SHUTDOWN THE GOVERNOR AND FCU CONTROL METERING SYSTEM. THE ENGINE WAS INSPECTED FOR EVIDENCE OF HIGH FREQUENCY OR ABNORMAL VIBRATIONS - NO EVIDENCE WAS FOUND. A PRECAUTIONARY INSPECTION OF ALL LIKE LINE ON LT AND RT ENGINES WAS CARRIED OUT. | | | | | | | | | |
| 7322 | | BEECH C90 | PWA PT6A21 | | BENDIX 3207049B1 | ELBOW 314214 | MISSING FUEL CONTRL UNIT | 1253 | 6/26/93 CA930712103 |
| (CAN) ON APPLICATION OF POWER FROM LOW IDLE TO TAKEOFF SETTING IN A TOUCH AND GO SHORT FIELD APPROACH, AN ASYMMETRIC POWER SITUATION RESULTED CREATING A DEGRADATION OF AIRCRAFT DIRECTIONAL CONTROL. INVESTIGATION BY MAINTENANCE DETERMINED THE RESTRICTOR IN THE STAINLESS STEEL ELBOW P/N 3014214 CONNECTING THE P3 SENSE LINE TO THE FUEL CONTROL UNIT WAS FOUND NOT INSTALLED BY THE OVERHAUL FACILITY. | | | | | | | | | |
| 7230 | | BELL 206B | ALLSN 250C20 | | | SEAL 6853337 | LEAKING INLET | 5218 1453 | 2/18/97 CA970311022 |
| (CAN) NR 1 SEAL LEAKING. PART TC: 11,543. | | | | | | | | | |
| 7230 | | BELL 206B | ALLSN 250C20 | | ALLSN | ROTOR 6853337 | PUNCTURED ENG COMPRESSOR | 6672 3216 | 10/4/93 CA931019202 |
| (CAN) HOLE FOUND IN COMPRESSOR ROTOR ASSEMBLY AT 1750 HOUR CASE HALF INSPECTION. PART TC: 9,372. | | | | | | | | | |
| 7200 | | BELL 212 | PWA PT6T3 | | | ENGINE | FAILED NR 1 | 8/19/93 | CA931013129 |
| (CAN) NR 1 ENGINE HAD LOUD BANG ON TAKEOFF. AIRCRAFT LANDED. ENGINE SENT TO REPAIR AND OVERHAUL. REPORT TO FOLLOW. | | | | | | | | | |
| 7210 | | BELL 212 | PWA PT6T3 | | | GEAR BOX | FAILED NR1 | 9/19/93 | CA931013123 |
| (CAN) NR 1 GEARBOX FAILED. ENGINE SENT TO P&W FOR DAMAGE ASSESSMENT. | | | | | | | | | |
| 7250 | | BELL 212 | PWA PT6T3 | | 3016700 | COMP TURBNE 313411 | BURNT ENGINE | 9081 2743 | 4/15/93 CA930715602 |
| (CAN) DURING FLIGHT, ENGINE FAILED TO PRODUCE POWER AND OVERTEMPEd. INSPECTION REVEALED COMPRESSOR TURBINE WHEEL BURNT AND MATERIAL MISSING. PART TC: 1,879. | | | | | | | | | |
| 7421 | | CESSNA 172M | LYC O320E2D | | SKYTRONICS | SPARK PLUG NUTS | DEFECTIVE IGNITION HARNESS | 364 | 5/4/93 CA930720303 |
| (CAN) DURING 50 HR INSPECTION, NOTED NR 1 CYLINDER BOTTOM PLUG LEAD NUT WOULD NOT TIGHTEN TO PROPER TENSION. FURTHER INVESTIGATION REVEALED THE LEAD WAS PULLED THROUGH THE NUT. THREE MORE NUTS REVEALED THE SAME STATE. IT IS BELIEVED THE NUTS WERE OVERTIGHTENED DURING A PREVIOUS INSPECTION. | | | | | | | | | |
| 8530 | | CESSNA 172N | LYC O320H2AD | | | CYLINDER LW15318 | FAILED SPARK PLUG AREA | 789 | 11/27/93 CA931210002 |
| (CAN) CYLINDER LOWER SPARK PLUG HAD BROKEN FROM CYLINDER. PART OF CYLINDER AND SPARK PLUG INSERT HAD BROKEN AWAY WITH THE LOWER SPARK PLUG. THERE WAS EVIDENCE OF A PREVIOUS WELD REPAIR TO THE CYLINDER HEAD. | | | | | | | | | |

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|---------------------------|-----------|----------------------------|
| 8520 | | CESSNA A185F | CONT IO520D | | | CRANKSHAFT | BROKEN NR 2 BRG SADDLE | 1229 | 9/17/93 CA931013301 |
| (CAN) THE ENGINE OIL SCREEN FOUND CONTAMINATED WITH ALUMINUM AFTER NR 1 CYLINDER WAS REPLACED. NR 1 CYLINDER WAS REMOVED AND THE PISTON PIN END PLUG WAS FOUND WORN DOWN BY ONE-THIRD. THE PIN WAS REPLACED AND THE ENGINE OIL SYSTEM FLUSHED. THE ENGINE WAS PRE-OILED AS IT WAS TURNED. ENGINE WAS GROUND-RUN AND TEST FLOWN SERVICEABLE. 11.8 HOURS AFTER THIS WORK WAS COMPLETED A VISUAL INSPECTION REVEALED A HOLE IN THE CRANKCASE UNDER THE RT MAG INDICATING A BROKEN CONNECTING ROD. TEARDOWN REVEALED THE CRANKSHAFT BROKE DUE TO A BENDING OVERLOAD AT THE NR 3 CHEEK. THIS EXCESS BENDING WAS CAUSED BY LACK OF SUPPORT OF THE NR 2 CRANKSHAFT MAIN JOURNAL DUE TO BEARING FAILURE. | | | | | | | | | |
| 8530 | | CESSNA A185F | CONT IO520D | | | CYLINDER 635448CP | CRACKED NR 2 | 933 | 10/4/93 CA931018603 |
| (CAN) NR 2 CYLINDER SPLIT DURING FLIGHT. PART NUMBER NOT INCLUDED IN TCM SB M91-6 FOR CYLINDER BARREL INSPECTION. | | | | | | | | | |
| 8520 | | CESSNA U206 | CONT IO520F | | | CRANKCASE | CRACKED NEAR NR 5 CYL | 947 | 7/7/93 CA930722207 |
| (CAN) DURING INSPECTION OF POWERPLANT, A CRACK WHICH WAS WEEPING OIL WAS DISCOVERED NEAR THE FORWARD BOLT OF NR 5 CYLINDER. FURTHER INVESTIGATION USING NDT REVEALED THE DEFECT TO BE 2.2 INCHES IN LENGTH. THE POWERPLANT WAS REMOVED FROM THE AIRCRAFT. | | | | | | | | | |
| 8530 | | CESSNA U206A | CONT IO520F | | | CYLINDER 639272C | CRACKED ENGINE | 699 | 7/8/93 CA930719403 |
| (CAN) DURING 100 HR COMPRESSION CHECK, CYLINDER SHOWED 30/80 DIFFERENTIAL WITH NOTICEABLE NOISE WHERE AIR ESCAPED THROUGH CRACKS. CYLINDER WAS REPLACED. | | | | | | | | | |
| 7260 | | CESSNA 404CESSNA | CONT GTSIO520M | | | OIL SEAL 2512 | WORN NR 1 ASSORY DRV | 66 | 6/26/93 CA930709207 |
| (CAN) NR 1 ENGINE HAD OIL LEAK IN-FLIGHT AND ENGINE WAS SHUT DOWN. MAINTENANCE FOUND THE DRY AIR PUMP DRIVE SEAL PAD LEAKING OIL. THE OIL SEAL WAS NOT SEATING PROPERLY. A NEW SEAL WAS INSTALLED AND THE AIRCRAFT RETURNED TO SERVICE. | | | | | | | | | |
| 8520 | | CESSNA 421B | CONT GTSIO520H | | | THRU BOLT 641931175 | BROKEN CRANKCASE | | 6/13/93 CA930709210 |
| (CAN) OIL LEAK NOTED ON ENGINE. REMOVAL OF NR 4 CYLINDER REVEALED THE FORWARD LOWER THROUGH BOLT WAS BROKEN. CRANKCASE WAS ALSO CRACKED BETWEEN NR 4 CYLINDER EXHAUST LIFTER HOLE AND LOWER FORWARD STUD. ENGINE RETURNED TO REPAIR AND OVERHAUL. | | | | | | | | | |
| 7313 | | CESSNA 425 | PWA PT6A112 | | | FUEL NOZZLE | TORCHING NR 2 ENG | | 3/30/98 142 CA980421002 |
| (CAN) DURING CLIMB AFTER TAKEOFF, NR 2 ENGINE POWER ROLLED BACK FROM 1244 POUNDS TORQUE TO 800 POUNDS, T5 TEMPERATURE WAS 670C AND NG WAS 81 PERCENT. PILOT RETURNED TO BASE. POWER SECTION WAS REMOVED FOR HSI AND EXTENSIVE TORCHING DAMAGE WAS FOUND ON THE COMPRESSOR TURBINE GUIDE VANES AND THE TURBINE WHEEL. THE POWER TURBINE AND GUIDE VANES WERE ALSO DAMAGED. THE DAMAGE WAS SUSPECTED TO HAVE BEEN CAUSED BY A FUEL NOZZLE TORCHING (FUEL STREAMING INSTEAD OF SPRAYING). THE ENGINE WAS 142 HOURS FROM AN HSI, WITH THE FUEL NOZZLES CLEANED AND FLOW CHECKED. THE PARTS WERE RETURNED FOR EVALUATION. | | | | | | | | | |
| 7322 | | CESSNA 441 | GARRTT TPE33110 | MCAULY 4HFR34C652 | GARRTT | FUEL CONTROL 3971119 | RUPTURED P3 BELLOWS | 40 | 9/29/93 CA931214008 |
| (CAN) ENGINE LOST POWER ON TAKEOFF ROLL. GROUND INSPECTION REVEALED FULL LEAKING FROM THE FUEL CONTROL ASSEMBLY. INITIAL FUNCTIONAL TEST CONFIRMED SIGNIFICANT FUEL LEAK FROM UNIT. THE FUEL LEAK WAS OBSERVED TO BE COMING FROM THE PNEUMATIC SYSTEM. SPECIAL TESTING DETERMINED THAT FUEL WAS ENTERING THE PNEUMATIC CIRCUIT FROM THE AREA AROUND THE BELLOWS ASSEMBLY. THE BELLOWS ASSEMBLY WAS REMOVED & A PRESSURE TEST REVEALED A RUPTURE BETWEEN ONE OF THE CONVOLUTIONS. LOSS OF PRESSURE RESULTED IN REDUCED FUEL FLOW & LOSS OF POWER. SINCE THE PNEUMATIC CIRCUIT IS "VENTED" OVERBOARD FUEL WHICH ENTERS THE AIR SYSTEM WILL "LEAK" FROM THE VARIOUS PNEUMATIC VENTING HOLES/PORTS. | | | | | | | | | |
| 7322 | | CESSNA 441 | GARRTT TPE33110 | | | FUEL CONTROL 8971119 | LEAKING ENGINE | 40 | 9/29/93 CA931014407 |
| (CAN) ENGINE FAILED IN FLIGHT. GROUND INSPECTION REVEALED FUEL CONTROL UNIT LEAKING. PART TC: 39. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES (cont'd)

5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------------|--------------|----------------------------|
| 8530 | | DHAV DHC2EVANS | PWA R985AN14B | | | CYLINDER | DEFECTIVE ENGINE | 80 | 8/30/93 CA931102103 |
| (CAN) OVERHAULED ENGINE WITH "CERMICHROME" CYLINDERS PURCHASED FROM AERO ENGINES INC., CALIFORNIA. ENGINE ACTUALLY HAD "NU-CHROME" CYLINDERS INSTALLED AND CONSUMED 3 LITRES OF OIL PER HOUR FOR THE 80 HOURS SINCE INSTALLATION (TSO). THE ENGINE WAS REMOVED AND RETURNED TO AERO ENGINE. NO RESPONSE WAS FORTHCOMING AS TO THE PROBLEM OR ANY CONCLUSION ARRIVED AT ON TEARDOWN. | | | | | | | | | |
| 8530 | | DHAV DHC3 | PWA R134059 | | | CYLINDER 2578 | FAILED NR 3 EXH VLV | 538 | 9/18/93 CA931018608 |
| (CAN) NR 3 CYLINDER EXHAUST VALVE ROCKER BOSS BROKE OFF FROM CYLINDER HEAD IN CRUISE, SEVERE BACKFIRING AND POWER LOSS OF ENGINE FORCED PILOT TO LAND IMMEDIATELY ON SMALL LAKE. OIL SCREENS AND SUMP INSPECTED AND NR 3 CYLINDER REPLACED. AIRCRAFT FERRIED BACK TO BASE. | | | | | | | | | |
| 7230 | | DHAV DHC6300 | PWA PT6A27 | | | BEARING 37194 | SEIZED COMPRESSOR | 17799 966 | 9/24/93 CA931014404 |
| (CAN) NR 1 ENGINE MADE A BANGING SOUND, SURGED, AND THE T5 TEMPERATURE WENT TO 900 DEGREES CELSIUS. ENGINE WAS SHUTDOWN AND FLIGHT DIVERTED. POS-FLIGHT INSPECTION REVEALED OIL LEAKING FROM NR 2 BEARING AREA. OIL FILTER CHECKED AND FOUND CONTAMINATED WITH NON-FERROUS METAL PARTICLES. COMPRESSOR 1ST STAGE BLADES CHECKED AND FOUND RUBBING ON THE TOP PART OF COMPRESSOR CASE. ENGINE SEIZED AND WOULD NOT TURN OVER. TEARDOWN REVEALED CAUSED IFSD WAS NR 1 BEARING DISTRESS, DUE TO HEAVY DAMAGE OF THE BEARING FRACTURE SURFACE. CAUSE OF DISTRESS WAS NOT DETERMINED. PART TC: 17,693. | | | | | | | | | |
| 7250 | | DHAV DHC6200 | PWA PT6A20 | | | VANE | FRACTURED COMPRESS TURBINE | 229 | 7/8/93 CA930727101 |
| (CAN) PERSISTENT HIGH TEMPERATURE ON NR 1 ENGINE. TAKEOFF MONITOR OAT + 6 DEGREES CELSIUS, 5 SECONDS STABILIZE AT 85 PERCENT NG, TORQUE 40/40; NP 97/98, T5 740/720, NG 95/100, FUEL FLOW 380/375. AFTER TROUBLESHOOTING CARRIED OUT, THE ENGINE WAS BORESCOPED AND ONE COMPRESSOR TURBINE VANE WAS FOUND FRACTURED. ONLY HALF THE VANE WAS THERE. ENGINE REMOVED AND SENT TO R&O. | | | | | | | | | |
| 7421 | | DHAV DHC6100 | PWA PT6A20 | | | IGNITOR AGF26 | LOOSE NR 2 ENGINE | | 9/29/93 CA931015101 |
| (CAN) ABOUT 1 MINUTE AFTER STARTING NR 2 ENGINE, THE NR 2 FIRE WARNING LIGHT CAME ON, WENT OUT 10 SECONDS AFTER SHUTDOWN. NO SIGNS OF SMOKE OR FIRE. NR 2 IGNITOR LOOSE IN COWL. | | | | | | | | | |
| 8530 | | HUGHES 269C | LYC HIO360D1A | | | CYLINDER LW1947 | FAILED ENGINE | 29 | 6/17/93 CA930713601 |
| (CAN) CYLINDERS FAILED. ENGINE REPLACED. | | | | | | | | | |
| 7414 | | MOONEY M20E | LYC IO360A1A | | BENDIX | MAGNETO 116352 | FAILED DISTRIBUTOR BLOC | 1350 | 11/18/93 CA931207301 |
| (CAN) INSPECTION REVEALED THE BAKELITE AROUND THE BUSHING AREA OF THE BUSHING ON THE DISTRIBUTOR BLOCK WAS MISSING. THE SHAFT SPUN FREELY IN THE PLASTIC GEAR, THE FINGER THAT DIRECTS THE SPARK TO EACH CYLINDER WAS LOOSE AND IT WAS WEARING AWAY AS WERE ALL THE TABS IN THE DISTRIBUTOR BLOCK. | | | | | | | | | |
| 7261 | | PIPER PA23250 | LYC IO540C4B5 | | | OIL LINE 1781503 | CUT RT NACELLE | 6730 | 12/22/97 CA980113014 |
| (CAN) AT SHUTDOWN OIL LEAKED OUT UNDER RH NACELLE ONTO LANDING GEAR DOORS. OIL PRESSUR LINE CUT UNDER CLAMP AT FIREWALL, TWO PLACES, WIDTH OF CLAMP. IMPROPER SIZE CLAMP. REPLACED CLAMP. | | | | | | | | | |
| 7320 | | PIPER PA31T | PWA PT6A28 | | | P3 LINE 331448 | FRACTURED ENGINE | 3999 | 6/24/93 CA930709205 |
| (CAN) ON START-UP, ENGINE WOULD NOT ACCELERATE ABOVE IDLE. THE P3 LINE BETWEEN THE P3 FILTER AND FCU WAS FOUND BROKEN. PART TC: 4,404. | | | | | | | | | |
| 7414 | | SCWZER G164 | CONT W6706A | | BOSCH | MAGNETO SB9RU3 | CRACKED RT MAG DIST BLK | 47 | 7/9/93 CA930719411 |
| (CAN) DURING RUN-UP PRIOR TO FLIGHT, PILOT REPORTED 160 TO 200 RPM DROP ON RIGHT MAGNETO SYSTEM. TROUBLESHOOTING ISOLATED THE MAGNETO AS THE PROBLEM. UPON REMOVAL, THE DISTRIBUTOR BLOCK WAS FOUND CRACKED WHERE THE IGNITION LEADS PICK UP THEIR SPARK. MAGNETO WAS REPLACED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 7320 | | SKRSKY | ALLSN | | | TUBE B NUT | LOOSE | | 10/22/93 |
| | | S76A | 250C30S | | | 6893073 | NR 2 ENG | | CA931103102 |
| (CAN) AIRCRAFT LOST POWER ON NR 2 ENGINE. ENGINE HAD INSTABILITY IN POWER RANGE, ALL PNEUMATIC LINES WERE CHECKED FOR LEAKAGE, AIR LEAK WAS FOUND AT "B" NUT OF P/N 6893073 TUBE. | | | | | | | | | |

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - ENGINES)

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS**5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 2562 | | CESSNA 172M | | | NARCO ELT10 | ANTENNA 165211 | FRACTURED ELT | 700 | 5/1/93 CA931015202 |
| (CAN) ANTENNA WHIP FRACTURED AT BASE AS A RESULT OF WHIPPING BACK AND FORTH IN FLIGHT. PROBLEM EXACERBATED BY ICE ACCUMULATION. | | | | | | | | | |
| 3418 | | DHAV DHC6300 | PWA PT6A27 | | | SWITCH 61373 | FAILED STALL WARN | | 5/29/93 CA930719412 |
| (CAN) STALL WARNING SWITCH FAILED. | | | | | | | | | |
| 3418 | | DHAV DHC6300 | PWA PT6A27 | | | SWITCH 61373 | FAILED STALL WARN | | 6/12/93 CA930719408 |
| (CAN) STALL WARNING SWITCH FAILED. | | | | | | | | | |
| 3455 | | PIPER PA34200 | | | KING KR87 | POTENTIOMETER 133138 | BROKEN ADF WIRES | | 7/12/93 CA930722210 |
| (CAN) PILOT REPORTED INTERMITTENT 15 DEGREE ERROR ON ADF. BENCH TEST FOUND INTERMITTENT, 25 DEGREE ERROR. POTENTIOMETER R-177 BROKEN WIRES. | | | | | | | | | |
| (End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - COMPONENTS) | | | | | | | | | |

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS

5/3/98 - 5/9/98 ISSUE: 98-19 ZAC-327

| ATA | REG. NO | ACFT MAKE | ENG MAKE | PROP MAKE | COMP MFG | PART NAME | PART COND | TT | DIFF. DATE |
|------|-----------|------------|----------|-----------|----------|-------------|-----------|-----|--------------|
| OPER | SERIAL NO | ACFT MODEL | ENG MDL | PROP MDL | COMP MDL | PART NUMBER | PART LOC. | TSO | OPER CONT NO |

(There was no data for this report.)

(End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY - PROPELLERS)



U.S. Department
of Transportation
**Federal Aviation
Administration**

SERVICE DIFFICULTY REPORT SUMMARY

GENERAL AVIATION - INDEX



The following information provides a tally of the Service Difficulty Reports (SDR's) contained in this weeks issue of the General Aviation SDR Summary. The totals represent only a summation of the SDR's that were submitted to the FAA, Aviation Data Systems Branch, AFS-620, and processed in time for inclusion in the Summary. The first table is a tally of the number of SDR's submitted through the indicated Flight Standards District Office (FSDO). The second table sorts the SDR's by the aircraft or equipment make and model. The heading at the top of each table provides a two digit Joint Aircraft System/Component (JASC) code grouping (e.g., JASC codes 1100 thru 1800 are represented by the heading labeled 11-18) which categorizes in general, the problem areas for each reported discrepancy.

The Flight Standards Service Difficulty Program objective is to achieve prompt and appropriate correction of conditions adversely affecting continued airworthiness of aeronautical products. This is accomplished by the collection of Service Difficulty and Malfunction or Defect Reports. SDR's are consolidation and collation into common data base where they are analyzed for trends, problems, and alert information. This information is then disseminated to the appropriate segments of the aviation community and to other FAA offices.

The number of SDR's submitted is not an indicator of the mechanical reliability or fitness of an air carrier's aircraft fleet and should not be used as such. The air carriers certificate holding office has the primary responsibility for planning, programming evaluations, and assessing the performance of operators. Questions regarding an air carrier's fleet performance should be directed to the appropriate Flight Standards District Office, Certificate Management Office, or Certificate Management Unit.

GENERAL AVIATION SUMMARY INDEX BY DISTRICT OFFICE**5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327**

| DISTRICT OFFICE | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|--------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| AL 03 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| CA | 0 | 14 | 11 | 0 | 16 | 10 | 35 | 10 | 96 |
| CE 03 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| CE 09 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 2 |
| EA 03 | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 3 |
| EA 05 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 2 |
| EA 07 | 0 | 2 | 0 | 0 | 0 | 1 | 0 | 0 | 3 |
| EA 09 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| EA 13 | 0 | 1 | 1 | 0 | 0 | 1 | 0 | 0 | 3 |
| EA 17 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| EA 21 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| EA 23 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| EA 25 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| GL 09 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| GL 11 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 2 |
| GL 13 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 3 |
| GL 19 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| GL 23 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 2 |
| NE 01 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| NE 03 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| NM 01 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 2 |
| NM 03 | 0 | 0 | 1 | 0 | 5 | 0 | 4 | 1 | 11 |
| NM 07 | 0 | 1 | 1 | 0 | 0 | 2 | 0 | 0 | 4 |
| NM 09 | 0 | 2 | 2 | 0 | 1 | 0 | 2 | 0 | 7 |
| NM 13 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| SO 11 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |

| DISTRICT OFFICE | | 11-18 | 21-29 | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | |
|-----------------|----|----------|-----------|--------------------------------------|----------|-----------|------------|-----------|-----------|------------|
| | | | | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | TOTAL |
| SO | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| SO | 15 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| SO | 33 | 0 | 1 | 1 | 0 | 0 | 0 | 1 | 0 | 3 |
| SW | 01 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| SW | 03 | 0 | 54 | 51 | 0 | 15 | 83 | 38 | 0 | 241 |
| SW | 05 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 1 | 3 |
| SW | 99 | 0 | 2 | 3 | 0 | 0 | 0 | 1 | 1 | 7 |
| WP | 09 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 2 |
| WP | 19 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 2 |
| TOTALS | | 0 | 86 | 81 | 0 | 42 | 101 | 89 | 16 | 415 |

(End of GENERAL AVIATION SUMMARY INDEX by DISTRICT OFFICE Report)

GENERAL AVIATION SUMMARY INDEX by MANUFACTURER MAKE and MODEL**5/3/98 To 5/9/98 ISSUE: 98-19 ZAC-327**

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| AEROSP | AS355F1 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 2 |
| AEROSP | AS355F2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| AEROSP | SA315B | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 2 |
| AEROSP | SA365N1 | 0 | 2 | 0 | 0 | 0 | 1 | 0 | 0 | 3 |
| AGUSTA | A109K2 | 0 | 1 | 1 | 0 | 0 | 2 | 0 | 0 | 4 |
| AMTRMO | SONERAI2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| AYRES | S2RNORMAL | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | 100BEECH | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BEECH | 200BEECH | 0 | 1 | 2 | 0 | 5 | 0 | 0 | 0 | 8 |
| BEECH | 200CBEECH | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| BEECH | 58 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | 95B55 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 3 |
| BEECH | 95B55B | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | 99 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 2 |
| BEECH | A100 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BEECH | B99 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | C90 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| BEECH | C99 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| BEECH | E55 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | E90 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BEECH | F33A | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BEECH | G18S | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| BELL | 204B | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 2 |
| BELL | 206B | 0 | 2 | 2 | 0 | 0 | 3 | 4 | 0 | 11 |
| BELL | 206B3 | 0 | 2 | 2 | 0 | 0 | 3 | 1 | 0 | 8 |
| BELL | 206L | 0 | 1 | 0 | 0 | 0 | 8 | 3 | 0 | 12 |
| BELL | 206L1 | 0 | 3 | 9 | 0 | 2 | 19 | 11 | 0 | 44 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| BELL | 206L3 | 0 | 7 | 3 | 0 | 2 | 3 | 2 | 0 | 17 |
| BELL | 206L4 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| BELL | 212 | 0 | 0 | 2 | 0 | 0 | 2 | 3 | 0 | 7 |
| BELL | 214ST | 0 | 7 | 1 | 0 | 0 | 9 | 1 | 0 | 18 |
| BELL | 222U | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BELL | 230 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 2 |
| BELL | 407 | 0 | 2 | 2 | 0 | 2 | 4 | 2 | 0 | 12 |
| BELL | 412 | 0 | 17 | 10 | 0 | 4 | 9 | 0 | 0 | 40 |
| BOEING | 1072 | 0 | 2 | 0 | 0 | 0 | 0 | 2 | 0 | 4 |
| BOLKMS | BK117A3 | 0 | 1 | 1 | 0 | 0 | 0 | 1 | 0 | 3 |
| BOLKMS | BK117A4 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| BOLKMS | BK117B1 | 0 | 3 | 2 | 0 | 1 | 4 | 0 | 0 | 10 |
| BOLKMS | BK117B2 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOLKMS | BO105C | 0 | 2 | 0 | 0 | 2 | 0 | 1 | 0 | 5 |
| BOLKMS | BO105CB* | 0 | 0 | 1 | 0 | 0 | 2 | 0 | 0 | 3 |
| BOLKMS | BO105CBS | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 3 |
| BOLKMS | BO105S | 0 | 4 | 5 | 0 | 0 | 11 | 10 | 0 | 30 |
| CESSNA | 150L | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | 152 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| CESSNA | 172E | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| CESSNA | 172L | 0 | 1 | 1 | 0 | 0 | 0 | 1 | 1 | 4 |
| CESSNA | 172M | 0 | 1 | 0 | 0 | 0 | 0 | 1 | 0 | 2 |
| CESSNA | 172N | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 1 | 3 |
| CESSNA | 172P | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 1 | 2 |
| CESSNA | 172RG | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | 175 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 3 |
| CESSNA | 180J | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| CESSNA | 182C | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | 182F | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| CESSNA | 182J | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 2 |
| CESSNA | 182P | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 2 |
| CESSNA | 208B | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | 210L | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 2 |
| CESSNA | 310I | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | 310R | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| CESSNA | 335 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| CESSNA | 402C | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| CESSNA | 404CESSNA | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| CESSNA | 421B | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| CESSNA | 425 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| CESSNA | 441 | 0 | 0 | 1 | 0 | 0 | 0 | 2 | 0 | 3 |
| CESSNA | 550 | 0 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 3 |
| CESSNA | A185E | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| CESSNA | A185F | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 2 | 3 |
| CESSNA | R182 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | T337B | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| CESSNA | U206 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 1 | 3 |
| CESSNA | U206A | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| CESSNA | U206G | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| DHAV | DHC2EVANS | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| DHAV | DHC2MK1 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| DHAV | DHC3 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 2 |
| DHAV | DHC6100 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 2 |
| DHAV | DHC6200 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| DHAV | DHC6300 | 0 | 0 | 3 | 0 | 0 | 0 | 1 | 0 | 4 |
| ENSTRM | F28C | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| GULSTM | 695 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| HILLER | UH12E | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| HUGHES | 269C | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| HUGHES | 369D | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 3 |
| LUSCOM | 8A | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| MOONEY | M20E | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| MOONEY | M20K | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| NOORDN | UC64A | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| PARTEN | P68C | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| PIPER | PA23250 | 0 | 1 | 2 | 0 | 0 | 0 | 1 | 0 | 4 |
| PIPER | PA28140 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 3 |
| PIPER | PA28161 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 2 |
| PIPER | PA28236 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| PIPER | PA28R201T | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 2 |
| PIPER | PA30 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| PIPER | PA31 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| PIPER | PA31350 | 0 | 0 | 0 | 0 | 1 | 0 | 3 | 0 | 4 |
| PIPER | PA31T | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 2 |
| PIPER | PA32R301 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| PIPER | PA34200 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| PIPER | PA34220T | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| PIPER | PA60600 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| SCWZER | G164 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| SKRSKY | S76 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| SKRSKY | S76A | 0 | 5 | 6 | 0 | 0 | 4 | 6 | 0 | 21 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | TOTAL |
| SNIAS | AS350B | 0 | 0 | 2 | 0 | 1 | 1 | 0 | 0 | 4 |
| SNIAS | AS350B2 | 0 | 1 | 0 | 0 | 0 | 6 | 1 | 0 | 8 |
| SNIAS | AS350BA | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| SOCATA | TB20TRINIDAD | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| UROCOP | EC135P1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| VARGA | 2150AMORISY | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| TOTALS | | 0 | 86 | 81 | 0 | 42 | 101 | 89 | 16 | 415 |

(End of AIR CARRIER SUMMARY INDEX by OPERATOR Report)

JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

PREFACE

The Joint Aircraft System/Component (JASC) Code Table is a modified version of the Air Transport Association of America (ATA), Specification 100 code. It was developed by the Federal Aviation Administration's (FAA), Aviation Data Systems Branch (AFS-620). Technical support was provided by the Galaxy Scientific Corporation, and various representatives of the air carrier and general aviation community.

Over the past four years, the JASC format of the ATA Spec 100 code has gained widespread industry acceptance. In a harmonized effort, the FAA's counterparts in Australia and Canada have adopted the JASC code with only a few exceptions. Some Canadian aircraft manufacturers have also recently adopted this new standard.

This code table is constructed by using the new JASC four (4) digit code, along with an abbreviated code title. The abbreviated titles have been modified in some cases to clarify the intended use of the accompanying code. This table can be used as a quick reference chart, to assist in the coding and review of aircraft structures or systems data (i.e., Service Difficulty Report (SDR), Accident/Incident Report).

The current coding scheme used in the JASC code was introduced in May 1991, for the technical classification of SDR's. Its predecessor, the FAA aircraft system/component code, was a similar but more complex eight-digit code which was developed over 25 years ago. It was constructed around the computer technology of that period. It consisted of a four digit numerical code plus a four alpha character code to make data retrieval possible. Since that time, computer technology has advanced many fold. Reducing the code from eight to four characters simplifies coding, and in some cases, makes JASC coding match the ATA Specification 100 first three digits, which are used to identify aircraft systems. The ATA code does not reference the fourth digit, so it is free to be used for identifying components.

The JASC code aircraft structural section has increased due to problems inherent with aging aircraft. As an example, FAA code 5301 SXBD was expanded to 20 items due to the high rate of reporting in this area (8021 structural reports were received in 1989). In some instances, there was very little reporting and codes were combined into other systems if the safety impact was not significant. The overall reduction in codes has been from 568 FAA codes to 488 JASC codes, with the significant increase being in the structural area as stated earlier.

The JASC code divides the engine section into two major code groups to separate the turbine and reciprocating engines. The codes for the turbine engines are in JASC Chapter 72, Turbine/Turboprop Engine. The codes for the reciprocating engines are now exclusively found in JASC Chapter 85, Reciprocating Engine.

The other major deviation from ATA Spec 100 is in ATA section 2730, specifically involves the stall warning system. Early technology (primarily on smaller aircraft) directly linked the sensing of flight attitude to one of the components which furnished the means of manually controlling the flight attitude characteristics (elevator). Today, most large transport category aircraft utilize electronic units to sense the change in the environmental condition called stall, and use the data to influence navigation. ATA section 3410, Flight Environment Data, includes high speed warning in its code definition. Stall warning (low speed) is the reciprocal term of high speed warning, so its filing under the same code appears more logical. Thus, with the JASC code it was decided to move the stall warning system to Chapter 34 under the separate code JASC code 3418, Stall Warning System.

The FAA is continuing to pursue worldwide involvement from operators and manufacturers in addressing the need for international standardization of aircraft system/component codes. The ultimate goal is to develop a universal aircraft/component numbering standard which can be used in the manufacturer's maintenance manual, wiring diagram manual, system manuals and illustrated parts catalog. This harmonized standard must be a usable standard for the aircraft manufacturers, air carrier operators and the general aviation community.

We welcome comments and feedback regarding the possible forming of working groups to achieve this long range consideration of possibly harmonizing the ATA Specification 100 code and the JASC code. Comments may be directed to the FAA, Aviation Data Sytem Branch, AFS-620, P.O. Box 25082, Oklahoma City, OK 73125.

JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

JASC/ TITLE

11 PLACARDS AND MARKINGS

1100 PLACARDS AND MARKINGS

12 SERVICING

1210 FUEL SERVICING
1220 OIL SERVICING
1230 HYDRAULIC FLUID SERVICING
1240 COOLANT SERVICING

18 HELICOPTER VIBRATION

1800 HELICOPTER VIB/NOISE ANALYSIS
1810 HELICOPTER VIBRATION ANALYSIS
1820 HELICOPTER NOISE ANALYSIS

21 AIR CONDITIONING

2100 AIR CONDITIONING SYSTEM
2110 CABIN COMPRESSOR SYSTEM
2120 AIR DISTRIBUTION SYSTEM
2121 AIR DISTRIBUTION FAN
2130 CABIN PRESSURE CONTROL SYSTEM
2131 CABIN PRESSURE CONTROLLER
2132 CABIN PRESSURE INDICATOR
2133 PRESSURE REGUL/OUTFLOW VALVE
2134 CABIN PRESSURE SENSOR
2140 HEATING SYSTEM
2150 CABIN COOLING SYSTEM
2160 CABIN TEMPERATURE CONTROL SYSTEM
2161 CABIN TEMPERATURE CONTROLLER
2162 CABIN TEMPERATURE INDICATOR
2163 CABIN TEMPERATURE SENSOR
2170 HUMIDITY CONTROL SYSTEM

22 AUTO FLIGHT

2200 AUTO FLIGHT SYSTEM
2210 AUTOPILOT SYSTEM
2211 AUTOPILOT COMPUTER
2212 ALTITUDE CONTROLLER
2213 FLIGHT CONTROLLER
2214 AUTOPILOT TRIM INDICATOR
2215 AUTOPILOT MAIN SERVO
2216 AUTOPILOT TRIM SERVO
2220 SPEED-ATTITUDE CORRECT. SYSTEM
2230 AUTO THROTTLE SYSTEM
2250 AERODYNAMIC LOAD ALLEVIATING

23 COMMUNICATIONS

2300 COMMUNICATIONS SYSTEM
2310 HF COMMUNICATION SYSTEM
2311 UHF COMMUNICATION SYSTEM
2312 VHF COMMUNICATION SYSTEM
2320 DATA TRANSMISSION AUTO CALL
2330 ENTERTAINMENT SYSTEM
2340 INTERPHONE & PA SYSTEM
2350 AUDIO INTEGRATING SYSTEM
2360 STATIC DISCHARGE SYSTEM
2370 AUDIO/VIDEO MONITORING

24 ELECTRICAL POWER

2400 ELECTRICAL POWER SYSTEM
2410 ALTERNATOR-GENERATOR DRIVE
2420 AC GENERATION SYSTEM
2421 AC GENERATOR-ALTERNATOR
2422 AC INVERTER
2423 PHASE ADAPTER

24 ELECTRICAL POWER CONT'D

2424 AC REGULATOR
2425 AC INDICATING SYSTEM
2430 DC GENERATING SYSTEM
2431 BATTERY OVERHEAT WARN. SYSTEM
2432 BATTERY/CHARGER SYSTEM
2433 DC RECTIFIER-CONVERTER
2434 DC GENERATOR-ALTERNATOR
2435 STARTER-GENERATOR
2436 DC REGULATOR
2437 DC INDICATING SYSTEM
2440 EXTERNAL POWER SYSTEM
2450 AC POWER DISTRIBUTION SYSTEM
2460 DC POWER/DISTRIBUTION SYSTEM

25 EQUIPMENT/FURNISHINGS

2500 CABIN EQUIPMENT/FURNISHINGS
2510 FLIGHT COMPARTMENT EQUIPMENT
2520 PASSENGER COMPARTMENT EQUIPMENT
2530 BUFFET/GALLEYS
2540 LAVATORIES
2550 CARGO COMPARTMENTS
2551 AGRICULTURAL SPRAY SYSTEM
2560 EMERGENCY EQUIPMENT
2561 LIFE JACKET
2562 EMERGENCY LOCATOR BEACON
2563 PARACHUTE
2564 LIFE RAFT
2565 ESCAPE SLIDE
2570 ACCESSORY COMPARTMENT
2571 BATTERY BOX STRUCTURE
2572 ELECTRONIC SHELF SECTION

26 FIRE PROTECTION

2600 FIRE PROTECTION SYSTEM
2610 DETECTION SYSTEM
2611 SMOKE DETECTION
2612 FIRE DETECTION
2613 OVERHEAT DETECTION
2620 EXTINGUISHING SYSTEM
2621 FIRE BOTTLE, FIXED
2622 FIRE BOTTLE, PORTABLE

27 FLIGHT CONTROLS

2700 FLIGHT CONTROL SYSTEM
2701 CONTROL COLUMN SECTION
2710 AILERON CONTROL SYSTEM
2711 AILERON TAB CONTROL SYSTEM
2720 RUDDER CONTROL SYSTEM
2721 RUDDER TAB CONTROL SYSTEM
2722 RUDDER ACTUATOR
2730 ELEVATOR CONTROL SYSTEM
2731 ELEVATOR TAB CONTROL SYSTEM
2740 STABILIZER CONTROL SYSTEM
2741 STABILIZER POSITION INDICATING
2742 STABILIZER ACTUATOR
2750 TE FLAP CONTROL SYSTEM
2751 TE FLAP POSITION IND. SYSTEM
2752 TE FLAP ACTUATOR
2760 DRAG CONTROL SYSTEM
2761 DRAG CONTROL ACTUATOR
2770 GUST LOCK/DAMPER SYSTEM
2780 LE FLAP CONTROL SYSTEM
2781 LE FLAP POSITION IND. SYSTEM
2782 LE FLAP ACTUATOR

28 FUEL

2800 AIRCRAFT FUEL SYSTEM
2810 FUEL STORAGE
2820 ACFT FUEL DISTRIB. SYSTEM
2821 ACFT FUEL FILTER/STRAINER
2822 FUEL BOOST PUMP
2823 FUEL SELECTOR/SHUTOFF VALVE
2824 FUEL TRANSFER VALVE
2830 FUEL DUMP SYSTEM
2840 ACFT FUEL INDICATING
2841 FUEL QUANTITY INDICATOR
2842 FUEL QUANTITY SENSOR
2843 FUEL TEMPERATURE INDICATING
2844 FUEL PRESSURE INDICATOR

29 HYDRAULIC POWER

2900 HYDRAULIC POWER SYSTEM
2910 HYDRAULIC, MAIN SYSTEM
2911 HYDRAULIC POWER-ACCUMULATOR-MAIN
2912 HYDRAULIC FILTER-MAIN SYSTEM
2913 HYDRAULIC PUMP. ELECT-ENG.-MAIN
2914 HYDRAULIC HANDPUMP-MAIN
2915 HYDRAULIC PRESSURE RELIEF VLV-MAIN
2916 HYDRAULIC RESERVOIR-MAIN
2917 HYDRAULIC PRESSURE REGULATOR-MAIN
2920 HYDRAULIC, AUXILIARY SYSTEM
2921 HYDRAULIC ACCUMULATOR-AUXILIARY
2922 HYDRAULIC FILTER-AUXILIARY
2923 HYDRAULIC PUMP-AUXILIARY
2925 HYDRAULIC PRESSURE RELIEF-AUXILIARY
2926 HYDRAULIC RESERVOIR-AUXILIARY
2927 HYDRAULIC PRESSURE REGULATOR-AUX.
2930 HYDRAULIC SYSTEM INDICATING
2931 HYDRAULIC PRESSURE INDICATOR
2932 HYDRAULIC PRESSURE SENSOR
2933 HYDRAULIC QUANTITY INDICATOR
2934 HYDRAULIC QUANTITY SENSOR

30 ICE AND RAIN PROTECTION

3000 ICE/RAIN PROTECTION SYSTEM
3010 AIRFOIL ANTI/DE-ICE SYSTEM
3020 AIR INTAKE ANTI/DE-ICE SYSTEM
3030 PITOT/STATIC ANTI-ICE SYSTEM
3040 WINDSHIELD/DOOR RAIN/ICE REMOVAL
3050 ANTENNA/RADOME ANTI-ICE/DE-ICE SYSTEM
3060 PROP/ROTOR ANTI-ICE/DE-ICE SYSTEM
3070 WATER LINE ANTI-ICE SYSTEM
3080 ICE DETECTION

31 INSTRUMENTS

3100 INDICATING/RECORDING SYSTEM
3110 INSTRUMENT PANEL
3120 INDEPENDENT INSTRUMENTS (CLOCK, ETC.)
3130 DATA RECORDERS (FLT/MAINT)
3140 CENTRAL COMPUTERS (EICAS)
3150 CENTRAL WARNING
3160 CENTRAL DISPLAY
3170 AUTOMATIC DATA

32 LANDING GEAR

3200 LANDING GEAR SYSTEM
3201 LANDING GEAR/WHEEL FAIRING
3210 MAIN LANDING GEAR
3211 MAIN LANDING GEAR ATTACH SECTION
3212 EMERGENCY FLOTATION SECTION
3213 MAIN LANDING GEAR STRUT/AXLE/TRUCK
3220 NOSE/TAIL LANDING GEAR
3221 NOSE/TAIL LANDING GEAR ATTACH SECTION
3222 NOSE/TAIL LANDING GEAR STRUT/AXLE
3230 LANDING GEAR RETRACT/EXT. SYSTEM
3231 LANDING GEAR DOOR RETRACT SECTION
3232 LANDING GEAR DOOR ACTUATOR
3233 LANDING GEAR ACTUATOR
3234 LANDING GEAR SELECTOR
3240 LANDING GEAR BRAKE SYSTEM
3241 BRAKE ANTI-SKID SECTION
3242 BRAKE
3243 MASTER CYL/BRAKE VALVE
3244 TIRE
3245 TIRE TUBE
3246 WHEEL/SKI/FLOAT
3250 LANDING GEAR STEERING SYSTEM
3251 STEERING UNIT
3252 SHIMMY DAMPER
3260 LANDING GEAR POSITION & WARNING
3270 AUXILIARY GEAR (TAIL SKID)

33 LIGHTS

3300 LIGHTING SYSTEM
3310 FLIGHT COMPARTMENT LIGHTING
3320 PASSENGER COMPARTMENT LIGHTING
3330 CARGO COMPARTMENT LIGHTING
3340 EXTERIOR LIGHTING
3350 EMERGENCY LIGHTING

34 NAVIGATION

3400 NAVIGATION SYSTEM
3410 FLIGHT ENVIRONMENT DATA
3411 PITOT/STATIC SYSTEM
3412 OUTSIDE AIR TEMP. IND./SENSOR
3413 RATE OF CLIMB INDICATOR
3414 AIRSPEED/MACH INDICATING
3415 HIGH SPEED WARNING
3416 ALTIMETER, BAROMETRIC/ENCODER

34 NAVIGATION CONT'D

3417 AIR DATA COMPUTER
3418 STALL WARNING SYSTEM
3420 ATTITUDE AND DIRECTION DATA SYSTEM
3421 ATTITUDE GYRO & IND. SYSTEM
3422 DIRECTIONAL GYRO & IND. SYSTEM
3423 MAGNETIC COMPASS
3424 TURN & BANK/RATE OF TURN INDICATOR
3425 INTEGRATED FLT. DIRECTOR SYSTEM
3430 LANDING & TAXI AIDS
3431 LOCALIZER/VOR SYSTEM
3432 GLIDE SLOPE SYSTEM
3433 MICROWAVE LANDING SYSTEM
3434 MARKER BEACON SYSTEM
3435 HEADS UP DISPLAY SYSTEM
3436 WIND SHEAR DETECTION SYSTEM
3440 INDEPENDENT POS. DETERMINING SYSTEM
3441 INERTIAL GUIDANCE SYSTEM
3442 WEATHER RADAR SYSTEM
3443 DOPPLER SYSTEM
3444 GROUND PROXIMITY SYSTEM
3445 AIR COLLISION AVOIDANCE SYSTEM (TCAS)
3446 NON RADAR WEATHER SYSTEM
3450 DEPENDENT POSITION DETERMINING SYSTEM
3451 DME/TACAN SYSTEM
3452 ATC TRANSPONDER SYSTEM
3453 LORAN SYSTEM
3454 VOR SYSTEM
3455 ADF SYSTEM
3456 OMEGA NAVIGATION SYSTEM
3457 GLOBAL POSITIONING SYSTEM
3460 FLIGHT MANAGE. COMPUTING SYSTEM

35 OXYGEN

3500 OXYGEN SYSTEM
3510 CREW OXYGEN SYSTEM
3520 PASSENGER OXYGEN SYSTEM
3530 PORTABLE OXYGEN SYSTEM

36 PNEUMATIC

3600 PNEUMATIC SYSTEM
3610 PNEUMATIC DISTRIBUTION SYSTEM
3620 PNEUMATIC INDICATING SYSTEM

37 VACUUM

3700 VACUUM SYSTEM
3710 VACUUM DISTRIBUTION SYSTEM
3720 VACUUM INDICATING SYSTEM

38 WATER/WASTE

3800 WATER & WASTE SYSTEM
3810 POTABLE WATER SYSTEM
3820 WASH WATER SYSTEM
3830 WASTE DISPOSAL SYSTEM
3840 AIR SUPPLY (WATER PRESS. SYSTEM)

45 CENTRAL MAINT. SYSTEM

4500 CENTRAL MAINT. COMPUTER

49 AIRBORNE AUXILIARY POWER

4900 AIRBORNE APU SYSTEM
4910 APU COWLING/CONTAINMENT
4920 APU CORE ENGINE
4930 APU ENGINE FUEL & CONTROL
4940 APU START/IGNITION SYSTEM
4950 APU BLEED AIR SYSTEM
4960 APU CONTROLS
4970 APU INDICATING SYSTEM
4980 APU EXHAUST SYSTEM
4990 APU OIL SYSTEM

51 STANDARD PRACTICES/STRUCTURES

5100 STANDARD PRACTICES/STRUCTURES
5101 AIRCRAFT STRUCTURES
5102 BALLOON REPORTS

52 DOORS

5200 DOORS
5210 PASSENGER/CREW DOORS
5220 EMERGENCY EXIT
5230 CARGO/BAGGAGE DOORS
5240 SERVICE DOORS
5241 GALLEY DOORS
5242 E/E COMPARTMENT DOORS
5243 HYDRAULIC COMPARTMENT DOORS
5244 ACCESSORY COMPARTMENT DOORS
5245 AIR CONDITIONING COMPART. DOORS
5246 FLUID SERVICE DOORS

5247 APU DOORS
5248 TAIL CONE DOORS
5250 FIXED INNER DOORS
5260 ENTRANCE STAIRS
5270 DOOR WARNING SYSTEM
5280 LANDING GEAR DOORS

53 FUSELAGE

5300 FUSELAGE STRUCTURE (GENERAL)
5301 AERIAL TOW EQUIPMENT
5302 ROTORCRAFT TAIL BOOM
5310 FUSELAGE MAIN STRUCTURE
5311 FUSELAGE MAIN FRAME
5312 FUSELAGE MAIN BULKHEAD
5313 FUSELAGE MAIN LONGERON/STRINGER
5314 FUSELAGE MAIN KEEL
5315 FUSELAGE MAIN FLOOR BEAM
5320 FUSELAGE MISCELLANEOUS STRUCTURE
5321 FUSELAGE FLOOR PANEL
5322 FUSELAGE INTERNAL MOUNT STRUCTURE
5323 FUSELAGE INTERNAL STAIRS
5324 FUSELAGE FIXED PARTITIONS
5330 FUSELAGE MAIN PLATE/SKIN
5340 FUSELAGE MAIN ATTACH FITTINGS
5341 WING ATTACH FITTINGS (ON FUSELAGE)
5342 STABILIZER ATTACH FITTINGS
5343 LANDING GEAR ATTACH FITTINGS
5344 FUSELAGE DOOR HINGES
5345 FUSELAGE EQUIPMENT ATTACH FITTINGS
5346 POWERPLANT ATTACH FITTINGS
5347 SEAT/CARGO ATTACH FITTINGS
5350 FUSELAGE AERODYNAMIC FAIRINGS

54 NACELLES/PYLONS

5400 NACELLE/PYLON STRUCTURE
5410 MAIN FRAME (ON NACELLE/PYLON)
5411 FRAME/SPAR/RIB(NACELLE/PYLON)
5412 BULKHEAD/FIREWALL (NAC/PYLON)
5413 LONGERON/STRINGER (NAC/PYLON)
5414 PLATE SKIN (NAC/PYLONS)
5415 ATTACH FITTINGS (NAC/PYLON)

55 STABILIZERS

5500 EMPENNAGE STRUCTURE
5510 HORIZONTAL STABILIZER STRUCTURE
5511 HORIZONTAL STABILIZER SPAR/RIB
5512 HORIZONTAL STABILIZER PLATE/SKIN
5513 HORIZONTAL STABILIZER TAB STRUCTURE
5520 ELEVATOR STRUCTURE

55 STABILIZERS CONT'D

5521 ELEVATOR SPAR/RIB STRUCTURE
5522 ELEVATOR PLATES/SKIN STRUCTURE
5523 ELEVATOR TAB STRUCTURE
5530 VERTICAL STABILIZER STRUCTURE
5531 VERTICAL STABILIZER SPAR/RIB STRUCTURE
5532 VERTICAL STABILIZER PLATES/SKIN
5533 VENTRAL STRUCTURE (ON VERT. STAB)
5540 RUDDER STRUCTURE
5541 RUDDER SPAR/RIB STRUCTURE
5542 RUDDER PLATE/SKIN STRUCTURE
5543 RUDDER TAB STRUCTURE
5550 EMPENNAGE FLT. CONT. ATTACH FITTING
5551 HORIZONTAL STABILIZER ATTACH FITTING
5552 ELEVATOR/TAB ATTACH FITTINGS
5553 VERT. STAB. ATTACH FITTINGS
5554 RUDDER/TAB ATTACH FITTINGS

56 WINDOWS

5600 WINDOW/WINDSHIELD SYSTEM
5610 FLIGHT COMPARTMENT WINDOWS
5620 PASSENGER COMPARTMENT WINDOWS
5630 DOOR WINDOWS
5640 INSPECTION WINDOWS

57 WINGS

5700 WING STRUCTURE
5710 WING MAIN FRAME STRUCTURE
5711 WING SPAR STRUCTURE
5712 WING RIB STRUCTURE
5713 WING LONGERON/STRINGER
5714 WING CENTER BOX
5720 WING MISCELLANEOUS STRUCTURE
5730 WING PLATES/SKINS
5740 WING ATTACH FITTINGS
5741 WING, FUSELAGE ATTACH FITTINGS
5742 WING, NAC/PYLON ATTACH FITTINGS
5743 WING, LANDING GEAR ATTACH FITTINGS
5744 CONTROL SURFACE ATTACH FITTINGS
5750 WING CONTROL SURFACE STRUCTURE
5751 AILERON STRUCTURE
5752 AILERON TAB STRUCTURE
5753 TE FLAP STRUCTURE
5754 LEADING EDGE DEVICE STRUCTURE
5755 SPOILER STRUCTURE

61 PROPELLERS/PROPULSORS

6100 PROPELLER SYSTEM
6110 PROPELLER ASSEMBLY
6111 PROPELLER BLADE SECTION
6112 PROPELLER DE-ICE BOOT SECTION
6113 PROPELLER SPINNER SECTION
6114 PROPELLER HUB SECTION
6120 PROPELLER CONTROL SYSTEM
6121 PROPELLER SYNCHRONIZER SECTION
6122 PROPELLER GOVERNOR
6123 PROPELLER FEATHERING/REVERSING
6130 PROPELLER BRAKING
6140 PROPELLER INDICATING SYSTEM

62 MAIN ROTOR

6200 MAIN ROTOR SYSTEM
6210 MAIN ROTOR BLADES
6220 MAIN ROTOR HEAD
6230 MAIN ROTOR MAST/SWASHPLATE
6240 MAIN ROTOR INDICATING SYSTEM

63 MAIN ROTOR DRIVE

6300 MAIN ROTOR DRIVE SYSTEM
6310 ENGINE/TRANSMISSION COUPLING
6320 MAIN ROTOR GEARBOX
6321 MAIN ROTOR BRAKE
6322 ROTORCRAFT COOLING FAN SYSTEM
6330 MAIN ROTOR TRANSMISSION MOUNT
6340 ROTOR DRIVE INDICATING SYSTEM

64 TAIL ROTOR

6400 TAIL ROTOR SYSTEM
6410 TAIL ROTOR BLADE
6420 TAIL ROTOR HEAD
6440 TAIL ROTOR INDICATING SYSTEM

65 TAIL ROTOR DRIVE

6500 TAIL ROTOR DRIVE SYSTEM
6510 TAIL ROTOR DRIVE SHAFT
6520 TAIL ROTOR GEARBOX
6540 TAIL ROTOR DRIVE INDICATING SYSTEM

67 ROTORS FLIGHT CONTROL

6700 ROTORCRAFT FLIGHT CONTROL
6710 MAIN ROTOR CONTROL
6711 TILT ROTOR FLIGHT CONTROL
6720 TAIL ROTOR CONTROL SYSTEM
6730 ROTORCRAFT SERVO SYSTEM

71 POWERPLANT

7100 POWERPLANT SYSTEM
7110 ENGINE COWLING SYSTEM
7111 COWL FLAP SYSTEM
7112 ENGINE AIR BAFFLE SECTION
7120 ENGINE MOUNT SECTION
7130 ENGINE FIRESEALS
7160 ENGINE AIR INTAKE SYSTEM
7170 ENGINE DRAINS

72 TURBINE/TURBOPROP ENGINE

7200 ENGINE (TURBINE/TURBOPROP)
7210 TURBINE ENGINE REDUCTION GEAR
7220 TURBINE ENGINE AIR INLET SECTION
7230 TURBINE ENGINE COMPRESSOR SECTION
7240 TURBINE ENGINE COMBUSTION SECTION
7250 TURBINE SECTION
7260 TURBINE ENGINE ACCESSORY DRIVE
7261 TURBINE ENGINE OIL SYSTEM
7270 TURBINE ENGINE BYPASS SECTION

73 ENGINE FUEL & CONTROL

7300 ENGINE FUEL & CONTROL
7310 ENGINE FUEL DISTRIBUTION
7311 ENGINE FUEL-OIL COOLER
7312 FUEL HEATER
7313 FUEL INJECTOR NOZZLE
7314 ENGINE FUEL PUMP
7320 FUEL CONTROLLING SYSTEM
7321 FUEL CONTROL/ELECTRONIC
7322 FUEL CONTROL/CARBURETOR
7323 TURBINE GOVERNOR
7324 FUEL DIVIDER
7330 ENGINE FUEL INDICATING SYSTEM
7331 FUEL FLOW INDICATING
7332 FUEL PRESSURE INDICATING
7333 FUEL FLOW SENSOR
7334 FUEL PRESSURE SENSOR

74 IGNITION

7400 IGNITION SYSTEM
7410 IGNITION POWER SUPPLY
7411 LOW TENSION COIL
7412 EXCITER
7413 INDUCTION VIBRATOR
7414 MAGNETO/DISTRIBUTOR
7420 IGNITION HARNESS (DISTRIBUTION)
7421 SPARK PLUG/IGNITER
7430 IGNITION SWITCHING

75 AIR

7500 ENGINE BLEED AIR SYSTEM
7510 ENGINE ANTI-ICING SYSTEM
7520 ENGINE COOLING SYSTEM
7530 COMPRESSOR BLEED CONTROL
7531 COMPRESSOR BLEED GOVERNOR
7532 COMPRESSOR BLEED VALVE
7540 BLEED AIR INDICATING SYSTEM

76 ENGINE CONTROLS

7600 ENGINE CONTROLS
7601 ENGINE SYNCHRONIZING
7602 MIXTURE CONTROL
7603 POWER LEVER
7620 ENGINE EMERGENCY SHUTDOWN SYSTEM

77 ENGINE INDICATING

7700 ENGINE INDICATING SYSTEM
7710 POWER INDICATING SYSTEM
7711 ENGINE PRESSURE RATIO (EPR)
7712 ENGINE BMEP/TORQUE INDICATING
7713 MANIFOLD PRESSURE (MP) INDICATING
7714 ENGINE RPM INDICATING SYSTEM
7720 ENGINE TEMP. INDICATING SYSTEM
7721 CYLINDER HEAD TEMP (CHT) INDICATING
7722 ENG. EGT/TIT INDICATING SYSTEM
7730 ENGINE IGNITION ANALYZER SYSTEM
7731 ENGINE IGNITION ANALYZER
7732 ENGINE VIBRATION ANALYZER
7740 ENGINE INTEGRATED INSTRUMENT SYSTEM

78 ENGINE EXHAUST

7800 ENGINE EXHAUST SYSTEM
7810 ENGINE COLLECTOR/TAILOPIPE/NOZZLE
7820 ENGINE NOISE SUPPRESSOR
7830 THRUST REVERSER

79 ENGINE OIL

7900 ENGINE OIL SYSTEM (AIRFRAME)
7910 ENGINE OIL STORAGE (AIRFRAME)
7920 ENGINE OIL DISTRIBUTION (AIRFRAME)
7921 ENGINE OIL COOLER
7922 ENGINE OIL TEMP. REGULATOR
7923 OIL SHUTOFF VALVE
7930 ENGINE OIL INDICATING SYSTEM
7931 ENGINE OIL PRESSURE
7932 ENGINE OIL QUANTITY
7933 ENGINE OIL TEMPERATURE

80 STARTING

8000 ENGINE STARTING SYSTEM
8010 ENGINE CRANKING
8011 ENGINE STARTER
8012 ENGINE START VALVES/CONTROLS

81 TURBOCHARGING

8100 EXHAUST TURBINE SYSTEM (RECIP)
8110 POWER RECOVERY TURBINE (RECIP)
8120 EXHAUST TURBOCHARGER

82 WATER INJECTION

8200 WATER INJECTION SYSTEM

83 ACCESSORY GEARBOXES

8300 ACCESSORY GEARBOXES

85 RECIPROCATING ENGINE

8500 ENGINE (RECIPROCATING)
8510 RECIPROCATING ENGINE FRONT SECTION
8520 RECIPROCATING ENGINE POWER SECTION

8530 RECIPROCATING ENGINE CYLINDER SECTION
8540 RECIPROCATING ENGINE REAR SECTION
8550 RECIPROCATING ENGINE OIL SYSTEM

MECHANICS CREED

UPON MY HONOR I swear that I shall hold in sacred trust the rights and privileges conferred upon me as a certified mechanic. Knowing full well that the safety and lives of others are dependent upon my skill and judgment, I shall never knowingly subject others to risks which I would not be willing to assume for myself, or for those dear to me.

IN DISCHARGING this trust, I pledge myself never to undertake work or approve work which I feel to be beyond the limits of my knowledge; nor shall I allow any non-certificated superior to persuade me to approve aircraft or equipment as airworthy against my better judgment; nor shall I permit my judgment to be influenced by money or other personal gain; nor shall I pass as airworthy aircraft or equipment about which I am in doubt, either as a result of direct inspection or uncertainty regarding the ability of others who have worked on it to accomplish their work satisfactorily.

I REALIZE the grave responsibility which is mine as a certified airman, to exercise my judgment on the airworthiness of aircraft and equipment. I, therefore, pledge unyielding adherence to these precepts for the advancement of aviation and for the dignity of my vocation.